| Postcode | Job Description | Contractor | Job Financia |
|----------|--|---------------|--------------|
| EH21 | PEST CONTROL - Poss squirrel is the attic, seen it going in a few times | Hogg Estate S | 2015 |
| EH41 | PEST CONTROL - flies everywhere in property | Hogg Estate S | 2015 |
| EH42 | Scratching and horrible smell coming frm the attic space | Hogg Estate S | 2015 |
| EH21 | Pest Control rats in back garden | Hogg Estate S | |
| EH21 | PEST CONTROL - bugs have appeared in the livingroom | Hogg Estate S | 2015 |
| EH33 | EMG - Tenant can hear a bird or animal stuck behind wooden panels | Hogg Estate S | |
| EH32 | Pest Control - mice droppings in the kitchen & bathroom today. poison put in loft friday | Hogg Estate S | |
| EH21 | Pest control blue bottles in stairwell for 2 weeks | Hogg Estate S | |
| EH32 | PEST CONTROL - black slugs in kitchen kick board all over kitchen unit door | Hogg Estate S | |
| EH32 | Confirmation of Pest Control Jan-Mar 2016 | Hogg Estate S | |
| EH39 | PEST CONTROL - wasps nest in the attic | Hogg Estate S | |
| EH21 | Tenant has mice in the kitchen | Hogg Estate S | |
| EH35 | Pest control - mice in the property | Hogg Estate S | |
| EH33 | EXT - Mice in the kitchen | Hogg Estate S | |
| TD3 | PESTCONTROL - flour mites in kitchen had them for 2 weeks tried everything | Hogg Estate S | |
| EH33 | PEST CONTROL - fleas in the property | Hogg Estate S | |
| EH33 | [as] Eradicate mice problem at photo copier I | Hogg Estate S | |
| EH42 | Rats in the garden of the property. | Hogg Estate S | |
| H21 | GB-fit anti bird spikes to cages & spaeker boxes at rear Theatre exit doors. | Hogg Estate S | |
| H33 | pest control fleas in property | Hogg Estate S | |
| H39 | PEST CONTROL - mice in attic | Hogg Estate S | |
| H33 | Pest Control - mouse droppings in the kitchen cupb | Hogg Estate S | |
| H41 | PEST CONTROL - mice in property kitchen & in attic / cavity walls | Hogg Estate S | |
| H35 | PEST CONTROL - mice in property, unsure of access point. Have put traps down. | Hogg Estate S | |
| EH21 | Pest control insects in kitchenL room & bedrooms silver fish. | Hogg Estate S | |
| EH32 | PEST CONTROL - woodlice in the living room | Hogg Estate S | |
| H39 | PEST CONTROL - slugs in bathroom area | Hogg Estate S | |
| EH32 | PEST CONT - mice in the property again | Hogg Estate S | |
| H21 | Insects in the property - Silver beetles and woodworm / lice | Hogg Estate S | |
| H21 | Slugs in the house | Hogg Estate S | |
| H21 | pest control beetles in property | Hogg Estate S | |
| H32 | PEST CONTROL something dead in floor board in bedroom really bad smell. Also wasps in attick | Hogg Estate S | |
| H41 | Rats in garden and side of house | Hogg Estate S | |
| H42 | pest control - blue bottles in the kitchen and toilet, think its a dead animal | Hogg Estate S | |
| :H33 | | | |
| H33 | Tenant has mice in the property. CR carry out treatment for rate ground building. | Hogg Estate S | |
| :H41 | GB-carry out treatment for rats around building. | Hogg Estate S | |
| :H41 | [as] bird proof any ext access points into building | Hogg Estate S | |
| H32 | Mice in property PEST CONTROL aluge coming in front door lost visit reported open pine coming into property | Hogg Estate S | |
| | PEST CONTROL - slugs coming in front door, last visit reported open pipe coming into property | Hogg Estate S | |
| H32 | Pest control - scratching heard, droppings, poss coming from hole in cupboard | Hogg Estate S | |
| H41 | PEST CONTROL - wood slaters in all the rooms | Hogg Estate S | |
| H21 | PEST CONTROL - rat in bathroom of property | Hogg Estate S | |
| H21 | PEST CONTROL - rats in back garden between no2 and no3 and also at side of no.2 | Hogg Estate S | |
| H21 | PEST CONTROL - rats in back garden area also holes under property at the front. | Hogg Estate S | |
| :H31 | Tenant has seen mice in the kitchen. Also seen droppings | Hogg Estate S | |
| H21 | Tenant finding insects that come out in the evening. | Hogg Estate S | |
| H41 | Pest control - mice in property, has set traps but thinks they might also be under flooring | Hogg Estate S | |
| H33 | PEST CONTROL - rate hole at the back of the property, nr to back door | Hogg Estate S | |
| H21 | PEST CONTROL - pigeons getting into eaves & mice in attic | Hogg Estate S | |
| H31 | Tenant hears scratching in the loft space - thinks there are birds or mice in there | Hogg Estate S | 201 |

| Files | | | 0045 |
|---|--|---|--|
| EH32 EH33 | Hogg Estates to visit Pest control - further issues with mice in kitchen cupboards, has put poison, traps down etc | Hogg Estate S | 2015 |
| EH33 | EXT CONT -Slugs in the property. Can't use pellets as has baby and dog. Had PC out before. | Hogg Estate S | 2015 |
| EH32 | Tenant has seen mice in the property | Hogg Estate S | 2015 |
| EH31 | PEST CONTROL - micro throughout the house getting in through a hole in the wall | Hogg Estate S | 2015 |
| EH41 | Pest control mice in property kitchen | Hogg Estate S | 2015 |
| EH21 | Pest control - rats in garden - tenant is disabled and not able to manage this issue | Hogg Estate S | 2015 |
| EH39 | Pest control - mice in bedroom - hears scratching through the night | Hogg Estate S | 2015 |
| EH32 | GC there a lots of black flies from time to time which seem to come from the clocktower | Hogg Estate S | 2015 |
| EH32 | Pest control - beetles/insect infestation in the kitchen | Hogg Estate S | 2015 |
| EH21 | Pest control - beetles apearing in property and I arve | Hogg Estate S | 2015 |
| EH21 | Pest control - beasts and larve all over the property, ongoing issue | Hogg Estate S | 2015 |
| EH21 | AVI - PEST CONTROL - PIGEONS IN ATTIC DROPPINGS IN ATTIC CAN HEAR THEM | Hogg Estate S | 2015 |
| EH41 | PEST CONTROL - rat in back garden | Hogg Estate S | 2015 |
| EH21 | PEST CONTROL - birds starting to nest in cavity in back wall, taking out insulation. | Hogg Estate S | 2015 |
| EH22 | AVI - ALL PITCHES. Rats and mice throughout the site. | Hogg Estate S | 2015 |
| EH33 | rats in the house | Hogg Estate S | 2015 |
| EH41 | Pest control - mice still in the property | | 2015 |
| EH32 | | Hogg Estate S | 2015 |
| EH21 | PEST CONTROL - rats in back garden PEST CONTROL - mice in property - could be coming in front door step (mice in cavities) | Hogg Estate S | 2015 |
| EH32 | PEST CONTROL - mice in property - could be coming in front door step (fince in cavities) PEST CONTROL insects in the bathroom! | Hogg Estate S | |
| EH21 | Tenant has mice. Has seen droppings as evidence. | Hogg Estate S | 2015 |
| EH33 | slater coming in kitchen window underneath the cill | Hogg Estate S | 2015 |
| EH33 | Mice in the kitchen | Hogg Estate S | 2015 |
| EH39 | Tenant has mice in the loft space | Hogg Estate S | 2015 |
| EH32 | PEST CONTROL - further issues with rats in back garden, Hogg Estates attended & placed poison but more | Hogg Estate S | 2015 |
| EH41 | slaters in the house | Hogg Estate S | 2015 |
| EH21 | GB-Carry out treatment for ants in main kitchen. | Hogg Estate S | 2016 |
| LIIZI | Ob-Carry out treatment for ants in main kitchen. | | |
| EH35 | Past control - rat at the back of the property -ca n hear scratching at night, on holiday 8/3 - 12/3 | | |
| EH35 | Pest control - rat at the back of the property -ca n hear scratching at night .on holiday 8/3 - 12/3 | Hogg Estate S | 2015 |
| EH21 | PEST CONTROL - mice in cupboard in the kitchen | Hogg Estate S Hogg Estate S | 2015 2015 |
| EH21 EH33 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic | Hogg Estate S Hogg Estate S Hogg Estate S | 2015 2015 2015 |
| EH21 EH33 EH35 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window | Hogg Estate S Hogg Estate S Hogg Estate S Hogg Estate S | 2015 2015 2015 2015 |
| EH21 EH33 EH35 EH41 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window PEST CONTROL - tenant thinks she has rats in her house | Hogg Estate S | 2015 2015 2015 2015 2015 |
| EH21 EH33 EH35 EH41 EH41 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window PEST CONTROL - tenant thinks she has rats in her house Pest control - large wasp nest in the attic | Hogg Estate S | 2015 2015 2015 2015 2015 2015 |
| EH21 EH33 EH35 EH41 EH41 EH31 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window PEST CONTROL - tenant thinks she has rats in her house Pest control - large wasp nest in the attic Pest control - Vermin in the house, items in kitchen were chewed | Hogg Estate S | 2015 2015 2015 2015 2015 2015 2015 |
| EH21 EH33 EH35 EH41 EH41 EH31 EH33 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window PEST CONTROL - tenant thinks she has rats in her house Pest control - large wasp nest in the attic Pest control - Vermin in the house, items in kitchen were chewed Pest control - rats in the kitchen possibly. noise , droppings, chewed rugs | Hogg Estate S | 2015 2015 2015 2015 2015 2015 2015 2015 |
| EH21 EH33 EH35 EH41 EH41 EH31 EH33 EH34 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window PEST CONTROL - tenant thinks she has rats in her house Pest control - large wasp nest in the attic Pest control - Vermin in the house, items in kitchen were chewed Pest control - rats in the kitchen possibly. noise , droppings, chewed rugs PEST CONTROL - ants in lobby & round fire large ants & large amounts | Hogg Estate S | 2015 2015 2015 2015 2015 2015 2015 2015 |
| EH21 EH33 EH35 EH41 EH41 EH31 EH33 EH34 EH21 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window PEST CONTROL - tenant thinks she has rats in her house Pest control - large wasp nest in the attic Pest control - Vermin in the house, items in kitchen were chewed Pest control - rats in the kitchen possibly. noise , droppings, chewed rugs PEST CONTROL - ants in lobby & round fire large ants & large amounts PEST CONTROL - beetles & larvae in bedroom and kitchen and livingroom | Hogg Estate S | 2015 2015 2015 2015 2015 2015 2015 2015 |
| EH21 EH33 EH35 EH41 EH41 EH31 EH33 EH34 EH21 EH42 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window PEST CONTROL - tenant thinks she has rats in her house Pest control - large wasp nest in the attic Pest control - Vermin in the house, items in kitchen were chewed Pest control - rats in the kitchen possibly. noise, droppings, chewed rugs PEST CONTROL - ants in lobby & round fire large ants & large amounts PEST CONTROL - beetles & larvae in bedroom and kitchen and livingroom PEST CONTROL - rats in the back garden, under the shed | Hogg Estate S | 2015 2015 2015 2015 2015 2015 2015 2015 |
| EH21 EH33 EH35 EH41 EH41 EH31 EH33 EH34 EH21 EH42 EH41 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window PEST CONTROL - tenant thinks she has rats in her house Pest control - large wasp nest in the attic Pest control - Vermin in the house, items in kitchen were chewed Pest control - rats in the kitchen possibly. noise , droppings, chewed rugs PEST CONTROL - ants in lobby & round fire large ants & large amounts PEST CONTROL - beetles & larvae in bedroom and kitchen and livingroom PEST CONTROL - rats in the back garden, under the shed PEST CONTROL - rate in flat | Hogg Estate S | 2015 2015 2015 2015 2015 2015 2015 2015 |
| EH21 EH33 EH35 EH41 EH41 EH31 EH33 EH34 EH21 EH42 EH41 EH42 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window PEST CONTROL - tenant thinks she has rats in her house Pest control - large wasp nest in the attic Pest control - Vermin in the house, items in kitchen were chewed Pest control - rats in the kitchen possibly. noise, droppings, chewed rugs PEST CONTROL - ants in lobby & round fire large ants & large amounts PEST CONTROL - beetles & larvae in bedroom and kitchen and livingroom PEST CONTROL - rats in the back garden, under the shed PEST CONTROL - rate in flat PEST CONTROL - cockroaches in livingroom area. | Hogg Estate S | 2015 2015 2015 2015 2015 2015 2015 2015 |
| EH21 EH33 EH35 EH41 EH41 EH31 EH33 EH34 EH21 EH42 EH41 EH42 EH41 EH21 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window PEST CONTROL - tenant thinks she has rats in her house Pest control - large wasp nest in the attic Pest control - Vermin in the house, items in kitchen were chewed Pest control - rats in the kitchen possibly. noise, droppings, chewed rugs PEST CONTROL - ants in lobby & round fire large ants & large amounts PEST CONTROL - beetles & larvae in bedroom and kitchen and livingroom PEST CONTROL - rats in the back garden, under the shed PEST CONTROL - rate in flat PEST CONTROL - cockroaches in livingroom area. PEST control - snails in property due to dampness | Hogg Estate S | 2015 2015 2015 2015 2015 2015 2015 2015 |
| EH21 EH33 EH35 EH41 EH41 EH41 EH31 EH33 EH34 EH21 EH42 EH41 EH42 EH41 EH21 EH35 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window PEST CONTROL - tenant thinks she has rats in her house Pest control - large wasp nest in the attic Pest control - Vermin in the house, items in kitchen were chewed Pest control - rats in the kitchen possibly. noise , droppings, chewed rugs PEST CONTROL - ants in lobby & round fire large ants & large amounts PEST CONTROL - beetles & larvae in bedroom and kitchen and livingroom PEST CONTROL - rats in the back garden, under the shed PEST CONTROL - rate in flat PEST CONTROL - cockroaches in livingroom area. PEST control - snails in property due to dampness PEST CONTROL - rats under the decking back garden | Hogg Estate S | 2015 2015 2015 2015 2015 2015 2015 2015 |
| EH21 EH33 EH35 EH41 EH41 EH41 EH31 EH33 EH34 EH21 EH42 EH41 EH42 EH41 EH21 EH35 EH33 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window PEST CONTROL - tenant thinks she has rats in her house Pest control - large wasp nest in the attic Pest control - Vermin in the house, items in kitchen were chewed Pest control - rats in the kitchen possibly. noise , droppings, chewed rugs PEST CONTROL - ants in lobby & round fire large ants & large amounts PEST CONTROL - beetles & larvae in bedroom and kitchen and livingroom PEST CONTROL - rats in the back garden, under the shed PEST CONTROL - rate in flat PEST CONTROL - cockroaches in livingroom area. PEST control - snails in property due to dampness PEST CONTROL - rats under the decking back garden PEST CONTROL - ants getting into kitchen | Hogg Estate S | 2015 2015 2015 2015 2015 2015 2015 2015 |
| EH21 EH33 EH35 EH41 EH41 EH41 EH31 EH33 EH34 EH21 EH42 EH41 EH42 EH41 EH21 EH35 EH33 EH34 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window PEST CONTROL - tenant thinks she has rats in her house Pest control - large wasp nest in the attic Pest control - Vermin in the house, items in kitchen were chewed Pest control - rats in the kitchen possibly. noise, droppings, chewed rugs PEST CONTROL - ants in lobby & round fire large ants & large amounts PEST CONTROL - beetles & larvae in bedroom and kitchen and livingroom PEST CONTROL - rats in the back garden, under the shed PEST CONTROL - rate in flat PEST CONTROL - cockroaches in livingroom area. PEST control - snails in property due to dampness PEST CONTROL - rats under the decking back garden PEST CONTROL - ants getting into kitchen pest control. moles in rear garden | Hogg Estate S | 2015 2015 2015 2015 2015 2015 2015 2015 |
| EH21 EH33 EH35 EH41 EH41 EH41 EH31 EH33 EH34 EH21 EH42 EH41 EH42 EH41 EH21 EH35 EH33 EH34 EH34 EH35 EH34 EH34 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window PEST CONTROL - tenant thinks she has rats in her house Pest control - large wasp nest in the attic Pest control - Vermin in the house, items in kitchen were chewed Pest control - rats in the kitchen possibly. noise, droppings, chewed rugs PEST CONTROL - ants in lobby & round fire large ants & large amounts PEST CONTROL - beetles & larvae in bedroom and kitchen and livingroom PEST CONTROL - rats in the back garden, under the shed PEST CONTROL - rate in flat PEST CONTROL - cockroaches in livingroom area. PEST control - snails in property due to dampness PEST CONTROL - rats under the decking back garden PEST CONTROL - ants getting into kitchen pest control. moles in rear garden flies in the attic space | Hogg Estate S | 2015 2015 2015 2015 2015 2015 2015 2015 |
| EH21 EH33 EH35 EH41 EH41 EH41 EH31 EH33 EH34 EH21 EH42 EH41 EH42 EH41 EH21 EH35 EH33 EH32 EH34 EH32 EH34 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window PEST CONTROL - tenant thinks she has rats in her house Pest control - large wasp nest in the attic Pest control - Vermin in the house, items in kitchen were chewed Pest control - rats in the kitchen possibly. noise, droppings, chewed rugs PEST CONTROL - ants in lobby & round fire large ants & large amounts PEST CONTROL - rats in the back garden, under the shed PEST CONTROL - rats in the back garden, under the shed PEST CONTROL - rate in flat PEST CONTROL - cockroaches in livingroom area. PEST CONTROL - rats under the decking back garden PEST CONTROL - ants getting into kitchen pest control. moles in rear garden flies in the attic space pest control - rats on the property, can hear them in the attic and had one in kitchen | Hogg Estate S | 2015 2015 2015 2015 2015 2015 2015 2015 |
| EH21 EH33 EH35 EH41 EH41 EH41 EH31 EH33 EH34 EH21 EH42 EH41 EH42 EH41 EH21 EH35 EH33 EH32 EH34 EH42 EH39 EH35 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window PEST CONTROL - tenant thinks she has rats in her house Pest control - large wasp nest in the attic Pest control - Vermin in the house, items in kitchen were chewed Pest control - rats in the kitchen possibly. noise, droppings, chewed rugs PEST CONTROL - ants in lobby & round fire large ants & large amounts PEST CONTROL - beetles & larvae in bedroom and kitchen and livingroom PEST CONTROL - rats in the back garden, under the shed PEST CONTROL - rate in flat PEST CONTROL - rate in flat PEST CONTROL - rate in flat PEST CONTROL - rate under the decking back garden PEST CONTROL - ants getting into kitchen pest control. moles in rear garden flies in the attic space pest control - rats on the property, can hear them in the attic and had one in kitchen PEST CONTROL - ants in property again | Hogg Estate S | 2015 2015 2015 2015 2015 2015 2015 2015 |
| EH21 EH33 EH35 EH41 EH41 EH41 EH31 EH33 EH34 EH21 EH42 EH41 EH42 EH41 EH21 EH35 EH33 EH32 EH34 EH42 EH39 EH35 EH33 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window PEST CONTROL - tenant thinks she has rats in her house Pest control - large wasp nest in the attic Pest control - Vermin in the house, items in kitchen were chewed Pest control - rats in the kitchen possibly. noise , droppings, chewed rugs PEST CONTROL - ants in lobby & round fire large ants & large amounts PEST CONTROL - atts in the back garden, under the shed PEST CONTROL - rate in flat PEST CONTROL - rate in flat PEST CONTROL - cockroaches in livingroom area. PEST CONTROL - rats under the decking back garden PEST CONTROL - ants getting into kitchen pest control - ants getting into kitchen pest control - rats on the property, can hear them in the attic and had one in kitchen PEST CONTROL - ants in property again PEST CONTROL - ants in property again PEST CONTROL - mice in the livingroom Tenant has toddler in property | Hogg Estate S | 2015 2015 2015 2015 2015 2015 2015 2015 |
| EH21 EH33 EH35 EH41 EH41 EH41 EH31 EH33 EH34 EH21 EH42 EH41 EH42 EH41 EH21 EH35 EH33 EH32 EH34 EH42 EH39 EH35 EH33 EH33 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window PEST CONTROL - tenant thinks she has rats in her house Pest control - large wasp nest in the attic Pest control - Vermin in the house, items in kitchen were chewed Pest control - rats in the kitchen possibly. noise , droppings, chewed rugs PEST CONTROL - ants in lobby & round fire large ants & large amounts PEST CONTROL - beetles & larvae in bedroom and kitchen and livingroom PEST CONTROL - rats in the back garden, under the shed PEST CONTROL - rate in flat PEST CONTROL - rate in flat PEST CONTROL - sails in property due to dampness PEST CONTROL - rats under the decking back garden PEST CONTROL - ants getting into kitchen pest control - moles in rear garden flies in the attic space pest control - rats on the property, can hear them in the attic and had one in kitchen PEST CONTROL - mice in the livingroom Tenant has toddler in property PEST CONTROL - mice in the livingroom Tenant has toddler in property | Hogg Estate S | 2015 2015 2015 2015 2015 2015 2015 2015 |
| EH21 EH33 EH35 EH41 EH41 EH41 EH31 EH33 EH34 EH21 EH42 EH41 EH21 EH35 EH33 EH32 EH34 EH42 EH39 EH35 EH33 EH35 EH33 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window PEST CONTROL - tenant thinks she has rats in her house Pest control - large wasp nest in the attic Pest control - Vermin in the house, items in kitchen were chewed Pest control - rats in the kitchen possibly, noise, droppings, chewed rugs PEST CONTROL - ants in lobby & round fire large ants & large amounts PEST CONTROL - beetles & larvae in bedroom and kitchen and livingroom PEST CONTROL - rats in the back garden, under the shed PEST CONTROL - rate in flat PEST CONTROL - cockroaches in livingroom area. PEST CONTROL - sails in property due to dampness PEST CONTROL - rats under the decking back garden PEST CONTROL - ants getting into kitchen pest control . moles in rear garden flies in the attic space pest control - rats on the property, can hear them in the attic and had one in kitchen PEST CONTROL - ants in property again PEST CONTROL - mice in the livingroom Tenant has toddler in property PEST CONTROL - Mice in the livingroom Tenant has toddler in property PEST CONTROL - Atleast 5 rats outside whitnessed this morning out kitchen window VOID\ TREAT\ REMOVE ANT INFESTATION IN PROPERTY | Hogg Estate S | 2015 2015 2015 2015 2015 2015 2015 2015 |
| EH21 EH33 EH35 EH41 EH41 EH41 EH31 EH33 EH34 EH21 EH42 EH41 EH42 EH41 EH21 EH35 EH33 EH32 EH34 EH42 EH39 EH35 EH33 EH33 | PEST CONTROL - mice in cupboard in the kitchen PEST CONTROL - bird stuck in bwteen kitchen celing & attic PEST CONTROL - ants coming front window PEST CONTROL - tenant thinks she has rats in her house Pest control - large wasp nest in the attic Pest control - Vermin in the house, items in kitchen were chewed Pest control - rats in the kitchen possibly. noise , droppings, chewed rugs PEST CONTROL - ants in lobby & round fire large ants & large amounts PEST CONTROL - beetles & larvae in bedroom and kitchen and livingroom PEST CONTROL - rats in the back garden, under the shed PEST CONTROL - rate in flat PEST CONTROL - rate in flat PEST CONTROL - sails in property due to dampness PEST CONTROL - rats under the decking back garden PEST CONTROL - ants getting into kitchen pest control - moles in rear garden flies in the attic space pest control - rats on the property, can hear them in the attic and had one in kitchen PEST CONTROL - mice in the livingroom Tenant has toddler in property PEST CONTROL - mice in the livingroom Tenant has toddler in property | Hogg Estate S | 2015 2015 2015 2015 2015 2015 2015 2015 |

| Rats in attic space | Hoad Estate S | |
|---------------------|---|--|
| | Hogg Estate S | 2015 |
| | | 2015 |
| · | | 2015 |
| | | 2015 |
| | | 2015 |
| | | 2015 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | | 2016 |
| | Hogg Estate S | 2016 |
| | PEST CONTROL - rate in greenhouse in back garden - renant keeps chickens PEST CONTROL - rate in the back garden Mouse or rat in attic space. To mant heard running and grawing, Attic needs a key for entry. More in the property rat under foorboards in property rate under foorboards in property rest control - sha shill in kitchen - coming in under kitchen unit pest control. I had in all event at from or attic PEST CONTROL - rate shill in kitchen or main buildin GC Arts in peel store cupboard GC arts in publiding see text fleas throughout property from previous tereant PEST CONTROL - art inferiestation in fiving from rate in garden PEST CONTROL - rate in back garden pest control mice in attic GB-carry out treatment for ants in manager's office & room 6. PEST CONTROL - rate in the back garden pest control mice in attic GB-carry out treatment for ants in manager's office & room 6. PEST CONTROL - rate in the back garden pest control rate in garden PEST CONTROL - rate in flored mouse neeting in kitchen area PEST CONTROL - rate in garden PEST | PEST CONTROL - moe in the back garden Mouse or six in situs papes. Ferrair tread running and grawing. Alto needs a key for entry. Hopg Essale 5 Mouse or six in situs papes. Terrair tread running and grawing. Alto needs a key for entry. Hopg Essale 5 GB-Chury out resiminest for six in moun 4 & custide bustmon 7. Hopg Essale 5 GB-Chury out resiminest for six in moun 4 & custide bustmon 7. Hopg Essale 5 PEST CONTROL - seathers & lauge influented has housement numerous almost day to get rid of them PEST CONTROL - seathers & lauge influented has housement numerous almost day to get rid of them PEST CONTROL - seathers & lauge influented has housement numerous almost day to get rid of them PEST CONTROL - seathers & lauge influented has housement numerous almost day to get rid of them PEST CONTROL - seathers & lauge influented has house day. PEST CONTROL - seathers & lauge influented has house day. PEST CONTROL - seathers & lauge influented has house day. PEST CONTROL - seathers & lauge influented has house day. Hopg Essale 5 PEST CONTROL - and a lauge influented has house day. Hopg Essale 5 PEST CONTROL - and a lauge influented has house day. Hopg Essale 5 PEST CONTROL - and a lauge influented has house day. Hopg Essale 5 PEST CONTROL - and a lauge garden Hopg Essale 5 PEST CONTROL - and a lauge garden Hopg Essale 6 Hopg Essale 6 PEST CONTROL - and a lauge garden Hopg Essale 7 PEST CONTROL - and in lauge garden Hopg Essale 6 PEST CONTROL - and in lauge garden Hopg Essale 7 PEST CONTROL - and in lauge garden Hopg Essale 7 PEST CONTROL - and in lauge garden Hopg Essale 8 PEST CONTROL - and in lauge garden Hopg Essale 9 PEST CONTROL - and in lauge garden place to lauge garden Hopg Essale 9 PEST CONTROL - and in lauge garden place to lauge garden place 1 Hopg Essale 9 PEST CONTROL - and in lauge garden place to lauge garden place 1 Hopg Essale 9 PEST CONTROL - and in lauge garden place to lauge garden place 1 Hopg Essale 9 PEST CONTROL - and in lauge garden place to lauge g |

| EH42 | PEST CONTROL - mice in attic and bedroom | Hogg Estato S | 2016 |
|------|---|-----------------------------|------|
| EH39 | PEST CONTROL - mice in attic and bedroom PEST CONTROL - maggots getting in via open vents from bird nests in vents | Hogg Estate S Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - Ant infestation in kitchen & livingroom | Hogg Estate S | 2016 |
| EH33 | Pest control - rats in the garden, please call bef re going out | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - Ant infestation in kitchen area, near sink area | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - mice in property, poss accessing through hole at back dr step into kitchen | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - ant in the kitchen | Hogg Estate S | 2016 |
| EH33 | EMG PEST CONTROL 2 x birds in bathroom one in tiles & underneath in bath. | Hogg Estate S | 2016 |
| EH32 | Pest Control ants in kitchen | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL-mice at side house in recycling containers | Hogg Estate S | 2016 |
| EH34 | PEST CONTROL - ants in property | Hogg Estate S | 2016 |
| EH21 | Pest Control black bugs through out house also some woodlice | Hogg Estate S | 2016 |
| EH33 | Pest Control - ants at the property at front door | Hogg Estate S | 2016 |
| EH39 | Pest Control ants in property | Hogg Estate S | 2016 |
| EH42 | Pest control wasps below front rhone near overflow pipe | Hogg Estate S | 2016 |
| EH39 | pest control - bed bugs at the property | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - ants in kitchen, livingroom and dinning room | Hogg Estate S | 2016 |
| EH41 | Ants in living room | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - ants in livingroom | Hogg Estate S | 2016 |
| EH21 | Clean up dead rats | Hogg Estate S | 2016 |
| EH33 | PEST CONT ants all over kitchen recurring issue every year | Hogg Estate S | 2016 |
| EH39 | Pest Control - Ants in the property, seeing them i n kitchen and stair | Hogg Estate S | 2016 |
| EH42 | wasps at back door | Hogg Estate S | 2016 |
| EH21 | Pest Control - wasps nest at the front of the prop erty at the window | Hogg Estate S | 2016 |
| EH32 | Pest Control - Ants in the kitchen and the toilet | Hogg Estate S | 2016 |
| EH33 | Pest Control ants in livingroom | Hogg Estate S | 2016 |
| EH21 | Pest Control ants in kitchen | Hogg Estate S | 2016 |
| EH21 | GB-Carry out treatment for ants in room 51. | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - ants in the livingroom and back door | Hogg Estate S | 2016 |
| EH31 | PEST CONTROL EMG - ants infested in bedroom have tried to hoover & sprayed chemicals on them. | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - squirrell in the floorboards Underfloor boards. | Hogg Estate S | 2016 |
| EH32 | Pest Control ants in kitchen | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - unsure if bird or sml animal trapped above bathrm vent, trying to get out | Hogg Estate S | 2016 |
| EH32 | GC Ant infestation in Community Room & stage | Hogg Estate S | 2016 |
| EH41 | Pest Control wasps in rear garden in a hole in grass | Hogg Estate S | 2016 |
| EH21 | GB-Carry out treatment for ants in bistro restaurant near fire exit. | Hogg Estate S | 2016 |
| EH33 | Pest Control - vent at back door, possible bees ne st | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - 1 rat in the garden Been there for the past week | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - ant infestation in kitchen | Hogg Estate S | 2016 |
| EH42 | GC nursery has ant infestion | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - ants in the livingroom | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - ants coming out chimney breast/wall | Hogg Estate S | 2016 |
| EH21 | Pest Control Black bug/ant type things all through house | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL mice in kitchen & bedroom | Hogg Estate S | 2016 |
| EH21 | AVI needle stick awareness infestation of ants in kitchen | Hogg Estate S | 2016 |
| EH36 | Ants in living room. Tenant has put powder down but still a problem | Hogg Estate S | 2016 |
| EH32 | Pest Control - ants in the property | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - ants in large amounts in throughout the house. Wake up with ants over them | Hogg Estate S | 2016 |
| EH32 | Pest Control - mice at the property, droppings in the kitchen | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - dead mice also mouse droppings in boiler cupboard also ant infestation in kitchen | Hogg Estate S | 2016 |
| EH32 | GC ants conservatory & dining hall | Hogg Estate S | 2016 |
| EH32 | GC after school club ans in cupboard | Hogg Estate S | 2016 |
| | | Hogg Estate S | _010 |

| EH33 | PEST CONTROL - wasp nest in vent at the front door and at the garage | Hogg Estate S | 2016 |
|------|---|---------------|------|
| EH41 | GC ants in bulding see text | Hogg Estate S | 2016 |
| EH42 | wasps at back door | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - mice in the attic | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - Ants in bedroom & livingroom came back again | Hogg Estate S | 2016 |
| EH32 | bird or rat in attic | Hogg Estate S | 2016 |
| EH32 | Pest Control Rats in the garden again under garden shed | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasps nest, wasps going in and out of wall cavity above livingroom window | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - rats at property | Hogg Estate S | 2016 |
| EH39 | Pest control - beetles in every room of the house | Hogg Estate S | 2016 |
| EH32 | Hole in front wall/back wall @ kitchen & livingroom - rats gets under into proeprty | Hogg Estate S | 2016 |
| EH33 | Birds getting into the property from the roof - keep falling into the bathroom - poss cavity | Hogg Estate S | 2016 |
| EH33 | Pest Control Rats in garden | Hogg Estate S | 2016 |
| EH42 | sound of blue bottles in air vent in bedroom | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - 4 rats in the garden | Hogg Estate S | 2016 |
| EH39 | Ants comimg in front door | Hogg Estate S | 2016 |
| EH32 | Pest Control - Ants in the property | Hogg Estate S | 2016 |
| EH34 | PEST CONTROL - ants in various rooms | Hogg Estate S | 2016 |
| EH33 | Report of Bees/Wasps in roof. | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - bees nest in grass approx 8ft from rear of property | Hogg Estate S | 2016 |
| EH32 | GC Infested with Ants at the crech area | Hogg Estate S | 2016 |
| EH42 | Tenant still has ants. Live ants bringing 100's of live ants bringing dead ones out | Hogg Estate S | 2016 |
| EH21 | Infestation of ants in kitchen and bathroom | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - dead pigoen in rhone above back door - as discussed with Gavin | Hogg Estate S | 2016 |
| EH41 | Ant infestation again | Hogg Estate S | 2016 |
| EH33 | Pest Control - hear scratching at night in the att ic. in tomorrow all day. | Hogg Estate S | 2016 |
| EH32 | pest control - ANT INFESTION | Hogg Estate S | 2016 |
| EH33 | Tenant has rats | Hogg Estate S | 2016 |
| EH32 | Infestation of ants in house | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - slugs in kitchen, livingroom, hall and bathroom | Hogg Estate S | 2016 |
| EH21 | HOMELESS: Pest Control - woodlice in property | Hogg Estate S | 2016 |
| EH21 | Void: report of bees nest back garden | Hogg Estate S | 2016 |
| EH35 | PEST CONTROL - ants present in kitchen | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - maggots in rhones and back door area after dead pigeon that was removed | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - carpet beetles everywhere | Hogg Estate S | 2016 |
| EH33 | Pest Control ants in livingroom - new line put on as per Rebecca | Hogg Estate S | 2016 |
| EH35 | PEST CONT lost of ants in living room | Hogg Estate S | 2016 |
| EH41 | Pest Control small honey bee's (not bumble bee's) at front step 2nd down where broken | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - wasps nest in the back garden play house | Hogg Estate S | 2016 |
| EH35 | PEST CONTROL - birds nesting in attic getting in through o/flow pipe that hasnt been replaced | Hogg Estate S | 2016 |
| EH32 | GB-Carry out treatment for ants in Nursery/tea prep areas. | Hogg Estate S | 2016 |
| EH21 | Tenant thinks she has mice / rats in the walls. Noise waking her up in he night. | Hogg Estate S | 2016 |
| EH41 | wasps nest inside garage in vent | Hogg Estate S | 2016 |
| EH21 | Pest Control insects in property bathroom hall bedrooms | Hogg Estate S | 2016 |
| EH21 | Ants in property | Hogg Estate S | 2016 |
| EH41 | Pest Control ants in property | Hogg Estate S | 2016 |
| EH32 | PEST control - wasp next in through the air vent | Hogg Estate S | 2016 |
| EH21 | Pest Control - Rats at the property, think it mig ht be neighbours hut thats issue | Hogg Estate S | 2016 |
| EH42 | Pest Control - Ants in the property | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasps nest in the attic and on the balcony | Hogg Estate S | 2016 |
| EH33 | Pest Control Bee's as you go in the gate at the fence near the window - not Bumble bees | Hogg Estate S | 2016 |
| EH32 | spray house for flies after eviction | Hogg Estate S | 2016 |
| EH33 | Pest Control rats in rear garden | Hogg Estate S | 2016 |

| EH21 | pest control - Fruit flies in kitchen & bathroom | Hogg Estate S | 2016 |
|------|--|----------------|------|
| EH21 | PEST CONTROL - birds nest in gully betwn roof & chimney, unsure if has chicks | Hogg Estate \$ | 2016 |
| EH41 | PEST CONTROL - rat in house | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - mice & slugs in kitchen area | Hogg Estate S | 2016 |
| EH34 | PEST CONT has mice entering o/s wall though hole for pipe | Hogg Estate S | 2016 |
| EH33 | bees in the attic, coming through bath tap | Hogg Estate S | 2016 |
| EH33 | Pest Control ants in hallway & kitchen | Hogg Estate S | 2016 |
| EH32 | Bees at back under livingroom window | Hogg Estate S | 2016 |
| EH41 | Pest control rats in kitchen & in attic | Hogg Estate S | 2016 |
| EH41 | Pest Control rats in loft again | Hogg Estate S | 2016 |
| EH32 | wasps nest at roof at back beside the sky dish | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - rats in back garden, poss under garden shed | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - rats in house 4th time | Hogg Estate S | 2016 |
| EH33 | Pest Control wasps nest at steps at front door | Hogg Estate S | 2016 |
| EH35 | [as] ants in kitchen see janitor for info | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - small black ant like beasts in kitchen area | Hogg Estate S | 2016 |
| EH32 | Steps at back door there is bees surrounding them | Hogg Estate S | 2016 |
| EH21 | Pest Control bees going into vent at rear next to window | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - Insects in bed | Hogg Estate S | 2016 |
| EH41 | Wasps at outhouse at front door | Hogg Estate S | 2016 |
| EH33 | [as] ants in soft play area | Hogg Estate S | 2016 |
| EH33 | [as] ant infestation at wraparound play area | Hogg Estate S | 2016 |
| EH39 | Pest Control fleas in property | Hogg Estate S | 2016 |
| EH32 | Tenant think she has a wasps nest near the gas box | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - ants in the kitchen | Hogg Estate S | 2016 |
| EH21 | GB-Carry out treatment for insects inside safe in main office. | Hogg Estate S | 2016 |
| EH21 | Pest control - mice at the property in garden will be in till 1pm 09/06/2016 all day 10/06/2016 | Hogg Estate S | 2016 |
| EH41 | Pest Control - Ants inthe kitchen | Hogg Estate S | 2016 |
| EH21 | PEST CONTOL - black slugs between bathroom & kitchen, tenant sight impaired | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - rats in back garden area | Hogg Estate S | 2016 |
| EH33 | Fumigate property at request of Housing Manager rechargeable work | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - Slugs in kitchen. Tenant overrun with them and says GH needs to find where they are | Hogg Estate S | 2016 |
| EH33 | Ants in living room | Hogg Estate S | 2016 |
| EH35 | PEST CONTROL - mice in the kitchen | Hogg Estate S | 2016 |
| EH31 | PEST CONTROL - wasps under back door step (LHS) next to brick | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - bees nest active on the ouside wall air vent | Hogg Estate S | 2016 |
| EH32 | PEST CONT excessive amount of slaters around house | Hogg Estate S | 2016 |
| EH21 | Mice in back garden again be in from 1pm onwards if needed | Hogg Estate S | 2016 |
| EH32 | PEST CONT wasps swarming under rhones above front porch. | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasps nest above bathroom window | Hogg Estate S | 2016 |
| EH32 | GC Ants in the creche kitchen area. | Hogg Estate S | 2016 |
| EH34 | Pest control - rat at property in garden | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - ants in the livingroom | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - Ants infestation in kitchen area | Hogg Estate S | 2016 |
| EH33 | PEST CONT lots of slugs in kitchen | Hogg Estate S | 2016 |
| EH21 | Wasps going in and out of air vent | Hogg Estate S | 2016 |
| EH33 | PEST CONT bees accessing hole just outside front door next to elec box | Hogg Estate S | 2016 |
| EH33 | New tenant: bait for rats boiler cupboard in kitch & attic space as per Scott Hood | Hogg Estate S | 2016 |
| EH39 | pest control -bees at the front of the house going into cavities | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - Wasps nest at front door | Hogg Estate S | 2016 |
| EH21 | Pest Control - Bees nest at the front of property. | Hogg Estate S | 2016 |
| EH21 | bee hive at back door | Hogg Estate S | 2016 |
| _ | | 1.55 = 31610 | |

| EH32 | PEST CONTROL - wasps nest, directly above livingrm wdw under the eves | Hogg Estate S | 2016 |
|------|---|---------------|------|
| EH42 | Pest Control - wasps/bees nest under the living rm window | Hogg Estate S | 2016 |
| EH33 | Ants in property | Hogg Estate S | 2016 |
| EH32 | Pest Control bees nest at back door at rhones | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasp nest at front door - air vent | Hogg Estate S | 2016 |
| EH21 | Void: fumigate property as per Housing Office keys at Brunton Hall | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - Cereal beatles in kitchen | Hogg Estate S | 2016 |
| EH41 | Pest Control - bee nest at front & side door - going in & out vent at side of house | Hogg Estate S | 2016 |
| EH21 | PEST CONT mice in property. Heard but not seen. Dropping behind cooker and in bedroom. | Hogg Estate S | 2016 |
| EH21 | Wasps next in shed | Hogg Estate S | 2016 |
| EH34 | Wasps going in and out of bottom air bricks | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasps nest in bird feeder in back garden | Hogg Estate S | 2016 |
| EH35 | Pest Control mice in kitchen | Hogg Estate S | 2016 |
| EH21 | Pest Control bees nest at vent at front and under green house | Hogg Estate S | 2016 |
| EH41 | PEST CONT wasp going into steps at front door rhs. concerned for grandkids. | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasps going in and out of wall cavity under bedroom window at the rear | Hogg Estate S | 2016 |
| EH41 | EMG- bees nesting in roof | Hogg Estate S | 2016 |
| EH33 | PEST control ant infestion in property | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasp nest front bedroom window upstairs | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL bugs & flies in the house | Hogg Estate S | 2016 |
| EH42 | Pest Control - Wasps in hole in wall at the back d oor | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - non bumble bees nest at guttering/ attick | Hogg Estate S | 2016 |
| EH21 | Tenant has lots of flies in the property. | Hogg Estate S | 2016 |
| EH42 | Pest Control wasps going in through concret area above livingroom window below rhone - getting into | Hogg Estate S | 2016 |
| EH32 | wasps nest in shed | Hogg Estate S | 2016 |
| EH41 | INSECTS - bug in house | Hogg Estate S | 2016 |
| EH33 | bird stuck behin | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasps/bees nesting under frt bathroom window | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - WASP NEST IN THE BIRD BOX | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - RATS IN THE HOUSE & THE ATTIC | Hogg Estate S | 2016 |
| EH33 | void: spray for fleas | Hogg Estate S | 2016 |
| EH34 | GB-Carry out a treatment for a wasps nest near entrance door used by the playgroup. | Hogg Estate S | 2016 |
| EH39 | GB-Carry out treatment for wasps-see John Burgess for exact location. | Hogg Estate S | 2016 |
| EH33 | Ants in porch and daughters bedroom | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - ants in livingroom | Hogg Estate S | 2016 |
| EH32 | Pest control ants in kitchen cupboards | Hogg Estate S | 2016 |
| EH39 | PEST CONTROL - bees (unsure) getting into hole betwn frt door & gas box | Hogg Estate S | 2016 |
| EH32 | Ants in kitchen | Hogg Estate S | 2016 |
| EH33 | wasp nest next to winow vent at back | Hogg Estate S | 2016 |
| EH21 | Wasps nest at front door | Hogg Estate S | 2016 |
| EH35 | Pest Control ants throughout the house | Hogg Estate S | 2016 |
| EH21 | Pest Control infestation of fruit flies | Hogg Estate S | 2016 |
| EH21 | Pest Control infestation of fruit flies | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - fly infestion in house | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasps at kitchen wndow & getting into a whole at window | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - bugs in the bedroom | Hogg Estate S | 2016 |
| EH33 | GB-Remove a dead bird from roof. | Hogg Estate S | 2016 |
| EH21 | GB-remove seagull nests from roof to allow service engineer access. | Hogg Estate S | 2016 |
| EH33 | Pest Control wasps going in at bottom of wall at righthand side of front door | Hogg Estate S | 2016 |
| EH33 | PEST CONT bees under pigeon loft at bottom of garden | Hogg Estate S | 2016 |
| EH32 | Wasp nest at back window near vent | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - wasp nest in the garage Garage attached to house | Hogg Estate S | 2016 |
| EH32 | wasp nest at rhones | Hogg Estate S | 2016 |

| EH21 | Wasps nest in air vent | Hogg Estate S | 2016 |
|------|---|---------------|------|
| EH35 | Pest control rats in rear garden | Hogg Estate S | 2016 |
| EH32 | Pest Contol - wasps going in overflow pipe just above bathroom window - can hear them in wall | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - slugs and ants inside house | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - bees nest at the front door unsure if bumble bees or honey bees | Hogg Estate S | 2016 |
| EH41 | Pest Control - wasp nest inside garage Please call to arrange access | Hogg Estate S | 2016 |
| EH32 | Pest control - wasp nest above bathroom window | Hogg Estate S | 2016 |
| EH21 | Pest Control - wasp nest above living room window | Hogg Estate S | 2016 |
| EH32 | Pest Control ants nest in sun porch just off the livingroom | Hogg Estate S | 2016 |
| EH32 | GC ANTS AT FRONT DESK. | Hogg Estate S | 2016 |
| EH21 | GC fly infestation at front desk see text | Hogg Estate S | 2016 |
| EH41 | Pest Control - wasp nest. Front living room window | Hogg Estate S | 2016 |
| EH39 | PEST CONTROL - ants in kitchen etc | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasp next at back bedroom window | Hogg Estate S | 2016 |
| EH21 | Bluebottles in kitchen | Hogg Estate S | 2016 |
| EH33 | Wasps in vent under living room window | Hogg Estate S | 2016 |
| EH35 | Ants in property. | Hogg Estate S | 2016 |
| EH33 | infestation of ants in kitchen | Hogg Estate S | 2016 |
| EH32 | Tenant has a swarm of bees in her kitchen | Hogg Estate S | 2016 |
| EH42 | Pest Control ants & flying ants in house | Hogg Estate S | 2016 |
| EH33 | Pest Control wasps nest at outhouse | Hogg Estate S | 2016 |
| EH41 | Wasp nest at eaves of back porch | Hogg Estate S | 2016 |
| EH32 | Pest Control - Wasps nest in attic | Hogg Estate S | 2016 |
| EH41 | Pest Control - at the back door, at gas pipe. | Hogg Estate S | 2016 |
| EH39 | Pest Control - 3 wasps nest above kitchen window 2/3 tiles up between window & front door | Hogg Estate S | 2016 |
| EH21 | Pest Control wasps nest at front porch | Hogg Estate S | 2016 |
| EH39 | gc BEES IN CHIMNEY | Hogg Estate S | 2016 |
| EH33 | gc Ants infested in club in craft room | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - Ants in living room | Hogg Estate S | 2016 |
| EH39 | gc WASP NEST IN RANGERS OFFICE | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - tenant thinks she has wasps in the attic | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - wasps coming in through roof from front of property | Hogg Estate S | 2016 |
| EH32 | Mice in attic space. | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasps nest in conifer at front door | Hogg Estate S | 2016 |
| EH33 | Pest Control - wasp nest on right of the house near roof | Hogg Estate S | 2016 |
| EH21 | Pest Control wasps nest at front below rhone | Hogg Estate S | 2016 |
| EH33 | Pest Control rats at front door area & side path | Hogg Estate S | 2016 |
| EH41 | Pest Control wasps nest at rear bedroom window right hand side at eaves | Hogg Estate S | 2016 |
| EH21 | Pest Control wasps nest rear window in hole in wall | Hogg Estate S | 2016 |
| EH34 | Pest Control biting inspects in house | Hogg Estate S | 2016 |
| EH21 | Pest Control wasps nest at front going into roof | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - wasps nest above bedrm wdw under guttering, frt of hse. | Hogg Estate S | 2016 |
| EH39 | Wasp nOutside boiler room on the right hand side | Hogg Estate S | 2016 |
| EH39 | Pest Control wasps nests in bush at front door | Hogg Estate S | 2016 |
| EH21 | Pest Control wasps nest. wasps in bedroom | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasps nest inside front door wasps are getting bigger and bigger | Hogg Estate S | 2016 |
| EH39 | PEST CONTROL - wasps nest at back bedroom window, just as you turn the corner | Hogg Estate S | 2016 |
| EH33 | pest control wasps nest in vent at rear | Hogg Estate S | 2016 |
| EH41 | GC ants and wood lice in building | Hogg Estate S | 2016 |
| EH33 | BLOCK Ants in the building | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasps nest in air vent at frt of property under bedrm wdw | Hogg Estate S | 2016 |
| EH21 | Pest Control - look like carpet bugs in carpets kitchen units, in all bedrooms. Every Room | Hogg Estate S | 2016 |
| EH21 | Wasps nest on roof at the back | Hogg Estate S | 2016 |

| EH41 | Pest Control insects in bedroom bedbugs | Hogg Estate S | 2016 |
|------|---|---------------|------|
| EH31 | wasps nest near eaves/ pipe at right of porch at front | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - wasp nest under front window in vent | Hogg Estate S | 2016 |
| EH32 | Bumble bees at shed at bottom ofgarden already been stung. Swarming at bottom Garden | Hogg Estate S | 2016 |
| EH33 | Pest Control mice in a hole in wall at front between 29/30. | Hogg Estate S | 2016 |
| EH42 | GB-Remove seagull nest from roof-see janitor for location. | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - bees nest at back of and under the shed in back garden | Hogg Estate S | 2016 |
| EH32 | Wasps nest in roof space and garden | Hogg Estate S | 2016 |
| EH31 | PEST CONTROL - bees or wasps, entering pipe at the back of the house, possibly nesting | Hogg Estate S | 2016 |
| EH21 | Pest control - mites in kitchen,bathroom now in bedrooms & living room | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - Ant infestation in kitchen & livingroom | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasps nest at front wdw top LH corner | Hogg Estate S | 2016 |
| EH34 | PEST CONTROL -ants in front bedroom possibly in cavity wall | Hogg Estate S | 2016 |
| EH41 | Wasps nest in vent under bedroom window. Urgent | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - noise from attic potential birds in attack space | Hogg Estate S | 2016 |
| EH39 | PEST CONTROL - bees at rear house underneath bathroom window | Hogg Estate S | 2016 |
| EH32 | Pest Control - wasps nest front bedrrom window & bees are side of house (front door) @ brown vent | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL,- Wasp nest under the living room window, wasps are flying into vents. | Hogg Estate S | 2016 |
| EH21 | Wasp nest up above the bedroom window at the front. | Hogg Estate S | 2016 |
| EH32 | Wasps in overflow pipe on the outside | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - Ants in hall, living room & kids bedroom. Few going upstairs | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - ants in kitchen. | Hogg Estate S | 2016 |
| EH21 | Wasps nest poss in attic, wasps going through rhone | Hogg Estate S | 2016 |
| EH32 | Wasps nest in garden | Hogg Estate S | 2016 |
| EH21 | Pest Contol - wasps nest in back garden at the wall | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - Ant infestation in bedroom, coming in betwn bedrm wdw cill & gas box | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - ant infestation in livingrm, coming in under window | Hogg Estate S | 2016 |
| EH33 | pest control - flying ants in bedroom | Hogg Estate S | 2016 |
| EH41 | Pest Control flying ants in L room | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - ants in livingroom | Hogg Estate S | 2016 |
| EH21 | GB-Carry out treatment for ants in laundry room & common lounge. | Hogg Estate S | 2016 |
| EH33 | Pest Control mice in kitchen | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - flies in various rooms | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasp nest in between guttering & wall at rear property | Hogg Estate S | 2016 |
| EH21 | Wasps nest underneath bathroom window | Hogg Estate S | 2016 |
| EH34 | PEST CONTROL - Wasps nest back bedroom vent also ants nest frt bedroom wdw, all getting | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - rats in attic area, concerned has young child | Hogg Estate S | 2016 |
| EH39 | PEST CONTROL - ants coming in front door | Hogg Estate S | 2016 |
| EH32 | Pest Control - Rats or mice scratching at night in attic | Hogg Estate S | 2016 |
| EH41 | Ants in property | Hogg Estate S | 2016 |
| EH32 | Pest Control ants in property | Hogg Estate S | 2016 |
| EH35 | PEST CONTROL - ants in kitchen | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - ant infestion - front door covered | Hogg Estate S | 2016 |
| EH41 | GB-Carry out treatment for flying ants-see staff for location. | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL black flys unsure what they are in bathroom. Has baby & child with special needs | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - slaters infestion | Hogg Estate S | 2016 |
| EH33 | Pest Control wasps or bees in attic going in at back near balcony | Hogg Estate S | 2016 |
| EH35 | wasps nest above door reported by d.hamilton | Hogg Estate S | 2016 |
| EH33 | Pest Control wasps nest front corner of house just where roof goes up - at side gate | Hogg Estate S | 2016 |
| EH39 | GB-Carry out treatment for ants at back door area. | Hogg Estate S | 2016 |
| EH21 | Pest Control - wasps in back bedroom coming in through wall | Hogg Estate S | 2016 |
| EH31 | PEST CONTROL - wasp nest at rear of proeprty in roof eves - near back door | Hogg Estate S | 2016 |
| EH32 | Wasps nest in garden | Hogg Estate S | 2016 |

| FUIDA | DEST CONTROL | | 0040 |
|--------------|---|-----------------------------|------|
| EH31 | PEST CONTROL - wasps nest in the eves at the front of the property | Hogg Estate S | 2016 |
| EH42 | Pest Control - shed at the side of the house has wasps nest | Hogg Estate S | 2016 |
| EH42 EH21 | PEST CONTROL - wasp nest in back of property at bathroom vent | Hogg Estate S Hogg Estate S | 2016 |
| EH33 | Has seen a rat in the garden Reat Central wash past shows front door | | 2016 |
| EH41 | Pest Control wasp nest above front door PEST CONTROL - wasp nest in shed | Hogg Estate S Hogg Estate S | 2016 |
| EH21 | pest control - wasps nest at the roof at rear of p roperty | Hogg Estate S | 2016 |
| EH34 | Pest control - rat at property in garden | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasps nest in back garden, burrow into grass, approx half way at hilly patch | Hogg Estate S | 2016 |
| EH21 | Pest Control - wasps at side of house - 2 storey | Hogg Estate S | 2016 |
| EH39 | GB-Carry out treatment for wasps at pavilion. | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasps nest under guttering at the back of property above livingrm wdw | Hogg Estate S | 2016 |
| EH21 | Pest Control small black beetles type insects in bedroom, livingroom, hall & kitchen | Hogg Estate S | 2016 |
| EH32 | PEST CONT wasp nest in soffit to back of property (upper level). Entering at overflow pipe. | Hogg Estate S | 2016 |
| EH32 | Pest Control wasps nest in attic? under eves at side of house | Hogg Estate S | 2016 |
| EH33 | Pest Control fleas throughout house | Hogg Estate S | 2016 |
| EH21 | Pest Control - wasps nest in vent underneath livingroom window | Hogg Estate S | 2016 |
| EH41 | entryphone handset faulty, tenant unable to hear anyone buzzing at main door | Hogg Estate S | 2016 |
| EH32 | Pest Control ants in property | Hogg Estate S | 2016 |
| EH42 | Rat in kitchen | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - ants in kitchen | Hogg Estate S | 2016 |
| EH35 | RTB restricted - wasps nest in eaves, coming into property, at rear, report back damage to eaves | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - snails getting into property at the front door | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasps nest at front bedroom window | Hogg Estate S | 2016 |
| EH21 | bluebottles in property | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - wasps nests in the attic | Hogg Estate S | 2016 |
| EH32 | Ants in living room. GH previous been but more ants in property | Hogg Estate S | 2016 |
| EH32 | PEST COTNROL - wasp nest in attic | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - infestion of ants at back door, front door/window a& around side of building | Hogg Estate S | 2016 |
| EH35 | Pest Control wasps going in at vent on righthand of front bedroom window (brick type) | Hogg Estate S | 2016 |
| EH41 | Pest control - Infestation of bed bugs | Hogg Estate S | 2016 |
| EH41 | Pest control - large amounts of wasps in garden, not sure if issue with void house next door | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - wasps nest at the back of property above kitchen window | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasp nest beside bathroom window right hand side | Hogg Estate S | 2016 |
| EH32 | pest control - wasps nest - back of property at rhone level | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - bees nest at side of house knocked brickwork away and inside wall | Hogg Estate S | 2016 |
| EH41 | wasps at the bottom of the back garden next to the shed | Hogg Estate S | 2016 |
| EH32 | PEST CONT wasps nest at back bedroom window and accessing property | Hogg Estate S | 2016 |
| EH32 | GC Wasps nest outside P4 | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - wasps nest beside kitchen window in an air vent | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - ants behind lving room window and coming into living room | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - wasps nest above bedroom window upstairs | Hogg Estate S | 2016 |
| EH21 | wasps nest under the front bedroom window | Hogg Estate S | 2016 |
| EH21 | GB-Carry out treatment for insects in dining room. | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - pigeons on balcony and cannot move them - nests hatched now | Hogg Estate S | 2016 |
| EH21 | GC Wasps nest in outside caretakers flat | Hogg Estate S | 2016 |
| EH34 | Pest Control - wasps nest in the guttering next to front door | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - mice getting into garden shed | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - bugs under kitchen sink and all over kitchen floor | Hogg Estate S | 2016 |
| EH32 | Infestation of bluebottles betwenn 5&7 Harlaw Hill as per E'Mail | Hogg Estate S | 2016 |
| EH33 | Pest Control - wasps nest on the guuttering above the front door | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - tenants house is infested with wasp thinks nest is in attic. Seem to be coming out hot | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL * Mice in house | Hogg Estate S | 2016 |

| EH21 | Wasps nest in fan in kitchen | Hogg Estate S | 2016 |
|------|---|---------------|------|
| EH32 | PEST CONTROL - wasps nest above back bedroom window | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL* Wasp nest above back door unsure if in attick | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasp nest above the front door wasps going in and out of attic | Hogg Estate S | 2016 |
| EH39 | PEST CONTROL - wasps coming in through kitchen vent - 2 storey house | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - Garage in garden has wasps nest | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasps nest in front garden as you enter gate its the bush to the right hand | Hogg Estate S | 2016 |
| EH33 | CB wasps behind radiator in bedroom | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - Bees nest in garden bush. Right next to front door | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - pigeons on balcony and nesting - been told by PC that shouldnt matter | Hogg Estate S | 2016 |
| EH39 | PEST CONTROL Wasp nest outside bathroom window coming into bathroom | Hogg Estate S | 2016 |
| EH32 | GB-Carry out treatment for ants in kitchen area. | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - wasps nest in kitchen fan | Hogg Estate S | 2016 |
| EH39 | PEST CONTROL - wasp nest at gutterings in the roof | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasp nest in vent at front door left handside. | Hogg Estate S | 2016 |
| EH31 | PEST CONTROL - mice in loft and kitchen cupboard | Hogg Estate S | 2016 |
| EH39 | PEST CONTROL - wasps going in eves at bottom | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - rats or mice in kitchen/livingroom eighbour no 30 recently had p.control | Hogg Estate S | 2016 |
| EH32 | Pest Control wasps nest out bathroom window wasps now going into the bathroom | Hogg Estate S | 2016 |
| EH39 | PEST CONTROL - Wasp nest in the shed back garden | Hogg Estate S | 2016 |
| EH21 | Wasps in garden at side of apple tree also another nest above kitch and I/room window | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - ants in property again | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - 2 wasps nest at coal cellar and coming through living room vent. Need to go in no | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - small back flying insect in kitchen area. Concerned for 2 young babies | Hogg Estate S | 2016 |
| EH21 | Pest Control wasps swarming above side door possibly nesting in attic? | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - Wasps nest on roof above front door wasps are now getting into the house, tenant has | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - wasps nest in front garden bush | Hogg Estate S | 2016 |
| EH41 | Pest control - Tenant has crawlies on settee and LR | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - bees at garage door | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasp nest at gate at back door | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - flying ants are getting in through holes under radiator | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - flying ants | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasps nest above front door - carers struggling to get in | Hogg Estate S | 2016 |
| EH34 | Tenant still having problem with ants in the property | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL bees nesting at rear of house | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - wasps nest in bedroom at bdrm wdw also under guttering above wdw | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - Ants in living room | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - black slaters type insects in bedroom, poss bathrm | Hogg Estate S | 2016 |
| EH32 | Pest Control wasp nest above bedroom window maybe in the wall or attic not sure | Hogg Estate S | 2016 |
| EH33 | Pest Control ants in property | Hogg Estate S | 2016 |
| EH21 | GB-Carry out a treatment for ants at the rear door area(inside library). | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - insects in kitchen & livingroom | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - Infestation of flying ants mainly in livingroom area, under window cill | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - wasps at front and back of property | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - wasp bink in attic | Hogg Estate S | 2016 |
| EH41 | W.E plumber reported wasp bink in attic pest control | Hogg Estate S | 2016 |
| EH21 | GB-Carry out treatment for wasps nest at gate house & 2 at groundcare bothy. | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasps at back bedroom window | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasps nest at livingroom window | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - rat stuck in chimney breast no fire in fireplace. | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - ants in kitchen - coming from back door area | Hogg Estate S | 2016 |
| | | | |
| EH21 | PEST CONTROL - wasps nest at gable end of property abv frt dr under guttering | Hogg Estate S | 2016 |

| EH33 | PEST CONT bed bugs in property need property fumigated before new bed arrives | Hogg Estate S | 2016 |
|------|---|---------------|------|
| EH35 | wasp nest at back garden beside bathroom window | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - ants in property - bathroom | Hogg Estate S | 2016 |
| EH21 | wasps at the front of the garage | Hogg Estate S | 2016 |
| EH41 | [as] Eradicate problem with wasps nests at P2 and infants nursery | Hogg Estate S | 2016 |
| EH41 | PEST CONT wasp nest on soffit above front door of bungalow | Hogg Estate S | 2016 |
| EH32 | pest control wasps nest at front near rhones & upstair window | Hogg Estate S | 2016 |
| EH42 | Rat on kitchen worktop | Hogg Estate S | 2016 |
| EH42 | Tenant has saw rat running across worktop | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - wasps nest at back bedroom window - bungalow | Hogg Estate S | 2016 |
| EH21 | Pest control - Rats in garden. Chewed into cupboard under decking and fences | Hogg Estate S | 2016 |
| EH31 | Pest control - Wasps nest at kitchen window | Hogg Estate S | 2016 |
| EH35 | Pest control - Snails in living room | Hogg Estate S | 2016 |
| EH32 | Pest Control - wasp next above the front door in t he eves | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasps nest at gable end at guttering, directly above recycling boxes | Hogg Estate S | 2016 |
| EH32 | PEST CONT ants in kitchen and loads of different flies. | Hogg Estate S | 2016 |
| EH21 | Pest Control - Wasps next at the back door | Hogg Estate S | 2016 |
| EH33 | PEST CONT wasps entering wall at front door | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - wasp nest at front of house towards the roof | Hogg Estate S | 2016 |
| EH33 | Pest control - Wasps nest in pipe at the back door | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasps nest at front & back guttering to property | Hogg Estate S | 2016 |
| EH39 | [as] eradicate problem with wasps nest at front of building | Hogg Estate S | 2016 |
| EH32 | GC wasp nest see text | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasps nest at bottom of garden right beside shed door | Hogg Estate S | 2016 |
| EH21 | Wasps nest at roof facia coming into bathroom | Hogg Estate S | 2016 |
| EH21 | PEST CONT wasps entering vent brick to rhs front window | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - wasps in loft space | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasp nest in side garden next to driveway | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - 2 rats found in garden, possibly from No. 63 (council) | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - rats in the attic (joe s & stuart y aware of this) | Hogg Estate S | 2016 |
| EH32 | Confirmation of pest control july-sep 16 as per invoice 7664.16 | Hogg Estate S | 2016 |
| EH41 | wasps nest at front above bedroom window | Hogg Estate S | 2016 |
| EH31 | Pest Control slugs in bedroom | Hogg Estate S | 2016 |
| EH41 | pest control - wasps nest on top on the garage | Hogg Estate S | 2016 |
| EH41 | Pest Control - Wasps nest at the corner of this ga rage | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - beetles infestion and everyone getting bites | Hogg Estate S | 2016 |
| EH42 | Pest control Wasp nest in a tree in the garden. Tenant has out a chair in front of the tree | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasps nest under guttering at side of property above front door | Hogg Estate S | 2016 |
| EH33 | Beetles coming into kitchen unsure where from | Hogg Estate S | 2016 |
| EH35 | Suspected wasps next in vent under front window | Hogg Estate S | 2016 |
| EH33 | Pest control - mouse in kitchen | Hogg Estate S | 2016 |
| EH41 | Pest control - Rat in the kitchen | Hogg Estate S | 2016 |
| EH36 | wasp nest on the roof at back | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasps nest in garden | Hogg Estate S | 2016 |
| EH41 | GB-Carry out treatment for wasps nest outside senior management office window. | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - bees nest on LHS of front dr next to circular washing line fixed to wall | Hogg Estate S | 2016 |
| EH21 | pest control rats nest in hut | Hogg Estate S | 2016 |
| EH39 | GB-Carry out treatment for wasps nest near rear entrance door (in hedge). | Hogg Estate S | 2016 |
| EH21 | Pest Control wasp nest at property - as per email received | Hogg Estate S | 2016 |
| EH32 | Pest Control wasp nest maybe two? going in around drain pipe/roof at back door also around the side | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasps in stairwell and also impacted 28F (nest at rhone/loft of no 28F) | Hogg Estate S | 2016 |
| EH32 | EMG Pest Control - Wasps in property. So many they are waking him up at night | Hogg Estate S | 2016 |
| EH21 | GB-Carry out treatment for silverfish in theatre technicians office. | Hogg Estate S | 2016 |

| EH21 | PEST CONTROL - wasps nest beside rhones pipe | Hogg Estate S | 2016 |
|------|---|---------------|------|
| EH21 | Pest Control wasp in kitchen & bathroom - doesn't think the nest has been killed last time GH visit | Hogg Estate S | 2016 |
| EH39 | GC wasp coming into the salon | Hogg Estate S | 2016 |
| EH21 | down pipe at back is leaking | Hogg Estate S | 2016 |
| EH33 | Pest Control small caterpillar/worms in carpets L room & hall | Hogg Estate S | 2016 |
| EH42 | Pest Control - wasps nest on roof above bathroom w indow | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - silverfish in bathroom | Hogg Estate S | 2016 |
| EH32 | Pest Control wasps nest going into roof at LHS near bedroom window | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - Slugs in kitchen. Keep coming back | Hogg Estate S | 2016 |
| EH32 | Pest Control mice in kitchen.ongoing issues | Hogg Estate S | 2016 |
| EH32 | PEST CONT wasps nest under eaves at back of property | Hogg Estate S | 2016 |
| EH31 | Pest control - Wasps on the right of side of house at vents befoer the back gate | Hogg Estate S | 2016 |
| EH32 | Pest Control wasps nest front bedroom window going into roof | Hogg Estate S | 2016 |
| EH21 | Pest control - Wasps nest below bedroom window in air vent. Front of property | Hogg Estate S | 2016 |
| EH32 | pest control - blue bottle infestion in bathroom | Hogg Estate S | 2016 |
| EH32 | mice in property | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - ants in the kitchen | Hogg Estate S | 2016 |
| EH33 | gc Wasp nest round the back of building | Hogg Estate S | 2016 |
| EH32 | Pest Control - Slaters in living room up walls, ongoing issue | Hogg Estate S | 2016 |
| EH41 | gc Wasps nest in St Marys Courtyard o/s rm 246 | Hogg Estate S | 2016 |
| EH32 | Pest control - Wasps in property - Bathroom | Hogg Estate § | 2016 |
| EH32 | Pest control - upper villa. wasps nest in rowan at front of house - away holiday thursday | Hogg Estate S | 2016 |
| EH21 | GB-Carry out treatments for more wasp nests at bothy and gate house areas. | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - rat in back garden between 64 and 62 | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - small bugs throughout property concerned has 5wk old baby | Hogg Estate S | 2016 |
| EH32 | Pest Control - flying ants investation in the hou se -coming from behind kitchen cupboards | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasps nest in the external porch at front door | Hogg Estate S | 2016 |
| EH33 | [as] eradicate problem with wasps at kitchen window | Hogg Estate S | 2016 |
| EH33 | cas large infestation of wasps in her kitchen | Hogg Estate S | 2016 |
| EH21 | Pest control - Ants in kitchen, looking for GH to attend ASAP, disabled tenant | Hogg Estate S | 2016 |
| EH21 | Pest control - Wasps nest. Wasps coming from kitchen light | Hogg Estate S | 2016 |
| EH21 | Ant infestation in kitchen | Hogg Estate S | 2016 |
| EH34 | wasps nest in attic | Hogg Estate S | 2016 |
| EH21 | GB-Check box office area for fleas etc-staff reporting insect bites. | Hogg Estate S | 2016 |
| EH34 | PEST CONTROL - wasp nest / ants at the back door Able to access | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - 3 x birds in the attic/ slugs, flys ants in kitchen | Hogg Estate S | 2016 |
| EH32 | Pest control - Bugs in carpets | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - Wasps nest inside front door under stairs where all the glass is. | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - mice droppings under kitchen sink | Hogg Estate S | 2016 |
| EH32 | pest control - wasps nest in attic | Hogg Estate S | 2016 |
| EH42 | remove and dispose of wasp nest | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasps in bathroom - getting in through bathroom window | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - Mice are back again, around back garden area and shed | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - wasp nest above bedroom window rear of the property, right hand side | Hogg Estate S | 2016 |
| EH32 | wasps nest outside at roof at front above window | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasps nest beside bedroom window (back bedroom upstairs) | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasps are back at the front porch | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - mice in livingroom | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - small fly's jumping & biting tenant | Hogg Estate S | 2016 |
| EH21 | wasps nest at front under window | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasps coming through light fitting in kitchen, poss from attic | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL * slugs in the house | Hogg Estate S | 2016 |
| EH42 | Wasps nest in bathroom. | Hogg Estate S | 2016 |

| EH31 | PEST CONTROL - woodlice returned | Hogg Estate S | 2016 |
|------|---|---------------|------|
| EH31 | PEST CONTROL - wasps going into vents at ground level (at rear of proeprty) | Hogg Estate S | 2016 |
| EH21 | Pest Control - wasps nest in vent outside back door where the bin is. | Hogg Estate S | 2016 |
| EH21 | pest control as per estimate | Hogg Estate S | 2016 |
| EH21 | GB-Carry out treatment for wasps. | Hogg Estate S | 2016 |
| EH21 | GB-Remove pigeon nest from CCTV camera at rear ramp area. | Hogg Estate S | 2016 |
| EH21 | Pest control - mice in the property | Hogg Estate S | 2016 |
| EH33 | wasps nest at left of front door | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - mice nest found by tenant | Hogg Estate S | 2016 |
| EH41 | [as] Wasps nest in Gym Hall req removal | Hogg Estate S | 2016 |
| EH21 | Emg Wasps nest on front door at vent - tenants be ing stund when entering flats | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - wasps nest at front door coming through vent brick | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - wasps nest in attic area, getting in through vents in roof | Hogg Estate S | 2016 |
| EH32 | Wasps nest in guttering near bathroom window and in loft | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - flies nest in bedroom vents | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL- wasps nest at front door and window | Hogg Estate S | 2016 |
| EH41 | Pest Control lots of wasps in house - not sure if nest in attic - around back kitchen/bathroom area | Hogg Estate S | 2016 |
| EH21 | Pest Control Wasps nest in loft | Hogg Estate S | 2016 |
| EH32 | Pest Control wasp nest - recurring problem last out week commencing 13th | Hogg Estate S | 2016 |
| EH21 | EMG PEST CONTROL invasion of wasps in house tenant alergic to wasps | Hogg Estate S | 2016 |
| EH21 | wasps nest at left off front door | Hogg Estate S | 2016 |
| EH21 | wasps all in the kitchenout side window | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - rats in back garden area along back end of garden | Hogg Estate S | 2016 |
| EH39 | Pest Control bed bugs in property - recurring problem | Hogg Estate S | 2016 |
| EH21 | wasps nest at the front somewhere | Hogg Estate S | 2016 |
| EH33 | Pest Control wasps swarming at back - father been stung - poosible nest in roof no. 6? | Hogg Estate S | 2016 |
| EH33 | Pest control wasp going into roof area at front just above the bedroom window | Hogg Estate S | 2016 |
| EH31 | PEST CONT slugs in bedroom | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - silver fish in property | Hogg Estate S | 2016 |
| EH33 | Attend with JN 1096283 clear any insect nests behind cladding above front door | Hogg Estate S | 2016 |
| EH33 | wasps coming in house | Hogg Estate S | 2016 |
| EH42 | Pest Control dead rat in garden tenant requesting pest control to put poison down | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - ants in the proerty | Hogg Estate S | 2016 |
| EH33 | wasps at front at ven tand in kitchen | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasps nest roof/attic at rear above bedroom window | Hogg Estate S | 2016 |
| EH32 | Pest Control wasps nest in loft - going through pipe on attic | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - Rats in back garden | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - rats in kitchen and possibly under house | Hogg Estate S | 2016 |
| EH40 | Pest Control rats in back garden | Hogg Estate S | 2016 |
| EH32 | house covered in flies please spray | Hogg Estate S | 2016 |
| EH32 | beasties in the loft - Spider beetles | Hogg Estate S | 2016 |
| EH39 | Pest control - can hear scratching at night, neigh bour has had rat infestation so worried | Hogg Estate S | 2016 |
| EH41 | Pest officer - wasp nest outsdie bathroom window u pper flat | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - black beast in bathroom and kitchen | Hogg Estate S | 2016 |
| EH34 | [as] Eradicate problem with mice in nursery theres also a problem with ants in kitchen area | Hogg Estate S | 2016 |
| EH21 | Pest Control wood lice & beetles in house | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - wasp nest in attic | Hogg Estate S | 2016 |
| EH21 | Pest Control rats in back garden | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - front bedroom upstairs infested with blue bottles. | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - wasps nest in attic area | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - brown beasties in livingroom & kitchen | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasp nest in the gutter/attic at the front on right hand side, next TV aerial | Hogg Estate S | 2016 |
| EH41 | [as] eradicate problem with wasps | Hogg Estate S | 2016 |

| EH30 | Wanna in attic | Haga Fatata C | 2016 |
|--------------|---|-----------------------------|------|
| EH39 EH41 | Wasps in attic PEST CONTROL - mice in attic area | Hogg Estate S | 2016 |
| EH33 | Rat in back garden beside hut | Hogg Estate S Hogg Estate S | 2016 |
| EH39 | PEST CONTROL - mice droppings in bedroom | Hogg Estate \$ | 2016 |
| EH35 | Mice in all the house | Hogg Estate S | 2016 |
| EH32 | Pest Control something scratchiing inside hall wall not sure if it's rat or something? | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - Mice in property, have bitten through telephone cable | Hogg Estate S | 2016 |
| EH42 | Pest Control - Rats in back garden - thinks there may be nest under the shed | Hogg Estate S | 2016 |
| EH32 | Pest Control - tenant thinks there is a wasps nest in attic, can here them at night and seen a few fl | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasp nest front of property, above main door, fly infestation in main starts | Hogg Estate S | 2016 |
| EH32 | Pest Contol - multitude of flies in house and wasp nest above front door at top of flats | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - Mice in attic area, can hear scratching noises | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - black type beetles throughout property, mainly livingroom | Hogg Estate S | 2016 |
| EH42 | Pest Control tenant seen rat in front garden | Hogg Estate S | 2016 |
| EH35 | pest control - flies in back bedroom | Hogg Estate S | 2016 |
| EH22 | GC vermin in dusties office see text | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - rodents under floor boards | Hogg Estate S | 2016 |
| EH21 | Pest Control wasps nest in attic - please call to arrange access tel.no. 07979450805 | Hogg Estate S | 2016 |
| EH34 | Pest Contol - mole in the front garden | Hogg Estate S | 2016 |
| EH32 | as per phone call 21/10 disturbance of flies aga again men being bitten on body | Hogg Estate S | 2016 |
| EH32 | pest control - insect in the property that she wan ts investigated, was in ceiling | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - mice under kitchen sink | Hogg Estate S | 2016 |
| EH21 | please spray house for flies key jl | Hogg Estate S | 2016 |
| EH39 | Pest Control - thinks may be wasps in attic, cant get access as attic locked as solar panels | Hogg Estate S | 2016 |
| EH33 | GB-Carry out treatment for mice in building & check blue bottle issue at first floor. | Hogg Estate S | 2016 |
| EH41 | Pest Control - Thinks there may be rats in property | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - rats/mice in property | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL OCT/DEC 2016 as per invoice 8009.16 | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL EXT BIRDS NESTING MAKING HOLES INTO THE WOOD TRYING TO MAKE WAY THROUGH INTERNALLY | Hogg Estate S | 2016 |
| EH41 | Pest Control - wasps nest in attic | Hogg Estate S | 2016 |
| EH42 | Pest Control - snails in the kitchen, doesnt know where they are coming from | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - Bad smell under shed after rat poison put down. possible dead rat | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - fruit flies in the property | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - fruit flies in property | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - fruit flies in the property1 | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - mice in garden hut | Hogg Estate S | 2016 |
| EH21 | GB-Replace anti bird spikes at CCTV camera area at rear of building. | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - flies in the attic space which they are nipping the tenant. | Hogg Estate S | 2016 |
| EH32 | Pest Control - dead pigeon in the attic space and bird droppings | Hogg Estate S | 2016 |
| EH32 | Pest Control rat in kitchen gone behind washing machine | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - several wasps in the cupboard possible nest in the attic | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - rat climbing up tree at the side of garden - council land | Hogg Estate S | 2016 |
| EH32 | PEST CONTOL - small flies in property they are biting the tenant and all over the house | Hogg Estate S | 2016 |
| EH41 | REMOVE WASP NEST IN PROPERTY | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - beetls and maggots comign out of skirtings in various rooms | Hogg Estate S | 2016 |
| EH39 | Pest Control - wasp nest in the loft | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - mice in house in walls & slugs in kitchen | Hogg Estate S | 2016 |
| EH21 | Pest Control - lots black flies in house, tried everything | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - rat hole in back garden | Hogg Estate S | 2016 |
| EH21 | BLOCK - main door intercom panel showing error codes, dr jammed open | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - Rats possibly in garden wants rat traps. Advised to speak to housing offic | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - silver fish in bathroom | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - mouse or rat in property, has already tried own traps | Hogg Estate S | 2016 |

| EH41 | PEST CONTROL - rat droppings in tank cupboard | Hogg Estate S | 2016 |
|------|--|---------------|------|
| EH32 | PEST CONTROL - rats in attic and possibly boiler cupboard | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - dead rats & live rats in garden | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - rats in property - tenant seen one in kitchen this morning | Hogg Estate S | 2016 |
| EH35 | Pest Control - mice droppings under the sink | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - rats in the bedrooms | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - mice in the kitchen | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - possible mice in property, unsure if in kitchen wall cavity | Hogg Estate S | 2016 |
| EH33 | GB-Carry out treatment for rats in Howden wing garden. | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - possible flies in the property mutual exchange and previous tenant has 9 cats | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - poss mice in property, unsure is stuck between flr board & ceiling | Hogg Estate S | 2016 |
| EH42 | Pest Control - fleas in the house, gas team wont d o work unless sprayed - would need 5th or 6th dec | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - rats in the back garden | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - rats in back garden area. | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL mice in the bedroom air vent chewing up material | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - mice in property, hole in corner of livingroom | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - mice or rats in attic | Hogg Estate S | 2016 |
| EH32 | Pest Control saw rat in kitchen, hears scratching under floorboards | Hogg Estate S | 2016 |
| EH33 | GB-Carry out treatment for mice in Contact Centre kitchen. | Hogg Estate S | 2016 |
| EH22 | PEST CONTROL rats on site. Bait boxes need refill | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - finding wasps in property, poss under property also frt vent | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - bluebottles throughout the house | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - mice in hut, small hut and garage | Hogg Estate S | 2016 |
| EH33 | Droppings and activity in attic | Hogg Estate S | 2016 |
| EH42 | GB-Carry out pigeon survey & clean up at front of building. | Hogg Estate S | 2016 |
| EH32 | Pest Control bed bugs | Hogg Estate S | 2016 |
| EH41 | PEST CONT still have prob, therefore think its rats not mice(need to revisit) | Hogg Estate S | 2016 |
| EH33 | Pest control - possibly rats/mice in the property leave message on voicemail - works till 3.30pm | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - possible rodent in the kitchen Out between 10:30/14:30 works at school. | Hogg Estate S | 2016 |
| EH21 | Pest Control infestation of rats - appear to be under the house | Hogg Estate S | 2016 |
| EH32 | spray for flies men complaining | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL possible rats in loft can hear noise | Hogg Estate S | 2016 |
| EH42 | Pest Control mice possibly in house maybe nesting at back vent toilet area, insulation showing | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - bugs under the lino look like caterpillars | Hogg Estate S | 2016 |
| EH21 | PEST mice in property especially kitchen | Hogg Estate S | 2016 |
| EH33 | Pest control - Flying insects in the property. | Hogg Estate S | 2016 |
| EH33 | Pest Control - rats are in the attic - Hogg Estates out yesterday by no poison put in attic | Hogg Estate S | 2016 |
| EH39 | PEST CONTROL - flea's/bed bugs in house | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - mice under kitchen base unit | Hogg Estate S | 2016 |
| EH42 | Pest Control fly infestation in attic please I resolve | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - rats in attic. Droppings and nests | Hogg Estate S | 2016 |
| EH32 | Pest Control - flying ants in property | Hogg Estate S | 2016 |
| EH41 | Pest Control rats in loft again - looks like they are nesting in extractor fan flue | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - bluebottles throughout - started to come back | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL rat or mouse in livingroom | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - rat in kitchen | Hogg Estate S | 2016 |
| EH21 | PEST CONT mice in property in bedroom | Hogg Estate S | 2016 |
| EH42 | [as] Eradicate problem with vermin in after school club | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - tenant thinks may have rats/ mice in property | Hogg Estate S | 2016 |
| EH32 | Pest control - not happy sbout them coming back in 2 weeks to spray, please call, bed bugs | Hogg Estate S | 2016 |
| EH21 | Pest control - Tenant says there are birds in the vent of the boiler | Hogg Estate S | 2016 |
| EH41 | H@S camera all drains report back contact S Hood from site | Hogg Estate S | 2016 |
| EH41 | [as] Eradicate problem with ants in main kitchen | Hogg Estate S | 2016 |
| | | | |

| EH21 | Pest Control mice throughout house | Hogg Estate S | 2016 |
|------|--|---------------|------|
| EH32 | Pest control - Mrs Russell has seen another mouse | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - rats in back garden | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - mice in the bedroom | Hogg Estate S | 2016 |
| EH21 | Pest Control - mice in the kitchen | Hogg Estate S | 2016 |
| EH41 | [as] remove bird from building and block access hole that birds are getting in | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - in attic there is either mice/rats hearing scratching & chewing on something | Hogg Estate S | 2016 |
| EH33 | Pest control - mice in cupboards | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - mice in property. In cupboards | Hogg Estate S | 2016 |
| EH33 | Pest Control - rat in the garden - seen a couple of times over the last few days | Hogg Estate S | 2016 |
| EH33 | rat pison put down by contractor house now full of bluebottles also can poison be removed | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - rats at back door area | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - rat in back garden | Hogg Estate S | 2016 |
| EH33 | Pest Control Rats in garden | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - mice in house, think may be in the wall | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - mouse/rat in property, poss access under kitchen base unit | Hogg Estate S | 2016 |
| | | | |
| EH32 | PEST CONTROL - possible mice/rat at back door area | Hogg Estate S | 2016 |
| EH32 | Rats/mice in attic ,room | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - rats in property via hole in back step & vent | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - bettles in the bedroom | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - beetles/ woodwarm & silver fish in property. Tenant has no phone number but is in | Hogg Estate S | 2016 |
| EH42 | GB-Carry out treatment for mice in office cupboard | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - infested with bugs. | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - rats in the back garden | Hogg Estate S | 2016 |
| EH41 | Pest Control mice in house - Mr. Lindgren in bed most of time but back door open, knock & shout | Hogg Estate S | 2016 |
| EH42 | Block Pest Control rats at communal bin area | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - bin stores outside block 14 - rats in bin area | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - rats in the walls | Hogg Estate S | 2016 |
| EH33 | PEST CONT still hearing rats in bedroom | Hogg Estate S | 2016 |
| EH33 | GC rats seen around the building , Holes at the bo iler room into the dirt | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - sml black bugs in kitchen, hall & bathroom area | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - rats in back garden area, see holes under fence area | Hogg Estate S | 2016 |
| EH33 | Pest control - Rats in property | Hogg Estate S | 2016 |
| EH39 | Pest Control - lots of slugs in kitchen. Tried everything | Hogg Estate S | 2016 |
| EH33 | mice under sink in kitchen | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL the whole house is covered in flees unable to control | Hogg Estate S | 2016 |
| EH42 | PEST CONT rat in garden | Hogg Estate S | 2016 |
| EH32 | GC Potential sighting of mice droppings in oven. | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - Rat in kitchen | Hogg Estate S | 2016 |
| EH32 | Confirmation of Pest Management jan/mar 2017 as per invoice 8140 | Hogg Estate S | 2016 |
| EH21 | Pest Control silverfish & beetles in kitchen | Hogg Estate S | 2016 |
| EH33 | Pest control - Rat in garden on decking | Hogg Estate S | 2016 |
| EH41 | Pest Control - mice again, heard them in bedroom c upboard | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - fly infestation throughout the house | Hogg Estate S | 2016 |
| EH41 | Pest control- Thinks there is a rat in the kitchen She asked if PC can be quick | Hogg Estate S | 2016 |
| EH33 | Mice in the livingroom | Hogg Estate S | 2016 |
| EH35 | PEST CONTROL - flea issue in bedroom | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - mice in attic, kitchen, all over house - tenant said mice droppings in everyroom | Hogg Estate S | 2016 |
| EH32 | Pest control - Mice and crawling bugs in property. Advised property isn't very clean | Hogg Estate S | 2016 |
| EH21 | Pest control - Silverfish | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - kitchen/livingroom & bedrooms | Hogg Estate S | 2016 |
| EH32 | Pest Control - black flies in house. Everyone in block having same issue | Hogg Estate S | 2016 |
| EH33 | Pest Control - mice in the towel cupboard | Hogg Estate S | 2016 |

| Files | | | 2212 |
|--------------|---|-----------------------------|------|
| EH39 | PEST CONTROL brown rats in the kitchen has chewing through the wall. Has put poison. | Hogg Estate S | 2016 |
| EH21 | Pest Control - mice in back of property going into holes and walls. | Hogg Estate S | 2016 |
| EH31 EH33 | Pest control - mice behind the boiler cupboard? Fr uit getting eaten at night | Hogg Estate S Hogg Estate S | 2016 |
| EH41 | slugs in shower room pest control birds going into attic from side of property above L room window | Hogg Estate \$ | 2016 |
| EH33 | Pest control - Rats in garden | Hogg Estate \$ | 2016 |
| EH33 | PEST CONTROL -rats in back garden | Hogg Estate S | 2016 |
| EH32 | GB-Carry out treatment for ants in kitchen area. | Hogg Estate \$ | 2017 |
| EH32 | PEST CONTROL up beside the fence next the hut rats are appearing. Digging holes in the ground | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - mice in the stairwell | Hogg Estate \$ | 2016 |
| EH33 | PEST CONTROL - mouse in attic | Hogg Estate S | 2016 |
| EH32 | rats running about bathroom after contractor lifted floor wet/floor going inj | Hogg Estate \$ | 2016 |
| EH21 | Pest Control insects/caterpillars in bedroom at skirting | Hogg Estate S | 2016 |
| EH21 | rats /mouse in the attic | Hogg Estate \$ | 2016 |
| EH31 | PEST CONTROL - rats in back garden | Hogg Estate S | 2016 |
| EH21 | Pest Control wasps nest on corner of building & wasps are getting into house (queens wasps) | Hogg Estate S | 2016 |
| EH33 | follow up visit for rats | Hogg Estate S | 2016 |
| EH32 | Pest control beast coming out of wood work in cupboard & wall in bedroom - report back to | Hogg Estate S | 2016 |
| EH35 | Pest Control gnawing noises coming from the attic | Hogg Estate S | 2016 |
| EH41 | PEST CONT tenant hearing gnawing noises in walls. Back bedroom. | Hogg Estate \$ | 2016 |
| EH33 | Pest Control - mice n attic | Hogg Estate S | 2016 |
| EH21 | Pest control - mice in attic | Hogg Estate \$ | 2016 |
| EH33 | PEST CONTROL infested with fleas dog has been treated, came from dog downstairs | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - slugs in kitchen | Hogg Estate S | 2016 |
| EH39 | PEST CONT rat seen under decking | Hogg Estate S | 2016 |
| EH41 | Pest Control - scratching heard in attic also slaters in the bathroom | Hogg Estate S | 2016 |
| EH32 | rats in garden | Hogg Estate S | 2016 |
| EH42 | Pest Control - wasps appearing in the bedroom near window - cant see where they are coming from | Hogg Estate S | 2016 |
| EH21 | Pest Control - possible rats, food in the kitchen with bite marks in it, has been rats in the past | Hogg Estate S | 2016 |
| EH39 | PEST CONTROL - hyde beetles have came back again in property | Hogg Estate S | 2016 |
| EH42 | PEST CONTROL - slaters in kitchen and bathroom | Hogg Estate S | 2016 |
| EH33 | Pest Control bird or animal in attic noisy | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - rear of property there a hole next to drain visable signs of rats. | Hogg Estate S | 2016 |
| EH41 | Pest Control - Bug infestation - Hogg Estates to attend | Hogg Estate S | 2016 |
| EH41 | Pest control Birds nest in bathroom fan vent | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL-100-200 ants in kitchen at wkend Told to call us 1st sign of ants this season. | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - rat in garden | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - rats in garden under shed | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - large brown rat in the back garden they have been digging a hole (covered with dirt | Hogg Estate S | 2016 |
| EH32 | Pest Control - mice in kitchen whole in wall behind cooker | Hogg Estate S | 2016 |
| EH21 | Pest Control Rats in garden also seen in 35 | Hogg Estate S | 2016 |
| EH21 | rat spotted in garden | Hogg Estate S | 2016 |
| EH41 | Pest control - Rat in garden | Hogg Estate S | 2016 |
| EH32 | PEST CONTROL - wasp nest in attic | Hogg Estate S | 2016 |
| EH39 | GC ants are in building see text | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - silver fish in the bathroom | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - Mice in kitchen | Hogg Estate S | 2016 |
| EH33 | PEST CONT rats under decking | Hogg Estate S | 2016 |
| EH35 | Pest control mice in kitchen | Hogg Estate S | 2016 |
| EH22 | AVI PEST CONTROL - all pitches impacted with mices | Hogg Estate S | 2016 |
| EH33 | Pest Control - rats in back garden | Hogg Estate S | 2016 |
| EH21 | large wasps flying about in attic | Hogg Estate S | 2016 |
| EH21 | PEST CONTROL - bird getting in through the wall at front of property - nest building | Hogg Estate S | 2016 |

| EH41 | Pest Control - mouse in kitchen | Hogg Estate S | 2016 |
|------|---|---------------|------|
| EH41 | PEST CONTROL - ants in kitchen. | Hogg Estate S | 2016 |
| EH32 | GC ants in Day centre area | Hogg Estate S | 2016 |
| EH21 | Pest Control rat in bathroom | Hogg Estate S | 2016 |
| EH32 | GB-Carry out a treatment for ants in dining room. | Hogg Estate S | 2017 |
| EH21 | Pest Control - ant infestion in kitchen | Hogg Estate S | 2016 |
| EH42 | GB-Carry out a treatment for rats around Groundcare Depot. | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - Black beetles in the property I have email Scott Hood | Hogg Estate S | 2016 |
| EH35 | Pest control spray prior to ant infestation as advised 2016 | Hogg Estate S | 2016 |
| EH41 | PEST CONTROL - mice in the property | Hogg Estate S | 2016 |
| EH33 | PEST CONTROL - rats under decking in garden area | Hogg Estate S | 2016 |
| EH41 | [as] attend ant problem in kitchen | Hogg Estate S | 2017 |
| EH32 | Pest control - Crows building a nest in chimney at the back of the property | Hogg Estate S | 2016 |
| EH39 | Pest Control ants in kitchen | Hogg Estate S | 2016 |
| EH42 | Pest control - Tenant thinks there are birds in the loft space. Can hear pecking | Hogg Estate S | 2016 |
| EH32 | Pest control - birds or mice or both | Hogg Estate S | 2016 |
| EH32 | ants in house | Hogg Estate S | 2016 |
| EH41 | GB-ant infestation at property-see office staff for location. | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - possible bird or mice at fire area | Hogg Estate S | 2016 |
| EH33 | Pest Control possibly slugs in kitchen going up curtains - report back how they are getting in | Hogg Estate S | 2016 |
| EH21 | GB-Carry out treatment for ants in duty room. | Hogg Estate S | 2017 |
| EH33 | Pest Control - rats in the back garden | Hogg Estate S | 2016 |
| EH41 | Pest Control - Rat in property | Hogg Estate S | 2017 |
| EH42 | Pest Control - mice in the bedrroom in the corner | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - ant infestation in toilet cistern unsure how they are getting in | Hogg Estate S | 2017 |
| EH39 | Pest control - been out and baited it but needing a return visit | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - flies in property, has tried fly spray, not worked, poss under rhones | Hogg Estate S | 2017 |
| EH32 | PEST CONT birds building a nest in chimney and has gas fire | Hogg Estate S | 2017 |
| EH36 | Rats in back garden | Hogg Estate S | 2017 |
| EH33 | pest control - rats at garden and number 11 - rubb ish in garden | Hogg Estate S | 2017 |
| EH41 | [as] check for mice behind wall, see staff for loc | Hogg Estate S | 2017 |
| EH32 | Birds nesting & pulling insulation out of attic at back righthand side of building just before roof | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL- mice in livingroom | Hogg Estate S | 2017 |
| EH42 | seugull control as discussed | Hogg Estate S | 2017 |
| EH21 | Pest control - Tenant has seen a rat coming from the bin area. | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - right underneath window at air vent large wasps nest | Hogg Estate S | 2017 |
| EH35 | Pest Control ants in kitchen | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - ants in kitchen | Hogg Estate S | 2017 |
| EH32 | Pest Control flies in kitchen | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - 2 wasps nest and birds nest (none in it) | Hogg Estate S | 2017 |
| EH33 | slugs in kitchen | Hogg Estate S | 2017 |
| EH21 | Pest control - mice in the property | Hogg Estate S | 2017 |
| EH21 | Pest Control rats in garden | Hogg Estate S | 2017 |
| EH21 | Fumigate throughout | Hogg Estate S | 2017 |
| EH33 | Pest Control - wasps above the back bedrrom window | Hogg Estate S | 2017 |
| EH21 | GC ants in room 3. | Hogg Estate S | 2017 |
| EH41 | [as] check for rats / mice getting under building at front door | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL rats in the back garden coming from private next door. | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - rats under hut in back in garden | Hogg Estate S | 2017 |
| EH33 | Homeless: remove bird from property | Hogg Estate S | 2017 |
| EH39 | GC Ants in kitchen area | Hogg Estate S | 2017 |
| EH33 | Pest Control ants in kitchen & bedroom | Hogg Estate S | 2017 |
| EH41 | Pest Control - still issues with mice in kitchen | Hogg Estate S | 2017 |

| E1104 | Deat Control In action in headening around altistic as 9 in formitum | Harr Fatata C | 2047 |
|--------------|---|---------------|------|
| EH21 | Pest Control beetles in bedrooms around skirtings & in furniture | Hogg Estate S | 2017 |
| EH42 | Pest Control mice in bedroom cupboard | Hogg Estate S | 2017 |
| EH21 EH39 | PEST CONTROL - wasps getting into property possible nest outside window PEST CONTROL - poss birds starting to nest at gas supply pipe frt door SEE NOTES | Hogg Estate S | 2017 |
| EH35 | Infestation of ants in kitchen | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - invasion of mice (unknown how many all over the house) | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - rat in garden | Hogg Estate S | 2017 |
| EH32 | GC wasps nest in playground | Hogg Estate S | 2017 |
| EH34 | Wasps nest at front of house under bathroom window | Hogg Estate S | 2017 |
| EH32 | Pest Control mice at hut at front door also hut & garage in back door | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL rats in garden possibly under the hut | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - bugs in her house - she has caught some in a jar | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - slugs in kitchen | Hogg Estate S | 2017 |
| EH33 | Pest Control ants in kitchen | Hogg Estate S | 2017 |
| EH32 | GC wasps in the building see text | Hogg Estate S | 2017 |
| EH41 | GC ants ladies toilet block | Hogg Estate S | 2017 |
| EH32 | Confirmation of Pest Control APR/JUN 2017 as per invoice 8257 | Hogg Estate S | 2017 |
| EH32 | Pest Control rats coming into no. 59's garden up at neighbour old dog kennel | Hogg Estate S | 2017 |
| EH21 | GB-Carry out treatment for ants in the Bistro office.(ants are on window ledge). | Hogg Estate S | 2017 |
| EH32 | PEST CONT ants in property at front door Only 5 or 6. Wants someone out. | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - slugs in 2 end bedrooms & hall | Hogg Estate S | 2017 |
| EH33 | Pest Control - rat coming between this property and number 8, tried to catch it but no success | Hogg Estate S | 2017 |
| EH35 | Pest Control - Ants infestation in the hall and li ving room | Hogg Estate S | 2017 |
| TD13 | GB-Carry out a treatment for rats near toilet block. | Hogg Estate S | 2017 |
| EH33 | pest control - still getting wasps coming in her b ack bedroom?? | Hogg Estate S | 2017 |
| EH32 | PEST CONTOL beehive at back door at the back of a pipe | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - Rats or mice in the house. | Hogg Estate S | 2017 |
| EH32 | GB-Carry out treatment for wasps in attic & ants in Comm Centre kitchen. | Hogg Estate S | 2017 |
| EH39 | GB-Carry out treatment for wasps in main hall area | Hogg Estate S | 2017 |
| EH31 | Pest Control - Ant problem, at the door threshold this morning, keeps putting powder down | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - rats in garden | Hogg Estate S | 2017 |
| EH32 | PEST CONTOL - Wasps nest next to bedroom window at the back next to gutter/downpipe | Hogg Estate S | 2017 |
| EH21 | Fumigate house due to flea infestation | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - fleas in the house cat has been treated unsure where it is coming from | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - rats in front and back garden | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasps going in under guttering at back of house | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - tenant has complained of being bitten - thinks its in the bedrooms/beds | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - moths in the house | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - rats in house & garden | Hogg Estate S | 2017 |
| EH21 | GB-Carry out treatment for ants in rooms 4,5 & 6. | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - Mice in house. | Hogg Estate S | 2017 |
| EH21 | Pest Control infestation of big black flies in bathroom - has been using fly spray, not working | Hogg Estate S | 2017 |
| EH32 | Pest control - mice in the property | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL Rats in garden | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - beetles in the property | Hogg Estate S | 2017 |
| EH34 | PEST CONTROL - beetle type insects mainly in bedroom area/sliding wardrobe | Hogg Estate S | 2017 |
| EH42 | Pest Control - Wasps nest at the back door | Hogg Estate S | 2017 |
| EH33 | pest control possible wasps nest below bathroom window | Hogg Estate S | 2017 |
| EH35 | PEST CONTROL - wasps nest underneath guttering above bck dr LHS | Hogg Estate S | 2017 |
| EH42 | Pest Control - rats around the property, cat keeps bringing them in | Hogg Estate S | 2017 |
| EH35 | Pest Control - Ants in the kitchen | Hogg Estate S | 2017 |
| EH35 | PEST CONTROL - Ant infestation in kitchen, surrounding sink area | Hogg Estate S | 2017 |
| EH42 | [as] Eradicate problem with vermin in after school club | Hogg Estate S | 2017 |

| EH41 | [as] Eradicate problem with ants in main kitchen and room 9 [sensory room] | Hogg Estate S | 2017 |
|------|---|---------------|------|
| EH39 | Pest control - Thinks theres a wasp / bee nest in attic | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - slugs and ants in house | Hogg Estate S | 2017 |
| EH42 | VOID/HOGG ESTATE/PEST CONTROL IN KITCHEN | Hogg Estate S | 2017 |
| EH21 | Pest Control seagulls nesting on chimney stack | Hogg Estate S | 2017 |
| EH35 | PEST CONTROL - rats in the back garden Please call to arrange access locked gate | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - scratching sound from livingrm up to bedrm, sml hole next to bedrm light | Hogg Estate S | 2017 |
| EH40 | Pest control reports of mice in kitchen | Hogg Estate S | 2017 |
| EH39 | PEST CONTROL - wasps in attic area, finding them in bedroom, tenant been stung | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - slugs in property | Hogg Estate S | 2017 |
| EH21 | pest control - wasp nest below bedroom window - front house middle window | Hogg Estate S | 2017 |
| EH21 | GB-carry out treatment for mice in property-keys at Sports Centre or with Caroline. | Hogg Estate S | 2017 |
| EH32 | Rat in the stair but away now, tenant wants pest control to check for nest nearby | Hogg Estate § | 2017 |
| EH39 | Pest Control - ants in the property in the kitchen | Hogg Estate S | 2017 |
| EH33 | GB-Carry out a treatment for rats outside 110A Church Street-former Alpha Signs. | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - rats in property rear garden | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - fleas in property cat hasd been treated and still fleas indoors | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - rats in the attic | Hogg Estate S | 2017 |
| EH41 | GB-Carry out treatment for ants in small dining area. | Hogg Estate S | 2017 |
| EH33 | VOID/HOGG/SPRAY WHOLE HOUSE FOR FLEAS | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - at back door on right hand side poss wasps nest | Hogg Estate S | 2017 |
| EH21 | [as] eradicate problem with rats under TU floor | Hogg Estate S | 2017 |
| EH21 | infestation off beasts in bathroom and kitchen | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - rat in back garden | Hogg Estate S | 2017 |
| EH21 | birds nesting on the roof at back | Hogg Estate S | 2017 |
| EH41 | wasps coming into property at living and bedroom window | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - black bugs in the kitchen | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasps nest in holly tree in bck garden. Concerned for young children | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - ants in the house at the front door | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps nest at front door | Hogg Estate S | 2017 |
| EH39 | NSA PEST CONTROL - wasps nest under the house - needlestick aware, tenant advised needles | Hogg Estate S | 2017 |
| EH32 | [as] eradicate problem with ants in cafe and i puffin area | Hogg Estate S | 2017 |
| EH32 | Pest control - Wasps nest just outside back door | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - ants in kitchen | Hogg Estate S | 2017 |
| EH33 | Block - PEST CONTROL, Scratching heard at the top corrider | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasps nest in fence at back door | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - 2 wasps nests at back of house at guttering | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - ant at front door coming up onto worktops & floors | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - small black caterpillar types bugs in room around wall/bed | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps going in pipe at front of property | Hogg Estate S | 2017 |
| EH41 | GB-Carry out treatment for ants in room 2. | Hogg Estate S | 2017 |
| EH32 | infestation of ants coming into house from communa path at front | Hogg Estate S | 2017 |
| EH32 | infestation of ants coming in front door | Hogg Estate S | 2017 |
| EH32 | wasps in house | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - Possible bed bugs | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - thinks she has mice above bedroom and in walls | Hogg Estate S | 2017 |
| EH32 | gc ANTS IN KITCHEN AND pUFFIN ROOM | Hogg Estate S | 2017 |
| EH22 | Block AVI Pest control for the site, no tenants at present. rats | Hogg Estate S | 2017 |
| EH34 | Pest Control rats in back garden | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL wasp nest at kitchen window between bathroom/bedroom wasp nest, | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - wasp nest at front door | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - bees in the garden hive in the lawnmower near back door area | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - Mice in the kitchen | Hogg Estate S | 2017 |

| EH33 | birds under bath | Hogg Estate S | 2017 |
|------|---|---------------|------|
| EH32 | Birds going in the Facia Eaves at front of property | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - wasps in coalbunker and gutter | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - bees/wasps nest at front of property at overflow pipe (gap) | Hogg Estate S | 2017 |
| EH21 | GB-Investigate & carry out a treatment for rats at the rear of Brunton Hall. | Hogg Estate S | 2017 |
| EH39 | PEST CONTROL - ants in the kitchen | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasp nest in the attic | Hogg Estate S | 2017 |
| EH21 | Mole in garden at front at path right hand side advised to put job on by Gavin | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - bees nest in bird box attach to hut and mice coming from no 5 into | Hogg Estate S | 2017 |
| EH31 | Pest Control - ant infestation in the kitchen | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - beetles in bedrms around skirting & in some furniture | Hogg Estate S | 2017 |
| EH32 | Pest control - 2 wasps nest at corner of guttering | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - bees nest back door going into attic/back bedroom window (going into vent at | Hogg Estate S | 2017 |
| EH34 | PEST CONTROL - wasp nest above the kitchen window | Hogg Estate S | 2017 |
| EH35 | PEST CONTROL - wasps going into house from front door | Hogg Estate S | 2017 |
| EH31 | PEST CONTROL- seen rats in back garden | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - under bathroom window outside wasps are nesting in the vent which is no longer in use. | Hogg Estate S | 2017 |
| EH42 | GB-Carry out a further treatment for rats around depot. | Hogg Estate S | 2017 |
| EH32 | PEST CONT bees nest outside back door prev advised masonery bees but sone just | Hogg Estate S | 2017 |
| EH32 | wasps nest in the shed | Hogg Estate S | 2017 |
| EH33 | PEST CONT bees entering holes in wall. 1ft from ground under back liv rm window. | Hogg Estate S | 2017 |
| EH32 | GB-Carry out a treatment for ants in main reception area. | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - bees at the rhone pipe at back of house | Hogg Estate S | 2017 |
| EH39 | Pest control - Bees in attic | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - beehive at back door | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - bees going into pipe at I/room window and into wall | Hogg Estate S | 2017 |
| EH33 | GB-Carry out treatment for ants in hall.Keys at Penston House if not open. | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - ants in the kitchen and bathroom wasps nest above I/room window | Hogg Estate S | 2017 |
| EH33 | Pest Control - bee hive at the back of the house, entering the house at the overflow pipe | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - ants in livingroom | Hogg Estate S | 2017 |
| EH35 | PEST CONTROL - Ant infestation in kitchen, does not know where coming from | Hogg Estate S | 2017 |
| EH32 | GC wasp nest in the nursery garden - | Hogg Estate S | 2017 |
| EH39 | GC wasps in th ebuilding see text | Hogg Estate S | 2017 |
| EH32 | GC ants in toilets see text | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - Flying ants in cavity wall under livingrm wdw, to call back when reappeared | Hogg Estate S | 2017 |
| EH33 | Pest Control - mice/rats in the loft, hearing scra tching | Hogg Estate S | 2017 |
| EH41 | [as] eradicate problem with ants in art room | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - ants in the kitchen | Hogg Estate S | 2017 |
| EH32 | GC wasp nest see text | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - rats in external property garden | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - ants in kitchen | Hogg Estate S | 2017 |
| EH31 | PEST CONTROL - wasps nest in eves of garden shed | Hogg Estate S | 2017 |
| EH33 | [as] eradicate problem with rats in Jim Wylies office/store room | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL wasps or bees going into the overflow into the attic | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - bee nest in roof/gutters | Hogg Estate S | 2017 |
| EH33 | Pest Control mice in outhouse & in kitchen | Hogg Estate S | 2017 |
| EH41 | VOID/HOGG ESTATES/REMOVE WASPS NEST FROM ATTIC | Hogg Estate S | 2017 |
| EH33 | Pest Control Nest of bumble bee's back garden where shet has been removed | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - Rats in back garden area, tenant has dogs | Hogg Estate S | 2017 |
| EH33 | Pest Control wasps at side of house - to rightside of house as you go in the path | Hogg Estate S | 2017 |
| EH36 | PEST CONTROL - rat in back garden | Hogg Estate S | 2017 |
| EH32 | Pest Control bees going in pipe at the back of house up by the rhone - getting into house | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - Ant infestation at front door & hallway | Hogg Estate S | 2017 |

| EH21 | Pest control ants in kitchen cupboard | Hogg Estate S | 2017 |
|------|--|---------------|------|
| EH21 | PEST CONTROL - blue bottles in kitchen | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - bide bottles in kitchen PEST CONTROL - bees in attic | Hogg Estate S | 2017 |
| EH21 | Pest Control bees going in and around hole under meter box at front of property - please report | Hogg Estate S | 2017 |
| EH33 | PEST CONT bees behind vent brick under kitchen window, near bins. | Hogg Estate S | 2017 |
| EH21 | PEST CONT bees nest above back bedroom window. Going in hole at side of downpipe. | Hogg Estate S | 2017 |
| EH33 | PEST CONT bee hive in attic, going under gutter at back of property. | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL check attic space for evidence of birds, squirrels or mice etc. | Hogg Estate S | 2017 |
| EH21 | Pest control - Wasps nest at the front of the property | Hogg Estate S | 2017 |
| EH32 | bees coming in at gable end at back of house and also at front | Hogg Estate S | 2017 |
| EH39 | PEST CONTROL bees nest at side of property | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - rat in back garden | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL- mice in the kitchen | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - Rat in back garden area | Hogg Estate S | 2017 |
| EH33 | rats coming in wall at back of house | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - beetles all over the house | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - squirrel possible under the floorboards/atic - nest in there | Hogg Estate S | 2017 |
| EH21 | Beasties in livingroom, elderly tenant | Hogg Estate S | 2017 |
| EH33 | Bees nest in the guttering at the back of property | Hogg Estate S | 2017 |
| EH33 | Pest Control rats in garden - rat holes at back fence btwn no. 4 | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - bees in cavity wall following install of new bathrm extractor fan | Hogg Estate S | 2017 |
| EH21 | Mice /Rats in back garden near the hut | Hogg Estate S | 2017 |
| EH21 | bees at back going in the roof | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - rats in outhouse, outhouse is at front door | Hogg Estate S | 2017 |
| EH21 | GB-Check & remove birds nest from gents toilet- 113 key for access if locked. | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL where the old gas box was at pipe front of house bees nest. | Hogg Estate S | 2017 |
| EH41 | Slugs in kitchen HOGG EST pest control | Hogg Estate S | 2017 |
| EH32 | EMG Bee's swarming in back garden - up top of garden - young children & pets | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - back door vent into wall that goes into cupboard. wasp nest | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - bees nest (in vennel between 2 houses at overflow area) | Hogg Estate S | 2017 |
| EH33 | void: pest control bees at front door | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - bee hive under back door step - door to vennel will be open | Hogg Estate S | 2017 |
| EH35 | PEST CONT wasps going into vent above back door an poss into attic. Not coming into kitchen. | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - bees nest in eves at frt of hse & also under garden shed | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - Ant infestation in kitchen | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - Bees nest directly above bedrm wdw, becoming aggressive | Hogg Estate S | 2017 |
| EH32 | Pest Control wasps or bees right hand side of house under eves (corner back side of house) | Hogg Estate S | 2017 |
| EH21 | Carry out a treatment for rats at garage/workshop & remove any dead rats. | Hogg Estate S | 2017 |
| EH33 | [as] remove seagull nest from roof, roof repair required, see janitor for location | Hogg Estate S | 2017 |
| EH42 | GB-Carry out a treatment for rats near the skip in the Cemetery. | Hogg Estate S | 2017 |
| EH42 | Pest Control slugs still coming into kitchen, even now vents have been closed off | Hogg Estate S | 2017 |
| EH21 | Pest control Blue bottles in the bathroom | Hogg Estate S | 2017 |
| EH32 | Pest control Ant infestation in the toilet cistern | Hogg Estate S | 2017 |
| EH21 | Pest control crawling insects keys @ Brunton Hall as per D Thompson | Hogg Estate S | 2017 |
| EH21 | Beasties in carpet worse, elderly tenant | Hogg Estate S | 2017 |
| EH41 | [as] eradicate problem with ants reported to be in trunking at window, see staff for info | Hogg Estate S | 2017 |
| EH39 | PEST CONTROL - hole at front of property possibly going upto attic (invasion of wasps) | Hogg Estate S | 2017 |
| EH32 | Pest Control bees both corners of house - gutters. Getting into house, young child terrified. | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - The grid at the back of kitchen has wasp nest, req permission from neigbour above | Hogg Estate S | 2017 |
| EH36 | Pest control - Mice have chewed through a vent under LR window near electrical sockets | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - ants coming in chimney breast/wall crawling/flying about the livingroom | Hogg Estate S | 2017 |
| EH33 | Wasps nest on outsie at kitcken window | Hogg Estate S | 2017 |
| EH32 | Pest Control loads of wasps at plum tree in back garden | Hogg Estate S | 2017 |

| EH31 | Pest control - Rat droppings at the back door. On holiday tomorrow for a week | Hogg Estate \$ | 2017 |
|------|---|----------------|------|
| EH41 | Pest Control Wasps swarming - going into the eves at the back of the house | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - bees nest in the loft, through the pipe and cavity. Large amount. | Hogg Estate S | 2017 |
| EH21 | Pest Control wasps nest btwn bedroom & bathroom window | Hogg Estate S | 2017 |
| EH21 | Pest Control wasps nest in back garden in the hedg at bottom of garden | Hogg Estate S | 2017 |
| EH42 | report of rats in binstore | Hogg Estate S | 2017 |
| EH32 | Pest control - Wasps going in beside bedroom window at the back | Hogg Estate S | 2017 |
| EH39 | Pest Control Bee's at the back of house going under the tiles at the end of rhone pipe | Hogg Estate S | 2017 |
| EH39 | Pest control - Thinks there are pigeons nesting in the loft space | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - bee hive in out house cellar | Hogg Estate S | 2017 |
| EH32 | Pest control Wasps nest in garden shed | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasps nest at front of property beside gas box | Hogg Estate S | 2017 |
| EH33 | Pest Control - Slugs in the kitchen, not sure wher e they are coming from | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - slugs all over prperty mainly bedroom & hallway | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - rats in back garden, near shed and bins | Hogg Estate S | 2017 |
| EH32 | wasp nest at livingroom window | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - ant infestion | Hogg Estate S | 2017 |
| EH21 | Pest Control ant infestation in kitchen | Hogg Estate S | 2017 |
| EH21 | GB-Carry out a treatment for ants in laundry. | Hogg Estate S | 2017 |
| EH21 | GB-Carry out a treatment for insects in reception back office-coming from ventilation duct. | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL at the front door outside at the arch on right handside wasp nest size of a tennis ball. | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL slugs in house | Hogg Estate S | 2017 |
| EH32 | Void: check blue bottles in flat | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - slugs and catipillars in kitchen | Hogg Estate S | 2017 |
| EH21 | Pest Control wasps nest in hut (back garden) | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - rats in the back garden | Hogg Estate S | 2017 |
| EH34 | [as] eradicate problem with ants at stage end of hall | Hogg Estate S | 2017 |
| EH21 | pest control - slugs in front hall | Hogg Estate S | 2017 |
| EH34 | Pest Control - Wasps nest in the garden at hut | Hogg Estate S | 2017 |
| EH21 | insects in the kitchen | Hogg Estate S | 2017 |
| EH34 | PEST CONTROL - wasps nest in bush at front door | Hogg Estate S | 2017 |
| EH34 | PEST CONTROL - wasps nesting under the house going in at the front | Hogg Estate S | 2017 |
| EH32 | void/hogg estate/fumigate property | Hogg Estate S | 2017 |
| EH33 | Pest Control bedbugs & silverfish infestation new tenant, new mattresses & everything being | Hogg Estate S | 2017 |
| EH31 | Wasps nest at vent at front of house under living window | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - at front of property the hedge has a bees nest at the edge, | Hogg Estate S | 2017 |
| EH32 | PEST CONT bees in pile of moss at back of garden | Hogg Estate S | 2017 |
| EH42 | wasp nest in attic | Hogg Estate S | 2017 |
| EH32 | Ants on worktops in kitchen | Hogg Estate S | 2017 |
| EH32 | bees going in low vents at back and front | Hogg Estate S | 2017 |
| EH33 | pest control bees going in vent at back under window very first vent | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - wasps nest in shed | Hogg Estate S | 2017 |
| EH42 | large quantity of mice droppings under bath | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - bees nest at front of property at the vent | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - scratching coming from attic unsure what it could be poss mice | Hogg Estate S | 2017 |
| EH33 | Pest Control - wasps in the garden shed | Hogg Estate \$ | 2017 |
| EH33 | PEST CONTROL - wasps in garage | Hogg Estate \$ | 2017 |
| EH21 | Pest Control - wood lice in the kitchen | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - ants in kitchen. | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - ants in I/room | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - rats in back garden area, nr to recycling at back door, possibly neighbours hut | Hogg Estate S | 2017 |
| EH21 | GB-Carry out a treatment for wasps nest near access door to caretakers flat. | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - blue bottles coming from side of fire places | Hogg Estate S | 2017 |

| EU04 | Deat Control mice in hitchen | Home Fototo S | 2047 |
|--------------|---|---------------|------|
| EH21 | Pest Control mice in kitchen | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - mice in kitchen | Hogg Estate S | 2017 |
| EH33 EH41 | PEST CONTROL - wasps entering hole top corner ledge of front door, may be in attic PEST CONTROL - flying ant infestation, mainly in kitchen area | Hogg Estate S | 2017 |
| | PEST CONTROL - hying and intestation, mainly in kitchen area PEST CONTROL - wasps going into house via vents | Hogg Estate S | 2017 |
| EH21 EH35 | Pest Control infestation blue bottles in tank cupb | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps nest under front door | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - wasps riest under nont door PEST CONTROL - bees nest undernath the I/room window ledge | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - mice in attic | Hogg Estate S | 2017 |
| EH21 | GB-carry out treatment for ants in dining room & laundry room. | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - wasps nest in eves btwn bed & bathrm, nr downpipe, unsure if in attic | Hogg Estate S | 2017 |
| EH21 | Pest Control Bee nest in attic | Hogg Estate S | 2017 |
| EH33 | Rats in back garden I/h/s rubbish | Hogg Estate S | 2017 |
| EH33 | Pest Control Slugs in kitchen | Hogg Estate S | 2017 |
| EH21 | GB-Carry out treatment for ants in staff toilet. | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - flies coming up in property | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - ants in porch area | Hogg Estate S | 2017 |
| EH21 | Pest control flying ants in house | Hogg Estate S | 2017 |
| EH33 | Wasps nest outside front door at gas meter | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - rats in shared attic area also rat droppings in cupboard, report back rodents | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - Brown ants in back garden. 10 ant hills, advised by Environmental Health | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - wasps nest on side of building in bush attached to hse, nr back door | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - bees nest in attic area, elderly tenant, access nr downpipe at frt of hse. | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - invasion of ants at the kitchen | Hogg Estate S | 2017 |
| EH21 | GB-Carry out a treatment for ants in toilet opposite room 6. | Hogg Estate S | 2017 |
| EH32 | Pest Control rats in garden near hut in back garden | Hogg Estate S | 2017 |
| EH39 | GB-Carry out a treatment for ants in the health suite area. | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - invasion of wasps in the vent at the back of house. | Hogg Estate S | 2017 |
| EH41 | EMG - ant infestation in livingroom - disabled tenant on CAS | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - ants in bedroom | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - wasp nest under gutters poss going into attic | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - ants invaded the front porch again. Advised if outside we cant touch them only inside | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps nest at side window and coming through vent into property | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps in property thinks may be nest in chimney | Hogg Estate S | 2017 |
| EH32 | Pest Control wasps all gather at drain pipe at bac | Hogg Estate S | 2017 |
| EH39 | PEST CONTROL - ants at front door and back | Hogg Estate S | 2017 |
| EH34 | PEST CONTROL - ant infestation in the kitchen tenant has dementia so just ask to explain why | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - ants & flying ants in the stair | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasps coming up through floorboards from underneath the stair well | Hogg Estate S | 2017 |
| EH33 | Pest Control - wasps nest at the back garden at th e fence | Hogg Estate S | 2017 |
| EH33 | pest control - slugs in the kitchen cuboard | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - ant infestation & small beetle type insects coming up through chimney breast | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - wasps possibly nesting in attic several wasps around this area | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - ants in bedroom | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - ant and flying ant infestation mainly seen at livingrm wdw area | Hogg Estate S | 2017 |
| EH21 | Pest Control - rats in the garden at the property, | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - ants nest at back door | Hogg Estate S | 2017 |
| EH39 | PEST CONTROL - wasps nest (poss in cavity) hole at rear livingrm wdw next to a vent | Hogg Estate S | 2017 |
| EH39 | PEST CONTROL - wasps nest at pipe in back garden | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - wasps nest at bathroom pipe | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL I - wasps nest in back of old rabbit hutch in garden | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - bird nesting on top of the electric box -bottom stairwell | Hogg Estate S | 2017 |
| EH32 | Pest Control lots of insects around livingroom window ledge and floor | Hogg Estate S | 2017 |

| EH32 | AVI-wasp nest under property | Hogg Estate S | 2017 |
|--------------|--|---------------|------|
| EH33 | PEST CONTROL - rats in back garden | Hogg Estate S | 2017 |
| EH35 | PEST CONTROL - ants in I/room | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - ants + flying ants in bathroom tenant says she cannot use bathroom | Hogg Estate S | 2017 |
| EH39 | PEST CONTROL - wasps nest in attic/rhones at the back door, tenant has bad reaction to wasps | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasps nest in vent under livingroom | Hogg Estate S | 2017 |
| EH32 | PEST CONTORL - ant infestation in kitchen area | Hogg Estate S | 2017 |
| EH32 | Pest Control - rats in the garden | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - in the bedroom there is rats ongoing problems with rats. | Hogg Estate S | 2017 |
| EH39 | PEST CONTROL - invasion of 'carpet beetles' are in few rooms sometimes. | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasps nest under front window in vent | Hogg Estate S | 2017 |
| EH21 | investigate and report back ie investation of flys as per callout on 24 july | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps nest on flat roof at front garden | Hogg Estate S | 2017 |
| EH32 | Pest Control ants in livingroom & kitchen | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - ants in the kitchen | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - mice in livingroom & kitchen | Hogg Estate S | 2017 |
| EH41 | Pest Control - wasps nest as the property at the b ack door | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps nest under tiles on roof possibly in attic | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasp nest at the side of the house above the wheelie bin, going into the wall | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL rat running in the bedroom. children in the house. | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - birs nesting in triangular facia area (back of house) | Hogg Estate S | 2017 |
| EH39 | PEST CONTROL - Above the back door the wasps have moved nest to above there. | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - ants in property | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL- slugs in kitchen every morning keeps removing them but coming back | Hogg Estate S | 2017 |
| EH21 | Pest Control wasps out back garden - lots in house hoping not in attic, can't see where coming from | Hogg Estate S | 2017 |
| EH32 | Confirmation of pest control Jul/Sept as per invoice 8343 | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - keeps getting slugs in the kitchen. | Hogg Estate S | 2017 |
| EH21 | PEST - wasps nest up at sofit in overflow pipe at back of property | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - beehive in garden at hut | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps nest in attic | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - wasps nest on roof at back at private property above 341 - SHARED | Hogg Estate S | 2017 |
| EH21 | GB-Carry out treatment for hornets nest at Musselburgh Windsor storage unit. | Hogg Estate S | 2017 |
| EH21 | pest control - silver fish (bathroom & kitchen) infestion | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasps nest somewhere in back garden | Hogg Estate S | 2017 |
| EH21 | pest control lots of beetles all in property | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - wasps nest at front door disabled lady can't use back dor | Hogg Estate S | 2017 |
| EH32 | AVI PEST CONTROL - wasps nest at air vent at garden path | Hogg Estate S | 2017 |
| EH41 | GB-Carry out a treatment for ants in bedroom 21 of main house. | Hogg Estate S | 2017 |
| EH31 | Pest Control Rat droppings again at back door | Hogg Estate S | 2017 |
| | PEST CONTROL - wasp nest at the front door | Hogg Estate S | |
| EH39 EH32 | PEST CONTROL - wasp nest at the front door PEST CONTROL - ants in kitchen & livingroom infestion | Hogg Estate S | 2017 |
| | PEST CONTROL - and in kitchen a livingroom fillestion PEST CONTROL - invasion of ants in the livingroom turning into flys - have put ant powder down. | | 2017 |
| EH35 | | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - wasps nest at side of house where roof hits the rhone | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasp nest in rhone back of property coming in bedroom window | Hogg Estate S | 2017 |
| EH33 | [as] eradicate problem with rats in buffer store area. | Hogg Estate S | 2017 |
| EH41 | [as] wasps nest in pr3 corridor [upstairs] | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasp nest in the eves/ loft | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL price in yeart at healt grander | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - mice in vent at back garden | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - clear wasps that have nest at scoor - under floor? | Hogg Estate S | 2017 |
| FLICE | | Hoga Estato C | 2017 |
| EH33 EH41 | Pest control - Wasp nest in vent at front of living room window PEST CONTROL - blue bottles in the I/room | Hogg Estate S | 2017 |

| ГЦээ | Deat central wagns hive book of drive way, onen grass area baside fance | Hogg Fototo C | 2017 |
|------------------|--|-------------------------------|------|
| EH33 | Pest control wasps hive back of drive way - open grass area beside fence | Hogg Estate S | 2017 |
| EH21 | Pest Control rats in back garden around the recycling boxes & down under decking | Hogg Estate S | 2017 |
| EH41 | Pest control - wasps nest in hole on front of house | Hogg Estate S | 2017 |
| EH21 | PEST CONT: small black insect behind all skirting (like maggots with legs) | Hogg Estate S | 2017 |
| EH21 | Tenant report insects t/out possibleTrogidae | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - fleas in property, animals have been treated | Hogg Estate S | 2017 |
| EH21 EH32 | PEST CONTROL - wasps nest at air vent near front door PEST CONTROL - mice in back garden near back door | Hogg Estate S | 2017 |
| EH32 | | Hogg Estate \$ Hogg Estate \$ | |
| EH41 | PEST CONTROL - mice in the back garden (brown) | | 2017 |
| EH32 | GC ants in p2 at the window see text GC wasp nest see text | Hogg Estate \$ Hogg Estate \$ | 2017 |
| EH32 | Pest Control ants all at front kitchen window at gate and back of property facing next door neig | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL _ bees nest next to fence and box in back garden | Hogg Estate \$ | 2017 |
| EH32 | Pest control - Ants and flies coming in back door | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - large ants nest at window frame and under back door step. | Hogg Estate S | 2017 |
| EH35 | PEST CONTROL - infestation of ant flies coming up from floorboards | Hogg Estate S | 2017 |
| EH21 | | | 2017 |
| EH33 | Pest control - swarm of ants at steps and pathway PEST CONTROL - ant infestation in kitchen, poss access under back door step | Hogg Estate \$ Hogg Estate \$ | 2017 |
| EH32 | Pest control - Problem with ants outside landing window | Hogg Estate S | |
| EH42 | PEST CONTROL - Something burrowing under the property. Earth has been dug out. Also a hole | Hogg Estate \$ | 2017 |
| EH32 | PEST CONTROL - mice droppings in kitchen and bagthroom (tenant blind) | Hogg Estate \$ | 2017 |
| EH33 | Void: spray for insects in bedroom | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - invasion of ants in the bedroom | Hogg Estate S | 2017 |
| EH33 | Ant infestation outside property, coming in door and window, line to go on as per Elaine | Hogg Estate \$ | 2017 |
| EH33 | PEST CONTROL - flying ants in bedroom | Hogg Estate S | 2017 |
| EH32 | Pest Control wasps around the rhone at the front & vent at livingroom - getting into livingroom | Hogg Estate S | 2017 |
| EH21 | Pest Control Rat/Mice in back garden | Hogg Estate S | 2017 |
| EH32 | GC flying ants in cafe see text | Hogg Estate \$ | 2017 |
| EH21 | Pest Control wasp nest on balcony - Hogg Est | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - ants in kitchen, I/room and bedroom | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - slugs in kitchen area, tenant partially blind (washing machine/freezer area) | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasps nests at front door getting in a hole at front of house | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL flea investiation has no pets a lot of cats on the stariwell. | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - Ant infestation in bedroom | Hogg Estate S | 2017 |
| EH39 | PEST CONTROL - wasps nest inside shed and mouse in kitchen | Hogg Estate S | 2017 |
| EH33 | fly infestation in main building | Hogg Estate S | 2017 |
| EH33 | pest control - mouse in livingroom | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasp nest under the window on the left hand side going into the vent. | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - mice in kitchen | Hogg Estate S | 2017 |
| EH39 | Pest control wasps nest still at front door | Hogg Estate S | 2017 |
| EH36 | Pest Control wasps going in near the front bedroom window just under rhone (going in hole) | Hogg Estate S | 2017 |
| EH32 | Pest control - Wasps nest above bedroom window Back gate open for access | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasps at I/room and kit window - upper storey | Hogg Estate S | 2017 |
| EH41 | Eradicate problem with wasps in garden scarecrow | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - above the front door there is birds nest needing removed. | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps nest in attic | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - invasion of blue bottles in the kitchen dead rat at the back of the cooker. | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - young wasp nests at the back garden coming from old overflow. Next to the back door | Hogg Estate S | 2017 |
| EH41 | PEST CONTORL - AVI - earwigs coming through floorboards in hall | Hogg Estate S | 2017 |
| EH33 | Pest Controll infestation of flies in kitchen | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - Ants nest at front door step poss in property | Hogg Estate S | 2017 |
| EH31 | PEST CONTROL - wasps nest inside the vent on the gable end, vent next to gas meter | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - seagull nest needing removed from roof, birds not nesting | Hogg Estate S | 2017 |
| _ · · _ · | | 1.0gg Lotato C | 2017 |

| EH32 | PEST CONTROL - wasps nest outside b/room window and coming into property through attic | Hogg Estate S | 2017 |
|------|---|----------------|------|
| EH33 | Pest control - Has many flying insects in the property | Hogg Estate S | 2017 |
| EH21 | Pest Control lots of black beetles in kitchen unit | Hogg Estate S | 2017 |
| EH33 | Pest Control - ants and flying ants in the kitchen | Hogg Estate S | 2017 |
| EH42 | PEST CONT wasps accessing property through eaves at front of property. | Hogg Estate S | 2017 |
| EH32 | Pest control - in her area she found a wasps nest in the grass | Hogg Estate S | 2017 |
| EH33 | Pest control Ants. Thinks they are coming from a pipe under the window | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - vent broken under livingrm wdw, has seen 3 mice in vent | Hogg Estate S | 2017 |
| EH21 | wasps nest in attic | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - flying ants in the livingroom | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - mice in kitchen cupboards | Hogg Estate S | 2017 |
| EH21 | Pest Controll infestation off flying flies | Hogg Estate \$ | 2017 |
| EH33 | PEST CONTROL - wasps nest at side of property and in attic | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - rats coming into back garden | Hogg Estate S | 2017 |
| EH35 | | | |
| | PEST CONTROL rat in back garden area | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - rat in back garden area | Hogg Estate S | 2017 |
| EH21 | Pest control - beetles and catapillars at night time in the property | Hogg Estate S | 2017 |
| EH32 | Pest Control bee's nesting in front door step | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps nest at vent above bathroom window, poss missing slate above guttering | Hogg Estate S | 2017 |
| EH21 | Pest Control wasps going in vent at front just below bedroom window | Hogg Estate S | 2017 |
| EH33 | Pest control Rats in garden | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - flying ants in the livingroom again | Hogg Estate S | 2017 |
| EH32 | Pest control Rats in the attic. Heard scraping and screaming | Hogg Estate S | 2017 |
| EH21 | Pest Control flea infestation | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasps going into air vent at property. Poss nest in air vent | Hogg Estate S | 2017 |
| EH34 | Pest Control wasps back now under hedge at front of house, along the side of the path | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - wasps nest in spare room | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - possible wasps nest in attic, acces under gutter at rear of property | Hogg Estate S | 2017 |
| EH39 | PEST CONTROL - wasps nest above porch at front door | Hogg Estate S | 2017 |
| EH42 | Pest control rats roaming about back garden near shed | Hogg Estate S | 2017 |
| EH33 | Pest Control - wasps nest in gap at conservatory w all- call after 2pm as at work | Hogg Estate S | 2017 |
| EH32 | [as] Red School , conf line to cover invoice 8404 problem with bees nests in rrof space | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL0-wasp nest gable end of house (next to bedroom window) | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL- bees/wasps getting in via vent having to pick them up in house (large amount) | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps nest in attic | Hogg Estate S | 2017 |
| EH32 | Ext - wasps nest in the facia | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - bees /wasps nest poss in attic area, access via air vent at rear or roof | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - small beetle type insects throughout property | Hogg Estate S | 2017 |
| EH21 | Pest control - Rats in garden | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - rats/mice in the in the walls and in the cavity | Hogg Estate S | 2017 |
| EH33 | Pest control - kitchen overrun with small bugs. Daughter has many bites | Hogg Estate S | 2017 |
| EH33 | Pest control - Rats in garden. | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasps nest in vent under the front window | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - birds nest on balcony | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - mice in kitchen pantry | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasps nest at back door beside light | Hogg Estate S | 2017 |
| EH21 | GB-Carry out a treatment for mice in the Museum. | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasps nest above bedrrom window ar rear | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - wasp nest in bushes back garden elderly tenant - as instructed by Inspectors | Hogg Estate S | 2017 |
| EH35 | PEST CONTROL - mice in kitchen cupboard | Hogg Estate S | 2017 |
| EH40 | PEST CONTROL - back garden has rats, one found dead. | Hogg Estate S | 2017 |
| EH33 | Urgent Pest Control wasp nest at back door wasps in kitchen | Hogg Estate S | 2017 |
| EH32 | GB-Carry out treatment for ants in resource centre & kitchen. | Hogg Estate S | 2017 |

| EH21 | Pest Control wasps in attic, going in and out above back bedroom window (flat type) | Hogg Estate S | 2017 |
|------|---|---------------|------|
| EH21 | Pest control wasp nest at front door | Hogg Estate S | 2017 |
| EH21 | Wasps nest going into attic at back | Hogg Estate S | 2017 |
| EH42 | Pest Control - Pigeons nesting under solar panels and alot of mess 907706584624 | Hogg Estate S | 2017 |
| EH32 | fumigate house for fleas | Hogg Estate S | 2017 |
| EH32 | fumigate for fleas | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasps in attic | Hogg Estate S | 2017 |
| EH39 | Pest Control wasps nests at back door | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - mice in attic area | Hogg Estate S | 2017 |
| EH21 | Pest Control - wasp nest at the front door | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasp in front garden next to bush. | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps nest at front window cill | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasps getting via vent at back door under kitchen floor | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - fleas in property | Hogg Estate S | 2017 |
| EH42 | Pest control think rats are in back garden at back door | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - found mice droppings in kitchen | Hogg Estate S | 2017 |
| EH33 | eradicate wasps at porch benaldus unit | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasps nest around guttering at gable end of property, unsure if in attic | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasps nest in front garden inbetween some bushes | Hogg Estate S | 2017 |
| EH32 | GB-Resource Centre-carry out treatment for ants in art room & cooking room. | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - wasps nest beside bush in the back garden | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps nest at or around vent at bathrm at rear of property | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasps nest above back door reproted via elc painter | Hogg Estate S | 2017 |
| EH33 | GB-Carry out a treatment for rats outside Ogilvie building-near water tank. | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps nest in the loft, has no phon e, will be in all Tuesday, Wednesday and Friday | Hogg Estate S | 2017 |
| EH32 | Pest Control - frogs in the house, cant find where they are coming from, found 3 so far | Hogg Estate S | 2017 |
| EH21 | Pest Control - flea infestation | Hogg Estate S | 2017 |
| EH21 | Pest control wasps nest above kitchen window - possibly in the attic | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - 3 rats in property has 3 small kids in property | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - wasps nest in attic, tenant getting stung when in bed | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - rats in back the garden and poss at back door area | Hogg Estate S | 2017 |
| EH34 | Void: wasps nest in attic | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - house infested with beetles and maggots, flies | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps in the wall cavity can hear noise and wasps active outside the window | Hogg Estate S | 2017 |
| EH39 | Pest Control - large wasps nest outside his kitche n window at venel | Hogg Estate S | 2017 |
| EH39 | GB-Carry out a treatment for wasps nest at roof apex-see staff for exact location. | Hogg Estate S | 2017 |
| EH33 | pest control rats in garden | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - rats in back garden | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL EMG wasps nest in bathroom and some in bedroom son allergic to them | Hogg Estate S | 2017 |
| EH32 | Pest Control wasps in attic - going in at bathroom extractor fan | Hogg Estate S | 2017 |
| EH41 | pest control - slugs in house hallways/kitchen livingroom and bathroom | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL- rats in kitchen and bathroom, thinks may be some in attic aswell | Hogg Estate S | 2017 |
| EH32 | pest control - bed bugs in house (primarily bedroo as dismantled bed to put outside in full house now | Hogg Estate S | 2017 |
| EH31 | PEST CONTROL - wasps nest in attic or roof above the back door, wasp getting into bathroom | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - wasps coming in the airvent upstairs | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - flea infestation in property | Hogg Estate S | 2017 |
| EH32 | GB-Carry out a treatment for wasps nest at rear of building near disabled parking area. | Hogg Estate S | 2017 |
| EH42 | as per e-mail text phone call spray house twice before men go back in | Hogg Estate S | 2017 |
| EH39 | PEST CONT wasps nest above front door at gutter level (2 storey) | Hogg Estate S | 2017 |
| EH35 | PEST CONT rat in garden and neighbours at 14 | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - wasps nest poss in stairwell may be on external part of building 29A | Hogg Estate S | 2017 |
| EH41 | Pest Control lots of wasps coming into kitchen, possible nest in gutter | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - scratching sound behind multiboard in bathrm & boxed in unit | Hogg Estate S | 2017 |

| EH21 | PEST CONTROL - infestation of mice in property | Hogg Estate S | 2017 |
|------|---|---------------|------|
| EH35 | Pest Control wasps going & out vent at side of house next to gas box | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - mice in livingroom, can hear scratching within walls | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - wasps nest under guttering at rear of property, poss in attic | Hogg Estate S | 2017 |
| EH33 | PEST CONT holes in prop fixed but slugs still getting access to kitchen | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - flies in attic space, same issue as before | Hogg Estate S | 2017 |
| EH21 | BLOCK - PEST CONTROL - wasps nest in attic poss access under guttering at front | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - mice in hall/livingroom | Hogg Estate S | 2017 |
| EH21 | Pest Control Wasps nest in attic - wasps in bedroom & landing etc. | Hogg Estate S | 2017 |
| EH32 | Pest Control wasps going in small hole behind down pipe at the back | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - slugs in various rooms | Hogg Estate S | 2017 |
| EH40 | PEST CONTROL wasp nest at the back of the garden | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - possible wasps nest in attic | Hogg Estate S | 2017 |
| EH35 | Pest control wasps nest back garden where mound of dirt/grass area is. | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - wasps nest in attic but Scott has already been out | Hogg Estate S | 2017 |
| EH41 | Pest control, wasps nest in attic space | Hogg Estate S | 2017 |
| EH34 | [as] Eradicate problem with wasps at front door | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - mole in the backgarden | Hogg Estate S | 2017 |
| EH42 | GB-Carry out a treatment for wasps nest at gable end of dining hall. | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - rates in the walls and attic | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - blue bottles in kitchen and possibley dead rats under kick boards | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - slug in bedroom possibly coming out of the cupboard | Hogg Estate S | 2017 |
| EH34 | PEST CONTROL - wasp nest at back door nesting at the vent for the toilet. | Hogg Estate S | 2017 |
| EH41 | GB-Carry out a treatment for wasps nest at rear of building. | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - flying ants in kitchen & bedrms poss also livingrm | Hogg Estate S | 2017 |
| EH21 | void remove dead crowfrom living room chimney | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps nest in attic area, coming through light in bathroom | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - wasp nest at the front between 22 and 24 | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps nest at bedroom at front of property - 2 storey | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - woodlice all over the house | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - mice in the wall cavity | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - blue bottle infestation in the kitchen | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps going in through front window poss in attic | Hogg Estate S | 2017 |
| EH21 | pest Control - rat droppings behind cooker in kitc hen | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - wasp bink in rafters of attic | Hogg Estate S | 2017 |
| EH33 | Pest Control Rat in property in kitchen/livingroom | Hogg Estate S | 2017 |
| EH41 | Pest Control wasps nest at front in the guttering at left hand side | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - rats in back garden | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - mice in property | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - beetles in whole house | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - poss rats in property | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - rats in garden | Hogg Estate S | 2017 |
| EH32 | Pest Control flea's all through the house - young children in house (problem might be coming from | Hogg Estate S | 2017 |
| EH31 | Pest Control fleas in property stray cat keeps coming in property | Hogg Estate S | 2017 |
| EH41 | Pest Control wasps nest outside bedroom window at front of block number 15c | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - wasps nest below rhone at back of property reported as per builder | Hogg Estate S | 2017 |
| EH33 | Tenant says he has a rat in ther Property | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps nest under front bedroom window | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - mouse in kitchen | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps nest in loft, also going into house and stairwell | Hogg Estate S | 2017 |
| EH42 | pest control - flies infestion (cats in property been treated) | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - mice & slugs in property | Hogg Estate S | 2017 |
| EH42 | PEST CONTROI - Rats nesting in back garden | Hogg Estate S | 2017 |

| EH33 | Pest Control - under kitchen cupboard, evidence of mice/rats. Scratching heard too | Hogg Estate S | 2017 |
|------|--|---------------|------|
| EH32 | GC wasp in porto cabin at the eaves | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - rats in garden | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - rats coming into back garden | Hogg Estate S | 2017 |
| EH35 | PEST CONTROL - mice in property | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - need the rat poison tray filled up again | Hogg Estate S | 2017 |
| EH21 | Pest Control - slugs in the kitchen, ongoing probl em | Hogg Estate S | 2017 |
| EH33 | Pest control - slugs getting into kitchen | Hogg Estate S | 2017 |
| EH21 | EMG - AVI rats in garden | Hogg Estate S | 2017 |
| EH33 | Pest Control - Rats in the garden | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps in the water tank. | Hogg Estate S | 2017 |
| EH21 | Pest control - insects in the kitchen and Bathroom lifted the carpets and thrown one out | Hogg Estate S | 2017 |
| EH42 | pest control - wasps in attic | Hogg Estate S | 2017 |
| EH41 | EMG - large wasps nest in attic - wasps in flat - gas engineers due Thur to instal GCH | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - rats in back garden | Hogg Estate S | 2017 |
| EH33 | [as] Eradicate problem with rats at Building Clean office | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - possible mice in loft | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - mice in livingroom | Hogg Estate S | 2017 |
| EH41 | [as] eradicate problem with slaters in communial area | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL shared cost - rat in the block went into a lock up inside. Tenants are leaving | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - rats beside the outshouse RHS of the house outhouse put poison there has dog | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - wasps coming in from under window cill. Tenant and kids are severly allergic | Hogg Estate S | 2017 |
| EH33 | GC mice running around within main hall | Hogg Estate S | 2017 |
| EH21 | void: fumigate house as per housing office keys at Brunton Hall | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - rats are running about in the loft. | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - rats in the cupboard. | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - rats in property | Hogg Estate S | 2017 |
| EH21 | Remove dead pigeon from rof area & wasps nest in eaves of stairwell | Hogg Estate S | 2017 |
| EH33 | Void: check report of pigeons requested by Housing Office | Hogg Estate S | 2017 |
| EH21 | pest control - rat in kitchen from under sink potential hole | Hogg Estate S | 2017 |
| EH41 | wasp nest at gable downpipe, gutter level | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - wasps in property, coming through kitchen lights, nest in attic | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - wasps in attic area, finding a number of them in property | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - Irge rat in kitchen, access in nr to kickboards | Hogg Estate S | 2017 |
| EH21 | GB-Carry out a treatment for silverfish in the main Theatre auditorium. | Hogg Estate S | 2017 |
| EH41 | Pest Control - Fleas in the house | Hogg Estate S | 2017 |
| EH21 | GB-Bad smell in ground floor meeting room-check for signs of vermin. | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - requesting removal of 2 dead pigeons from attic | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL wasps nest in the attic dnd still wasps in bedroom | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - still wasps coming out taps and from attic | Hogg Estate S | 2017 |
| EH41 | PEST CONTOL - Rat in back garden | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - clear rats from under flooring in livingroom/kitchen - attend with joiner | Hogg Estate S | 2017 |
| EH22 | Pest control - fill up poison boxes on full site | Hogg Estate S | 2017 |
| EH32 | pest control - wasps nest in attic | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - wasps nest at guttering, near to gas meter box | Hogg Estate S | 2017 |
| EH33 | PEST CONT thinks there's a rat under kitchen unit as evidence of food eaten, Hole under units. | Hogg Estate S | 2017 |
| EH33 | Pest control noise coming from floor board in hall | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - just saw a mouse in the bedroom | Hogg Estate S | 2017 |
| EH21 | GB-Carry out a treatment for rats at the garage area. | Hogg Estate S | 2017 |
| EH21 | Pest control fleas in livingroom | Hogg Estate S | 2017 |
| EH33 | Pest control slugs coming in back and front door | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - mice in I/room, coming from side of fire place | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - rats at back garden and under back garden steps | Hogg Estate S | 2017 |

| EH33 | Pest Control rats noise coming from attic again | Hogg Estate S | 2017 |
|------|---|---------------|------|
| EH33 | PEST CONTROL - rats & mice in house | Hogg Estate S | 2017 |
| EH39 | PEST CONTROL rats at back door step under disbled ramp | Hogg Estate S | 2017 |
| EH32 | fumigate whole house fleas | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - rats or possibly mice in attic | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - mice in property, poss under staircase | Hogg Estate S | 2017 |
| EH21 | Pest control infestation of flies in house | Hogg Estate S | 2017 |
| EH21 | GB-Carry out a treatment for mice in the cafe store & staff room. | Hogg Estate S | 2017 |
| EH32 | GC rats in the building | Hogg Estate S | 2017 |
| EH35 | PEST CONTROL - Mice in property again | Hogg Estate S | 2017 |
| EH21 | Mice/rats in the kitchen | Hogg Estate S | 2017 |
| EH42 | PEST CONT rat under kitchen unit | Hogg Estate S | 2017 |
| EH41 | GB-Black flies reported in room G16-rent income. Carry out a treatment as required. | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - Rats in garden area of 89 + 90 | Hogg Estate S | 2017 |
| EH41 | Pest Control rats in front garden | Hogg Estate S | 2017 |
| EH32 | pest control - hall cupboard | Hogg Estate S | 2017 |
| EH39 | gc mice in clasrsroom see text | Hogg Estate S | 2017 |
| EH40 | rats in the back garden, nesting in the summer house | Hogg Estate S | 2017 |
| EH41 | Pest cotrol rat in kitchen cupboard | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - mice in the kitchen. | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - possible rats in shed at the front of the house | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - pigeons in the attic | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - rats in property | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - mice in property, kitchen or bedroom | Hogg Estate S | 2017 |
| EH39 | scott rats about garden fone call housing | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - mice under kitchen base unit has newborn baby in property | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL mice in the livingroom. USE BACK DOOR FOR ACCESS KNOCK & ENTER. Tenant disabled. | Hogg Estate S | 2017 |
| EH33 | PEST CONT still hearing rat under floor in hall | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - mice in house in livingroom under floorboards & in attic | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - rats in attic, previously attended but thinks they may still be there | Hogg Estate S | 2017 |
| EH33 | PEST CONTORL - sighted 2 rats in back garden also dead rat in No.14 (council) | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - mice in I/room again. A couple were caught in trap but can here more in back | Hogg Estate S | 2017 |
| EH33 | Tenant has rats in his Property | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - Beetles all over property and on skirtings in bedroom | Hogg Estate S | 2017 |
| EH41 | Pest Control - mouse in the kitchen, please ring in the morningso suuport worker is there | Hogg Estate S | 2017 |
| EH32 | Pest control moles in back garden | Hogg Estate S | 2017 |
| EH21 | Pest contol mice in livingroom | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - mice in property, can hear scatching in bedrm & livingrm walls | Hogg Estate S | 2017 |
| EH31 | Pest Control - rats in the property | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - mice under the stair | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - tenant says there's fleas in the property | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - sml black beetle type insects all throughout the property, Elderly tenant. | Hogg Estate S | 2017 |
| EH21 | EMG Rat behind boiler | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - mice in property | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - mice in property, think seen a rat aswell | Hogg Estate S | 2017 |
| EH21 | pest control - rat back in proeprty hole blocked | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - mice in loft | Hogg Estate S | 2017 |
| EH32 | VOID/ Pest control Wasps nest above fan | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - ongoing issue with mice, found more droppings in kitchen area | Hogg Estate S | 2017 |
| EH39 | PEST CONTROL - mice in kitchen | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - mice in house | Hogg Estate S | 2017 |
| EH21 | Pest control fleas in livingroom etc again | Hogg Estate S | 2017 |
| EH33 | Pest control rats in back garden besdie the rubbish | Hogg Estate S | 2017 |

| EH32 | EMG- rats in garden neighbours gardens full of rubbish and | Hogg Estate S | 2017 |
|------|---|---------------|------|
| EH33 | PEST CONTROL - rats in attic, child with weak immuse system in property | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - rats under stairs again | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - beetles everywhere in the house | Hogg Estate S | 2017 |
| EH21 | PEST CONTROLt - mice in house livingroom (sleeps in livingroom - disabled oap) | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - mice in attic | Hogg Estate S | 2017 |
| EH21 | intercom system not working still. Tenant called company and they said job had been done and | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - rats in kitchen and attic | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - mice in attic again, sounds like more have come in | Hogg Estate S | 2017 |
| EH42 | GB-Carry out pigeon control around building. | Hogg Estate S | 2017 |
| EH21 | GB-Carry out a treatment for foxes in rear garden- see staff for details. | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - pigeons underneath solar panels and nests | Hogg Estate S | 2017 |
| EH40 | PEST CONT infestation of mice in ktchen | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - fleas in the property | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL thinks may have a rat in the house bedroom/hall | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - tenant has reported fleas throughout property from previous tenant | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - rats in back garden, under the decking. Access needed from number 8 | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - Mice in kitchen | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL rats between number 9 and 10 at back fence | Hogg Estate S | 2017 |
| EH32 | GC dead rat in communial area see text | Hogg Estate S | 2017 |
| EH33 | Rats in and around the garden effecting private tenant also | Hogg Estate S | 2017 |
| EH33 | pest control send report back to sy | Hogg Estate S | 2017 |
| EH33 | PEST CONTORL rat in kitchen | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - rats in kitchen and smell in lower bathroom (pest control put down when at no 18) | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - rats in kitchen | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - scratching at night time & morning possibly rats/bats. | Hogg Estate S | 2017 |
| EH33 | Pest Control rats in back garden | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - slugs coming in to property | Hogg Estate S | 2017 |
| EH41 | Pest control mice in property | Hogg Estate S | 2017 |
| EH34 | PEST CONT mice/rats in attic/walls. Tenant can hear them scratching. | Hogg Estate S | 2017 |
| EH32 | spray house | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - mice/rats in property noticed them in kitchen. Tenant vunerable | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - rat in the attic | Hogg Estate S | 2017 |
| EH42 | Pest control rodents droppings in liv /kitchen | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - family of rats under hut in back garden | Hogg Estate S | 2017 |
| EH33 | Pest Control - rats in the garden | Hogg Estate S | 2017 |
| EH42 | rats | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - tenant still has fleas in the house | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - AVI rats in loft please arrange for 23 January 2018 | Hogg Estate S | 2017 |
| EH33 | [as] works order to cover invoice inv-8610 rat treatment at skips [groundcare] | Hogg Estate S | 2017 |
| EH41 | pest control - rats in attic again | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - rats in garden & mice in house. | Hogg Estate S | 2017 |
| EH21 | pest control - mouse in livingroom | Hogg Estate S | 2017 |
| EH34 | PEST CONTROL - slugs in kitchen (large amounts) | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL flies in house after rats in kitchen | Hogg Estate S | 2017 |
| EH33 | small beasties in property | Hogg Estate S | 2017 |
| EH39 | PEST CONTROL rats under floorboards getting in at back step | Hogg Estate S | 2017 |
| EH35 | Pest Control - possible mice/rats in the attic scratching noises | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - mice in the attic | Hogg Estate S | 2017 |
| EH31 | PEST CONTROL - rat in back garden area | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL rats in back garden | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - rats in back garden | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - rats in property posisbly one dead floor | Hogg Estate S | 2017 |

| ГЦ44 | AVI Deet control rate enotted in garden | Haga Fatata C | 2017 |
|------|--|-----------------------------|------|
| EH41 | AVI Pest control rats spotted in garden PEST CONTROL - rats in back garden, has put one or two traps down | Hogg Estate S Hogg Estate S | 2017 |
| EH22 | Pest control - All over site pest control and pitc h I has a mice infestation | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL rats in the attic need cleaned pest control hasnt been back | Hogg Estate S | 2017 |
| EH21 | PEST CONTORL - poss rats/mice in attic, possibly in air vent in bathroom (noisy) | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - mice in hall cupboard | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - mice in loft | Hogg Estate S | 2017 |
| EH40 | PEST CONTROL - poss mice/rats in back garden alot of holes at back area in garden | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - mice in the wall (internal) | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - rats in back garden & num 64 also | Hogg Estate S | 2017 |
| EH33 | rats/mice ate through waste pipe in bathroom | Hogg Estate S | 2017 |
| EH39 | PEST CONTROL - scratching sound, poss mice or rat in attic area | Hogg Estate S | 2017 |
| EH21 | PEST CONT ants appear to be in kitchen and hall cupboard. | Hogg Estate S | 2017 |
| EH21 | slugs in property survey report back findings to s | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - mice in property (kitchen), one has been caught already | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - scratching and stuff moving about in loft | Hogg Estate S | 2017 |
| EH21 | Pest control mice /rats in kitchen | Hogg Estate S | 2017 |
| EH21 | PEST CONT mice at property in kitchen & possibly attic. | Hogg Estate S | 2017 |
| EH42 | Pest control - flee infestation Hogg Es | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - mice in the attic large amount has put some traps down but not taking to them | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - rat in the back garden. | Hogg Estate S | 2017 |
| EH35 | PEST CONTROL - rats in bottom of hut in back garden | Hogg Estate S | 2017 |
| EH21 | Pest Control - blue bottles are coming from under the sink, possible dead rat? | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - mice in property, in hall scratching in attack | Hogg Estate S | 2017 |
| EH21 | Pest Control Thinks mice in bedroom | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - rat in front garden | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - rats/mice in cavity wall | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - beatles in the house | Hogg Estate S | 2017 |
| EH32 | Pest control rat at hut in back garden | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL- Rat in back garden | Hogg Estate S | 2017 |
| EH33 | Pest Control - suspects mice in the property, scra tching noises | Hogg Estate S | 2017 |
| EH33 | Pest control seen rat in livingroom/kitchen | Hogg Estate S | 2017 |
| EH39 | GC rats in the roof | Hogg Estate S | 2017 |
| EH33 | pest control - rats in garden possibly coming from neighbour as they have a | Hogg Estate S | 2017 |
| EH33 | Pest control rats in back garden 14.16.18. | Hogg Estate S | 2017 |
| EH41 | PEST CONT possible infestation with fleas throughout house. | Hogg Estate S | 2017 |
| EH32 | pest control - mice/rats scurry in ceiling | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - rats still in back garden | Hogg Estate S | 2017 |
| EH33 | Pest Control - mice in cupboards | Hogg Estate S | 2017 |
| EH32 | Pest control mice in livingroom is an OAP | Hogg Estate S | 2017 |
| EH34 | PEST CONTROL - mice in attic | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - rats in back garden seen beside huts has carcuss of dead rat | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - scracthing noises in the attic poss mice/rats | Hogg Estate S | 2017 |
| EH32 | GC mice in areas of the building | Hogg Estate S | 2017 |
| EH42 | Pest control mice in front bedroom | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - rats in back garden | Hogg Estate S | 2018 |
| EH42 | PEST CONTROL - large number of slugs in the kitchen | Hogg Estate S | 2018 |
| EH33 | Pest Control -possible rats in the garden- holes appearing | Hogg Estate S | 2018 |
| EH21 | PEST CONTROL - poss rats/mice in property | Hogg Estate S | 2018 |
| EH32 | pest control - rat at the bin stores | Hogg Estate S | 2018 |
| EH21 | PEST CONTROL - rats in back garden area, has put poison down but still has issue. | Hogg Estate S | 2018 |
| EH21 | PEST CONTOL - wasps nest in attic area, reported to tenant by BGas upgrade team in Feb | Hogg Estate S | 2018 |
| EH39 | Pest control silver fish in the bathroom | Hogg Estate S | 2018 |

| EH32 | PEST CONTROL - bug bites, cannot locate. No Animals Baby 4 wks old now bitten | Hogg Estate S | 2018 |
|------|--|---------------|------|
| EH33 | PEST CONTROL - bird trapped in attic space | Hogg Estate S | 2018 |
| EH33 | PEST CONTROL - poss birds building nest in cavity at gable end of property nr ridge tiles | Hogg Estate S | 2018 |
| EH21 | Pest Control Ants in kitchen | Hogg Estate S | 2018 |
| EH40 | Report of scratching noise in attic phoned to S Hood | Hogg Estate S | 2018 |
| EH42 | Block check as per D Murray | Hogg Estate S | 2018 |
| EH33 | PEST CONTROL - birds are coming via the roof and falling down into the cavity. Yearly problems. | Hogg Estate S | 2018 |
| EH35 | Pest Control - rat in the back garden | Hogg Estate S | 2018 |
| EH32 | PEST CONTROL - rat in garden | Hogg Estate S | 2018 |
| EH21 | Pest Control - Ants in the kitchen | Hogg Estate S | 2017 |
| EH41 | PEST CONTROL - mice or rats in kitchen cupboards | Hogg Estate S | 2018 |
| EH39 | GC rayts dead in ceiling void remove | Hogg Estate S | 2018 |
| EH35 | PEST CONTROL mice in livingroom | Hogg Estate S | 2018 |
| EH33 | PEST CONTROL - mice still in property | Hogg Estate S | 2017 |
| EH39 | GB-Carry out a treatment for ants in the medical cupboard. | Hogg Estate S | 2018 |
| EH41 | PEST CONTROL - invasion of ants in property. | Hogg Estate S | 2018 |
| EH21 | spray whole house keys reception | Hogg Estate S | 2018 |
| EH33 | PEST CONTROL - mice in property | Hogg Estate S | 2018 |
| EH21 | Pest control ants in livingroom and kitchen | Hogg Estate S | 2018 |
| EH32 | gc LOTS OF DEAD FLIES IN CLOCKTOWER ANNUAL OCURANCE ? | Hogg Estate S | 2017 |
| EH36 | PEST CONTROL - large rat in garden outside kitchen window. | Hogg Estate S | 2018 |
| EH33 | PEST CONTROL - rats front/garden & num 64 AGAIN | Hogg Estate S | 2018 |
| EH41 | PEST CONTROL - mice in the walls | Hogg Estate S | 2017 |
| EH32 | PEST CONT rat seen in kitchen last night. | Hogg Estate S | 2017 |
| EH33 | PEST CONTROL - mice all over the house | Hogg Estate S | 2017 |
| EH21 | rats in garden- several spoke with pest contol- in area tomorrow | Hogg Estate S | 2017 |
| EH40 | PEST CONTROL - mice in attic | Hogg Estate S | 2017 |
| EH21 | Pest Control mice infestation (seen in Iroom, kitchen & broom) baby in house | Hogg Estate S | 2017 |
| EH21 | PEST CONTROL - fleas in property | Hogg Estate S | 2017 |
| EH33 | Pest Control - rat in the garden | Hogg Estate S | 2017 |
| EH32 | Pest Control - rat in the hut and hole in the gard en | Hogg Estate S | 2017 |
| EH33 | Pest control ants and slaters throughout property | Hogg Estate S | 2017 |
| EH32 | GC ants in kitchen & Resource Centre | Hogg Estate S | 2017 |
| EH42 | PEST CONTROL - infestation of slaters and slipshears | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - mice in kitchen | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - rat in back garden again | Hogg Estate S | 2017 |
| EH32 | Crows nesting in chimney as cowl blew off in wind. Please remove nest and install new cowl. | Hogg Estate S | 2017 |
| EH32 | PEST CONTROL - possible wasps nest in attic - active | Hogg Estate S | 2018 |
| EH21 | PEST CONTROL - rat in back garden Report back R Drummond | Hogg Estate S | 2018 |
| EH32 | Pest Control - ants in the kitchen | Hogg Estate S | 2018 |
| EH33 | lay ant powder when kitchen removed 25/04/18 | Hogg Estate S | 2018 |
| EH21 | PEST CONTROL - rats have returned in huts has ate all the food that was put down last time | Hogg Estate S | 2018 |
| EH35 | PEST CONTROL - mice in house | Hogg Estate S | 2018 |
| EH21 | PEST CONTROL - Ant infestation mainly kitchen area also livingrm | Hogg Estate S | 2018 |
| EH41 | BLOCK p/contl can hear rats under floorboards from C/E may also be the attic | Hogg Estate S | 2018 |
| EH33 | PEST CONTROL - mice in attic area again | Hogg Estate S | 2018 |
| EH21 | Pest Control ant infestation in kitchen | Hogg Estate S | 2018 |
| EH21 | PEST CONTROL - mice in the kitchen | Hogg Estate S | 2018 |
| EH21 | GB-Carry out treatment for ants in kitchen & room 6. | Hogg Estate S | 2018 |
| EH32 | PEST CONTROL - rats in back garden | Hogg Estate S | 2018 |
| EH21 | PEST CONTROL - possible birds in the attic | Hogg Estate S | 2018 |
| EH33 | Pest Control rat in garden - has dog & children please speak tenant before putting anything down | Hogg Estate S | 2018 |
| EH33 | GB-Carry out a treatment for mice in Contact Centre kitchen. | Hogg Estate S | 2018 |

| EH33 | PEST CONTROL - birds in attic and in bathroom behind bath panel | Hogg Estate S | 2018 |
|------|--|----------------|------|
| EH33 | Pest control rats in back garden at the decking | Hogg Estate \$ | 2018 |
| EH33 | Pest Control mice in attic & wall cavity | Hogg Estate S | 2018 |
| EH42 | PEST CONT prob with large quantity of ants in livingroom. | Hogg Estate S | 2018 |
| EH21 | PEST CONTROL - birds in the eves of the building hole underneath in the rhones. | Hogg Estate S | 2018 |
| EH21 | Mice droppings in bedrooms & kitchen, has put down own traps too | Hogg Estate S | 2018 |
| EH21 | GC Ants in dining room | Hogg Estate S | 2018 |
| EH21 | GC moths in gents venue 1 see text | Hogg Estate S | 2018 |
| EH41 | Pest Control rats in garden - please speak to tenant before putting anything down as has pets | Hogg Estate S | 2018 |
| EH41 | gc ANTS IN BUILDING SEE TEXT | Hogg Estate S | 2018 |
| EH32 | Pest Control - birds in the eves | Hogg Estate S | 2018 |
| EH33 | PEST CONTROL - ants in property | Hogg Estate S | 2018 |
| EH32 | PEST CONTROL - ants in property | Hogg Estate S | 2018 |
| EH32 | Pest Control rats in attic | Hogg Estate S | 2018 |
| EH33 | PEST CONTROL - mice in attic area again | Hogg Estate S | 2018 |
| EH32 | PEST CONTROL - rats and flies in the kitchen | Hogg Estate S | 2018 |
| EH42 | Pest control - still having issues with pigeons un der solar panels, not heard bck from pest control | Hogg Estate S | 2018 |
| EH21 | PEST CONTROL - Rats in the property | Hogg Estate S | 2018 |
| EH21 | Pest Control - Small black beetles in the kitchen | Hogg Estate S | 2018 |
| EH32 | PEST CONT lots of ants in kitchen | Hogg Estate S | 2018 |
| EH21 | GB-Carry out a treatment for ants in Bistro restaurant area. | Hogg Estate S | 2018 |
| EH42 | PEST CONTROL - rats droppings in kitchen livingroom | Hogg Estate S | 2018 |
| EH42 | PEST CONTROL report of rats in the kitchen area | Hogg Estate S | 2018 |
| EH33 | Pest control Rat in back garden beside bins | Hogg Estate S | 2018 |
| EH32 | PEST CONTROL - rat in kitchen | Hogg Estate S | 2018 |
| EH21 | PEST CONTROL - mice in back garden and shed | Hogg Estate S | 2018 |
| EH32 | PEST CONTROL - Ant infestation in bathroom & livingroom | Hogg Estate S | 2018 |
| EH32 | Pest control ants in kitchen | Hogg Estate S | 2018 |
| EH40 | Pest control wasps there is a nest in gutteting at front coming/bedroom window | Hogg Estate S | 2018 |
| EH42 | PEST CONTROL - pigeons in attic | Hogg Estate S | 2018 |
| EH21 | GB-Carry out a treatment for ants in Manager's office, duty office & Secretary's office. | Hogg Estate S | 2018 |
| EH21 | GB-investigate & carry out a treatment for moths in Venue1 toilets & Theatre area. | Hogg Estate S | 2018 |
| EH33 | PEST CONTROL - Ant infestation in kitchen | Hogg Estate S | 2018 |
| EH31 | PEST CONTROL - tenant thinks she has a bee hive in the structure of the house - possibly a vent in | Hogg Estate S | 2018 |
| EH41 | EMG - bees in the house | Hogg Estate S | 2018 |
| EH42 | EMG pest control flea infestation - everywhere in house - previous tenant caused problem, Scott | Hogg Estate S | 2018 |
| EH32 | PEST CONTROL - ants in livingroom | Hogg Estate S | 2018 |
| EH42 | PEST CONTROL - ants all over property | Hogg Estate S | 2018 |
| EH33 | PEST CONTROL - rats in back garden | Hogg Estate S | 2018 |
| EH21 | Pest Control ants in ktichen | Hogg Estate S | 2018 |
| EH33 | Pest Control - ants in the property | Hogg Estate S | 2018 |
| EH33 | PEST CONTROL - Ant infestation in kitchen area | Hogg Estate S | 2018 |
| EH21 | Clear wasps nest in front garden next to fence | Hogg Estate S | 2018 |
| EH39 | PEST CONTROL - slugs in kitchen, poss access from pipe at back door | Hogg Estate S | 2018 |
| EH41 | Pest control rat droppings on patio at back thinks rats may be near garage | Hogg Estate S | 2018 |
| EH32 | Pest control ants in kitchen and livingroom | Hogg Estate S | 2018 |
| EH33 | Pest control - slugs coming into kitchen near sink 9 where outside drain) | Hogg Estate S | 2018 |
| EH21 | PEST CONTROL - rats in back /front garden near hut | Hogg Estate S | 2018 |
| EH32 | Pest Control - Ants in the house, kitchen | Hogg Estate S | 2018 |
| EH32 | Pest control - beehive next to gas box | Hogg Estate S | 2018 |
| EH35 | Pest Control mice in kitchen & upstairs cupboard | Hogg Estate S | 2018 |
| EH33 | GB-Carry out a treatment for rats.One already caught in kitchen. | Hogg Estate S | 2018 |
| EH34 | pest control - rats in rear garden | Hogg Estate S | 2018 |

| EH33 | PEST CONTROL - wasps nest in the fence at the back garden next to the gate | Hogg Estate S | 2018 |
|------|--|---------------|------|
| EH35 | PEST CONTRL - ants in kitchen1 KNOCK & ENTER | Hogg Estate S | 2018 |
| EH33 | PEST CONTROL - dead bees & wasps in attic unsure if any live ones | Hogg Estate S | 2018 |
| EH32 | PEST CONTROL - wasps nest in shed | Hogg Estate S | 2018 |
| EH21 | PEST CONTROL - black beasts coming in at waste pipe in bathroom | Hogg Estate S | 2018 |
| EH33 | PEST CONTORL - Ant infestation mainly in kitchen area | Hogg Estate S | 2018 |
| EH21 | PEST CONTROL - bird still in attack | Hogg Estate S | 2018 |
| EH34 | GC vermin in kitchen shut down food/hyg see text | Hogg Estate S | 2018 |
| EH35 | Pest Control - Ants in the kitchen | Hogg Estate S | 2018 |
| EH21 | Pest Control very large rat at back of freezer | Hogg Estate S | 2018 |
| EH32 | PEST CONTROL - ant infestation in bedroom area | Hogg Estate S | 2018 |
| EH34 | Pest Control slugs in livingroom | Hogg Estate S | 2018 |
| EH21 | PEST CONTROL - rats in back garden, poss from garden further along | Hogg Estate S | 2018 |
| EH21 | PEST CONTROL - ant infestation in the house | Hogg Estate S | 2018 |
| EH39 | GC Mice dropping found in kitchen units see tex | Hogg Estate S | 2018 |
| EH33 | GB-Carry out a treatment for mice in Sarah Mackie's office. | Hogg Estate S | 2018 |
| EH21 | PEST CONT rat seen in garden | Hogg Estate S | 2018 |
| EH21 | Pest Control silverfish all over the house | Hogg Estate S | 2018 |
| EH31 | PEST CONTROL - rats in garden - droppings in house aswell | Hogg Estate S | 2018 |
| EH33 | Pest Control wasps nest in attic | Hogg Estate S | 2018 |
| EH21 | Block Pest Control at front at downpipe above balcony of 31c wasps nest | Hogg Estate S | 2018 |
| EH33 | PEST CONTROL - ant infestation in kitchen area | Hogg Estate S | 2018 |
| EH32 | Pest Control hole at back door wasps getting into house under floor | Hogg Estate S | 2018 |
| EH32 | Pest Control wasps going in extractor fan vent in bathroom | Hogg Estate S | 2018 |
| EH21 | PEST CONTROL - wasps coming in all windows front and back | Hogg Estate S | 2018 |
| EH32 | PEST CONTROL ants in property | Hogg Estate S | 2018 |
| EH32 | PEST CONTROL - mice/bees/wasps in house and outhouse | Hogg Estate S | 2018 |
| EH39 | PEST CONTROL - wasps nest above front door | Hogg Estate S | 2018 |
| EH32 | GC infestion of ants in dining room kitchen back area | Hogg Estate S | 2018 |
| EH42 | PEST CONT lost of wasp enter eaves. Can hear buzzing in attic. | Hogg Estate S | 2018 |
| EH42 | PEST CONTROL - flees infestion in house | Hogg Estate S | 2018 |
| EH33 | PEST CONTROL - mice in property, poss cement missing at back door step/cavity wall | Hogg Estate S | 2018 |
| EH21 | PEST CONTROL - bees in attic tenant removed hive but still a lot of bees | Hogg Estate S | 2018 |
| EH32 | Pest Control ants in hall way | Hogg Estate S | 2018 |
| EH21 | PEST CONTROL - wasps poss in attic or eves of property | Hogg Estate S | 2018 |
| EH41 | pest contrl - ants inside front door | Hogg Estate S | 2018 |
| EH32 | pest control - rat in garden unsure of where its coming from | Hogg Estate S | 2018 |
| EH42 | Pest Control - crawling brown insects (grain of ri ce) in bathroom and bedroom | Hogg Estate S | 2018 |
| EH32 | pest control - rats in garden | Hogg Estate S | 2018 |
| EH32 | PEST CONTROL - Ant infestation in kitchen, poss through broken air vent | Hogg Estate S | 2018 |
| EH32 | PEST CONT (AVI) wasps in attic, possible entering eaves above bedroom window. | Hogg Estate S | 2018 |
| EH39 | gc ANTS IN THE BULDING SEE TEXT | Hogg Estate S | 2018 |
| EH39 | GC ant's in kitchen | Hogg Estate S | 2018 |
| EH21 | Pest Control - Ants in the kitchen | Hogg Estate S | 2018 |
| EH33 | PEST CONTROL - mice still in property | Hogg Estate S | 2018 |
| EH32 | Pest control rats beside the deckin in back garden | Hogg Estate S | 2018 |
| EH35 | Pest Control - rat in the garden | Hogg Estate S | 2018 |
| EH42 | Pest Control Seagulls on roof building nest | Hogg Estate S | 2018 |
| EH21 | PEST CONTROL - rats sighted in back garden area, running between gardens, poss 169 too | Hogg Estate S | 2018 |
| EH32 | Pest control small bugs in the house upstairs | Hogg Estate S | 2018 |
| EH42 | BLOCK - buzzer exit button sticking, tenant above at no.8 can hear constant buzzing | Hogg Estate S | 2018 |
| EH39 | PEST CONTROL - Ant infestation at front door area (inside property) | Hogg Estate S | 2018 |
| EH33 | Pest control slugs in kitchen | Hogg Estate S | 2018 |

| Personal P | | | l J | |
|---|------|---|---------------|------|
| PEST CONTROL - stugs in the knotwern | EH42 | PEST CONTROL - rats in property | Hogg Estate S | 2018 |
| Post Control arts at low flaces 201 | | | | |
| Post control rate all over house Post control rate all over house Post control rate all provinces Post control date of this guarant per house Post control rate as a return of the per house Post control rate Post | | | | |
| Filt Pet central dead half in gathering of back Post | | | | |
| PART PRI CONTRO can be a missing connert use feb to make secure Principle Principl | | | | |
| Peat control various at from | | | | |
| PAGE Contain the building | | | | |
| PEST CONTROL - bees in sitil sires, S. Phood address waspa need removed, but silf have bees 100 100 persons 2 201 101 | | | | |
| Field Pest Control - arts in the bitchen store cuphound Field Pest Control (Any) in in the garden, seen by religitour Field Pest Control (Any) in in the garden, seen by religitour Field Pest Control - Any) in in the garden, seen by religitour Field Pest Control - Any in the garden, seen by religitour Field Fi | | | | |
| Pest Pest Control (AV) not in the garden, seen by net girboor Pest Pest CoNTROL - coasps in but Pest CoNTROL - coasps in but Pest CoNTROL Pest Seales Pest Pest CoNTROL - coasps in but Pest Seales Pest Pest CoNTROL - coasps in tope Seales Pest Pest CoNTROL - coasps in tope Seales Pest Pest Seales Pest Se | | | | |
| PEST CONTROL - vasps at traps between window at the form of the property | | | | |
| PEST CONTROL - vesps at tope bedroom window at the front of the propenty Hogg Estate 201 | | | | |
| Petal Control - raice in the garden Hogg Estate 201 | | | | |
| Hogg Estate Part CONTROL rate in tack garden Hogg Estate Part CONTROL rate in the property coming from n eightbours Hogg Estate Part CONTROL rate in the house Hogg Estate Part CONTROL rate in House Hogg Estate Part CONTROL rate Hogg Estate Part CONTROL rate in House Hogg Estate Part CONTROL rate | | | | |
| FEST CONTROL ratis in back garden | | | | 2018 |
| EHHI PEST CONTROL - arts in property Hogg Estates 201 EH42 PEST CONTROL so of anish in flat, mostly in living room. Hogg Estates 201 EH33 Pest Control - arts in the property, coming from n eighbours Hogg Estates 201 EH32 Pest Control - arts in the house Hogg Estates 201 EH32 pest control - arts in the house 190 190 EH32 pest control - arts in the house 201 190 EH33 pest control - arts in the prosent living mask kilchen Hogg Estates 201 EH33 PEST CONTROL - and independent living mask kilchen Hogg Estates 201 EH33 PEST CONTROL - and lose comming unit of window Hogg Estates 201 EH33 Dest Control - Art wind bases - lying all over the foor Hogg Estates 201 EH33 pest Control - Art wind base in kilchen (plause actives get ternant up at 12) Hogg Estates 201 EH33 pest Control wasps and wasp mests at the property Hogg Estates 201 EH33 pest control wasps in livingroom and wasp mests at the property Hogg Estates 201 < | | | | 2018 |
| EH42 PEST CONT lots of arts in flat, mostly in living room. Hogg Estates 201 EH33 Pest Control - rats in the property, coming from n eighbours Hogg Estates 201 EH32 Pest Control - rats in the house Hogg Estates 201 EH32 Pest Control - ratis in the house Hogg Estates 201 EH32 pest Control - ratis in the house (above front Vroom possible wasps nest Hogg Estates 201 EH32 pest CONTROL - And infestation, livingm & kilchen Hogg Estate 201 EH32 PEST CONTROL - would lice coming out of window Hogg Estate 201 EH33 CC main hell wasps - lying all over the floor Hogg Estate 201 EH33 QC main hell wasps - lying all over the floor Hogg Estate 201 EH33 PEST CONT and back in kichen [please attend PM as carers get tenant up at 12) Hogg Estate 201 EH33 PEST CONT and back in kichen [please attend PM as carers get tenant up at 12) Hogg Estate 201 EH33 PEST CONT and back in kichen [blillow, poss deed rodent under floortocards?, not sewage Hogg Estate 201 EH33 Pest Contro | | | | 2018 |
| EH33 Pest Control - rats is the property, coming from neighbours Hogg Estate \$ 20 EH32 PESC Control - and is in the house Hogg Estate \$ 20 EH21 PESC CONT possibly rats in attic. 201 EH32 pest con - waspe in the house (above front froom possible wasps rest Hogg Estate \$ 20 EH33 PEST CONTROL - And interestation, livingm & kirchen Hogg Estate \$ 20 EH21 GB-Carry out a treatment for arts in the bowing club temporary unit. Hogg Estate \$ 20 EH21 GB-Carry out a treatment for arts in the bowing club temporary unit. Hogg Estate \$ 20 EH36 pest control - infeation of arts and climbing over cap Hogg Estate \$ 20 EH36 pest control - infeation of arts and climbing over cap Hogg Estate \$ 20 EH33 pest control wasps in kingroom Hogg Estate \$ 20 EH33 PEST CONTROL - unusual smell in hallway, poss dear rodent under floorthoards?, not sewage Hogg Estate \$ 20 EH32 PEST CONTROL - arts in kitchen poss still in kitchen cupboard, bely in prop Hogg Estate \$ 20 EH32 PEST CONTROL - arts in kitchen poss still in kitchen cupboard, bely in prop Hogg Estate \$ 20 EH32 PEST CONTROL - arts in kitchen or and porth an | | | | 2018 |
| EH32 Peat Control - ants in the house Hogg Estate \$ 201 EH21 PEST CONT possibility rats in atte. Hogg Estate \$ 201 EH32 pest con- wasps in the house (above front Proom possible wasps nest Hogg Estate \$ 201 EH32 pest CONTROL - Ant infestation, livingmi & kitchein Hogg Estate \$ 201 EH21 PEST CONTROL - And timestation, livingmi & kitchein Hogg Estate \$ 201 EH21 GB-Carry out a treatment for ants in the bowling club temporary unit. Hogg Estate \$ 201 EH23 GC main hall wasps - king all over the floor Hogg Estate \$ 201 EH33 pest control - infestion of ants and climbing over cap Hogg Estate \$ 201 EH33 PEST CONTROL - and sand climbing over cap Hogg Estate \$ 201 EH33 PEST CONTROL - unusual small in hallway, poss dead radent under floorboards?, not sewage Hogg Estate \$ 201 EH33 PEST CONTROL - unusual small in hallway, poss dead radent under floorboards?, not sewage Hogg Estate \$ 201 EH33 PEST CONTROL - unusual small in kinchen cupboard, baby in prop Hogg Estate \$ 201 EH34 PEST CONTROL - ant in kichen possibili in kinchen cupboard, baby in prop Hogg Estate \$ 201 EH21 pest control ants at bask | | | | 2018 |
| EH21 PEST CONT possibility rats in attile. Hogg Estate \$ 201 EH32 pest con- wasps in the house (a dobre front irroom possible wasps nest) Hogg Estate \$ 201 EH33 PEST CONTROL - Art infestation, kingmr & kitchern Hogg Estate \$ 201 EH21 PEST CONTROL - Art infestation, kingmr & kitchern Hogg Estate \$ 201 EH21 GB-Carry out a treatment for ants in the bowling club temporary unit. Hogg Estate \$ 201 EH39 GC main hall wasps - lying all over the floor Hogg Estate \$ 201 EH39 pest control - Infestion of arts and climbing over coap Hogg Estate \$ 201 EH30 pest Control - Infestion of arts and climbing over coap Hogg Estate \$ 201 EH33 PEST CONTROL - unusual smell in hallow, poss dead corderi under floorboards?, not sewage Hogg Estate \$ 201 EH33 Pest control wasps in livingroom Hogg Estate \$ 201 EH34 Pest Control - Less and wasp nests at the property Hogg Estate \$ 201 EH32 PEST CONTROL - rat in kitchen, poss sill in kitchen cupboard, baby in prop Hogg Estate \$ 201 EH32 PEST CONTROL - rat in kitchen, poss sill in kitchen under floorboards? wasps nests at top of sill in kitchen under floorboards? wasps nests at top of sill in kitchen under floorboards? wasps resp res | | | | 2018 |
| EH32 pest con - wasps in the house (above front Vircom possible wasps nest Hogg Estate \$ 201 EH33 PEST CONTROL - Ant infristration, livingm & kitchen Hogg Estate \$ 201 EH21 PEST CONTROL - woll loc comining out of window Hogg Estate \$ 201 EH21 GB-Carry out a treatment for ants in the bowling dub temporary unit. Hogg Estate \$ 201 EH39 GC main hall wasps - lying all over the floor Hogg Estate \$ 201 EH35 pest control -infestion of ants and climbing over cop Hogg Estate \$ 201 EH36 PEST CONTROL - unusual smell in hallway, poss dead rodent under floorboards?, not sewage Hogg Estate \$ 201 EH33 PEST CONTROL - unusual smell in hallway, poss dead rodent under floorboards?, not sewage Hogg Estate \$ 201 EH34 Pest control - bease and wasp nests at the property Hogg Estate \$ 201 EH32 PEST CONTROL - rall in kitchen, poss still in kitchen cupboard, baby in prop Hogg Estate \$ 201 EH32 PEST CONTROL - rall in kitchen, poss still in kitchen cupboard, baby in prop Hogg Estate \$ 201 EH32 PEST CONTROL - and in hitchen Hogg Estate \$ 201 EH32 PeST CONTROL - and in kitchen under the sink Hogg Estate \$ 201 EH33 | EH32 | | | 2018 |
| EH33 | EH21 | PEST CONT possiblty rats in attic. | Hogg Estate S | 2018 |
| EH21 PEST CONTROL - wod lice comining out of window Hogg Estate \$ 201 EH21 GB-Carry out a treatment for ants in the bowling club temporary unit. Hogg Estate \$ 201 EH35 Dest control - infestion of ants and climbing over osp EH35 Dest control - infestion of ants and climbing over osp EH35 Dest Control - infestion of ants and climbing over osp EH36 PEST CONTROL - unusual smell in hallway, poss dead roderet under floorboards?, not sewage Hogg Estate \$ 201 EH37 PEST CONTROL - unusual smell in hallway, poss dead roderet under floorboards?, not sewage Hogg Estate \$ 201 EH38 PEST CONTROL - unusual smell in hallway, poss dead roderet under floorboards?, not sewage Hogg Estate \$ 201 EH39 PEST CONTROL - ratin kitchen, poss still in kitchen cupboard, baby in prop Hogg Estate \$ 201 EH30 PEST CONTROL - rat in kitchen, poss still in kitchen cupboard, baby in prop Hogg Estate \$ 201 EH31 Pest Control wasps in livingroom Hogg Estate \$ 201 EH32 PEST CONTROL - rat in kitchen poss still in kitchen outpoard, baby in prop Hogg Estate \$ 201 EH32 PEST CONTROL - rat in kitchen did nivingroom kitchen Hogg Estate \$ 201 EH33 Pest Control and a back door and porch and in livingroom kitchen Hogg Estate \$ 201 EH32 PEST CONTROL - ratis in kitchen Hogg Estate \$ 201 EH33 Pest Control and a tweath nursery building-113 padlock for access to gate. Hogg Estate \$ 201 EH33 Pest Control and the roof & several staff reporting insect bites-carry out a treatment as required. Hogg Estate \$ 201 EH34 Pest Control wasps at front at the roof Hogg Estate \$ 201 EH34 Pest Control wasps at front at the roof Hogg Estate \$ 201 EH34 Pest Control wasps at front at the roof Hogg Estate \$ 201 EH34 Pest Control wasps at front at the roof Hogg Estate \$ 201 EH35 Pest Control wasps as per our telephone conversation property contains fees Hogg Estate \$ 201 EH35 Pest Control wasps are per our telephone conversation property contains fees Hogg Estate \$ 201 EH35 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH36 Pest Control - Ants in the property - bathroom | EH32 | pest con - wasps in the house (above front I/room possible wasps nest | Hogg Estate S | 2018 |
| EH21 GB-Carry out a treatment for ants in the bowling club temporary unit. Hogg Estate \$ 201 EH39 GC main hall wasps - lying all over the floor Hogg Estate \$ 201 EH35 pest control -infestion of ants and climbing over cap EH35 pest control -infestion of ants and climbing over cap EH36 PEST CONT ants back in kitchen (please attend PM as care'rs get tenant up at 12) Hogg Estate \$ 201 EH37 PEST CONTROL - unusual smell in hallway, poss dead rodent under floorboards?, not sewage Hogg Estate \$ 201 EH38 Pest control wasps in livingroom Hogg Estate \$ 201 EH39 Pest control vasps in livingroom Hogg Estate \$ 201 EH39 Pest CONTROL - rat in kitchen, poss still in kitchen cupboard, baby in prop Hogg Estate \$ 201 EH32 PEST CONTROL - rat in kitchen, poss still in kitchen cupboard, baby in prop Hogg Estate \$ 201 EH32 Pest control -2 wasps nests at top of stairs at gate (2ft away from door and have to pass to get Hogg Estate \$ 201 EH39 PEST CONTROL - rat in kitchen Hogg Estate \$ 201 EH39 PEST CONTROL - arts in kitchen Hogg Estate \$ 201 EH39 PEST CONTROL - arts in kitchen Hogg Estate \$ 201 EH39 PEST CONTROL - arts in kitchen Hogg Estate \$ 201 EH39 PEST CONTROL - arts in kitchen Hogg Estate \$ 201 EH31 GB-Carry out a treatment for rats at vacant nursery building-113 padlock for access to gate. Hogg Estate \$ 201 EH39 Pest Control - rat possibly getting in to kitchen u nder the sink Hogg Estate \$ 201 EH39 Pest Control - rat possibly getting in to kitchen u nder the sink Hogg Estate \$ 201 EH39 Pest Control - rat possibly getting in to kitchen u nder the sink Hogg Estate \$ 201 EH39 Pest Control kinds in livingroom, hall kitchen Hogg Estate \$ 201 EH39 Pest Control kinds in high livingroom Hogg Estate \$ 201 EH39 Pest Control kinds in high kitchen Hogg Estate \$ 201 EH39 Pest Control kinds in the kitchen, living room Hogg Estate \$ 201 EH39 Pest Control kinds in the kitchen, living room Hogg Estate \$ 201 EH39 Pest Control kinds in the kitchen, living room Hogg Estate \$ 201 EH39 Pest Control kinds in the kitchen prop | EH33 | PEST CONTROL - Ant infestation, livingrm & kitchen | Hogg Estate S | 2018 |
| EH39 GC main hall wasps - lying all over the floor Hogg Estate \$ 201 EH35 pest control -infestion of ants and climbing over oap Hogg Estate \$ 201 EH35 PEST CONT ants back in kitchen (please attend PM as carers get tenant up at 12) Hogg Estate \$ 201 EH33 PEST CONTROL - unusual smell in hallway, poss dead rodent under floorboards?, not sewage Hogg Estate \$ 201 Hogg Estate \$ 201 EH34 Pest Control wasps in livingroom Hogg Estate \$ 201 EH35 PEST CONTROL - rat in kitchen, poss still in kitchen cupboard, baby in prop Hogg Estate \$ 201 EH32 PEST CONTROL - rat in kitchen, poss still in kitchen cupboard, baby in prop Hogg Estate \$ 201 EH32 Pest control - 2 wasps nests at top of stairs at gate (2/t away from door and have to pass to get Hogg Estate \$ 201 EH32 Pest control ants at back door and porch and in livingroom, kitchen Hogg Estate \$ 201 EH32 PEST CONTROL - ants in kitchen GB-Resident in room 6 & several staff reporting insect bites-carry out a treatment as required. Hogg Estate \$ 201 EH33 Pest Control - rat possibly getting in to kitchen under the sink Hogg Estate \$ 201 EH34 QG ants in ladies toilets and in office Hogg Estate \$ 201 EH35 QG ants in ladies toilets and in office Hogg Estate \$ 201 EH36 QG ants in ladies toilets and in office Hogg Estate \$ 201 EH37 QG ants in ladies toilets and in office Hogg Estate \$ 201 EH38 QG cants in ladies toilets and in office Hogg Estate \$ 201 EH39 Pest Control Ants in livingroom, hall i,kitchen Hogg Estate \$ 201 EH39 Pest Control Ants in livingroom, hall i,kitchen Hogg Estate \$ 201 EH39 Pest Control Ants in livingroom hall i,kitchen Hogg Estate \$ 201 EH39 Pest Control Thou in the kitchen, living room Hogg Estate \$ 201 EH39 Pest Control - base on ing up from under slab at front gate (1st slab) Pest Control - Ants in the kitchen, living room lades also at front gate (1st slab) Pest Control - Ants in the property - bethroom Hogg Estate \$ 201 EH39 Pest Control - Ants in the property - bethroom Hogg Estate \$ 201 EH39 Pest Control - Ant | EH21 | PEST CONTROL - wod lice cominhg out of window | Hogg Estate S | 2018 |
| EH35 pest control -infestion of ants and climbing over oap EH36 PEST CONT ants back in kitchen (please attend PM as carers get tenant up at 12) EH37 PEST CONTROL - unusual smell in hallway, poss dead rodent under floorboards?, not sewage Hogg Estate \$ 201 EH38 Pest control wasps in livingroom Hogg Estate \$ 201 EH39 Pest Control wasps in livingroom Hogg Estate \$ 201 EH39 Pest Control - bees and wasp nests at the property Hogg Estate \$ 201 EH39 Pest Control - rat in kitchen, poss still in kitchen cupboard, baby in prop Hogg Estate \$ 201 EH39 Pest Control - rat in kitchen, poss still in kitchen cupboard, baby in prop Hogg Estate \$ 201 EH39 Pest control - rat in kitchen, poss still in kitchen cupboard, baby in prop Hogg Estate \$ 201 EH39 Pest control - rat sat top of stairs at gate (2ft away from door and have to pass to get Hogg Estate \$ 201 EH39 Pest control - ants in kitchen Hogg Estate \$ 201 EH30 Pest Control - ants in kitchen Hogg Estate \$ 201 EH31 GB-Garry out a treatment for rats at vacant nursery building-113 padlock for access to gate. Hogg Estate \$ 201 EH32 GB-Resident in room 6 & several staff reporting insect bites-carry out a treatment as required. Hogg Estate \$ 201 EH30 Pest Control - rat possibly getting in to kitchen u noder the sink Hogg Estate \$ 201 EH31 GC ants in ladies toilets and in offlice Hogg Estate \$ 201 EH42 Pest Control wasps at front at the roof Hogg Estate \$ 201 EH42 Pest Control wasps at front at the roof Hogg Estate \$ 201 EH41 Pest Control Ants in livingroom, hall kitchen Hogg Estate \$ 201 EH42 Pest Control Ants in the kitchen, living room Hogg Estate \$ 201 EH42 Pest Control Ants in the kitchen, living room Hogg Estate \$ 201 EH43 Pest Control Transcoardy bees et wat at end of building beside wayer taphose. Hogg Estate \$ 201 EH43 Pest Control - ants in vert at end of building beside wayer taphose. Hogg Estate \$ 201 EH43 Pest Control - Ants in the property as per our telephone conversation property contains fleas Pest Control - Ants in the property as per our telephone conversation pro | EH21 | GB-Carry out a treatment for ants in the bowling club temporary unit. | Hogg Estate S | 2018 |
| PEST CONTROL - unusual smell in hallway, poss dead rodent under floorboards?, not sewage Hogg Estate \$ 201 Pest control wasps in livingroom Hogg Estate \$ 201 Pest Control - bees and wasp nests at the property Hogg Estate \$ 201 Pest Control - bees and wasp nests at the property Hogg Estate \$ 201 Pest Control - bees and wasp nests at the property Hogg Estate \$ 201 Pest Control - bees and wasp nests at the property Hogg Estate \$ 201 Pest Control - rat in kitchen, poss still in kitchen cupboard, baby in prop Hogg Estate \$ 201 Pest control - 2 wasps nests at top of stairs at gate (2ft away from door and have to pass to get Hogg Estate \$ 201 Pest control ants at back door and porch and in livingroom ,kitchen Hogg Estate \$ 201 Pest Control ants in kitchen Pest Control as a vacant nursery building-113 padlock for access to gate. Pest Gontrol - rat possibly getting in to kitchen u nder the sink Hogg Estate \$ 201 Pest Control wasps at front at the roof Hogg Estate \$ 201 Pest Control wasps at front at the roof Hogg Estate \$ 201 Pest Control Ants in kitchen under the sink Hogg Estate \$ 201 Pest Control Ants in inthe kitchen under the sink Hogg Estate \$ 201 Pest Control Ants in inthe kitchen under the sink Hogg Estate \$ 201 Pest Control Ants in inthe kitchen under the sink Hogg Estate \$ 201 Pest Control Ants in inthe kitchen, living room Hogg Estate \$ 201 Pest Control Ants in the kitchen, living room Hogg Estate \$ 201 Pest Control ants in the kitchen, living room Hogg Estate \$ 201 Pest Control ants in the kitchen, living room Hogg Estate \$ 201 Pest Control ants in the kitchen, living room Hogg Estate \$ 201 Pest Control ants in the kitchen, living room Hogg Estate \$ 201 Pest Control ants in the kitchen, living room Hogg Estate \$ 201 Pest Control ants in the kitchen, living room under slab at front gate (1st slab) Hogg Estate \$ 201 Pest Control - Ants in the rowans - wak ing the children. At rear of the house at | EH39 | GC main hall wasps - lying all over the floor | Hogg Estate S | 2018 |
| EH33 PEST CONTROL - unusual smell in hallway, poss dead rodent under floorboards?, not sewage Hogg Estate \$ 201 EH34 Pest Control wasps in livingroom Hogg Estate \$ 201 EH35 PEST CONTROL - rat in kitchen, poss still in kitchen cupboard, baby in prop Hogg Estate \$ 201 EH32 PEST CONTROL - rat in kitchen, poss still in kitchen cupboard, baby in prop Hogg Estate \$ 201 EH32 Pest control - 2 wasps nests at top of stairs at gate (2ft away from door and have to pass to get Hogg Estate \$ 201 EH32 Pest control ants at back door and porch and in livingroom, kitchen Hogg Estate \$ 201 EH32 Pest CONTROL - ants in kitchen Hogg Estate \$ 201 EH32 Pest CONTROL - ants in kitchen Hogg Estate \$ 201 EH32 Pest CONTROL - ants in kitchen Hogg Estate \$ 201 EH33 Pest Control ants at vacant nursery building-113 padlock for access to gate. Hogg Estate \$ 201 EH33 Pest Control - rat possibly getting in to kitchen u nder the sink Hogg Estate \$ 201 EH33 Pest Control - rat possibly getting in to kitchen u nder the sink Hogg Estate \$ 201 EH42 AVI Pest Control wasps at front at the roof Hogg Estate \$ 201 EH42 Pest Control Ants in kingroom Hogg Estate \$ 201 EH44 Pest Control Ants in livingroom Hogg Estate \$ 201 EH44 Pest Control ants in kitchen, living room Hogg Estate \$ 201 EH44 Pest Control ants in hit kitchen, living room Hogg Estate \$ 201 EH45 Pest Control ants in the kitchen, living room Hogg Estate \$ 201 EH46 Pest Control ants in the broket Hogg Estate \$ 201 EH47 Pest Control and building see text Hogg Estate \$ 201 EH48 Pest Control and building see text Hogg Estate \$ 201 EH49 Pest Control and building see text Hogg Estate \$ 201 EH49 Pest Control and building see text Hogg Estate \$ 201 EH49 Pest Control and building see text Hogg Estate \$ 201 EH49 Pest Control - ants in the property observer and the control and the normal see in vent at end of building beside wayer taphose. Hogg Estate \$ 201 EH49 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH49 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 | EH35 | pest control -infestion of ants and climbing over oap | Hogg Estate S | 2018 |
| EH33 Pest control wasps in livingroom Hogg Estate \$ 201 EH34 Pest Control - bees and wasp nests at the property Hogg Estate \$ 201 EH32 PEST CONTROL - rat in kitchen, poss still in kitchen cupboard, baby in prop Hogg Estate \$ 201 EH32 Pest control - 2 wasps nests at top of stairs at gate (2ft away from door and have to pass to get Hogg Estate \$ 201 EH32 Pest control ants at back door and porch and in livingroom ,kitchen Hogg Estate \$ 201 EH32 PEST CONTROL - ants in kitchen Hogg Estate \$ 201 EH32 PEST CONTROL - ants in kitchen Hogg Estate \$ 201 EH33 PEST CONTROL - ants in kitchen Hogg Estate \$ 201 EH34 GB-Carry out a treatment for rats at vacant nursery building-113 padlock for access to gate. Hogg Estate \$ 201 EH33 Pest Control - rat possibly getting in to kitchen u nder the sink Hogg Estate \$ 201 EH33 Pest Control - rat possibly getting in to kitchen u nder the sink Hogg Estate \$ 201 EH34 GC ants in ladies toilets and in office Hogg Estate \$ 201 EH42 AVI Pest Control wasps at front at the roof Hogg Estate \$ 201 EH42 PEST CONTROL infestion of ants livingroom Hogg Estate \$ 201 EH41 Pest Control Ants in livingroom, hall, kitchen Hogg Estate \$ 201 EH42 Pest Control Indies in the kitchen, living room Hogg Estate \$ 201 EH44 Pest Control ants in the kitchen, living room Hogg Estate \$ 201 EH43 GC ants in ladies at bucket Hogg Estate \$ 201 EH44 Pest Control ants in the kitchen, living room Hogg Estate \$ 201 EH45 PEST CONTROL infestion of ants livingroom Hogg Estate \$ 201 EH45 PEST CONTROL ants in the kitchen, living room Hogg Estate \$ 201 EH46 Pest Control ants in the kitchen, living room Hogg Estate \$ 201 EH47 Pest Control ants in the kitchen, living room Hogg Estate \$ 201 EH48 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH49 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH49 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH49 PEST CONTROL - bees coming up from under slab at front gate (1st | EH35 | PEST CONT ants back in kitchen (please attend PM as carers get tenant up at 12) | Hogg Estate S | 2018 |
| EH34 Pest Control - bees and wasp nests at the property EH32 PEST CONTROL - rat in kitchen, poss still in kitchen cupboard, baby in prop Hogg Estate \$ 201 EH21 pest control - 2 wasps nests at top of stairs at gate (2ft away from door and have to pass to get Hogg Estate \$ 201 EH32 Pest control ants at back door and porch and in livingroom, kitchen Hogg Estate \$ 201 EH32 PEST CONTROL - ants in kitchen Hogg Estate \$ 201 EH32 PEST CONTROL - ants in kitchen Hogg Estate \$ 201 EH21 GB-Carry out a treatment for rats at vacant nursery building-113 padlock for access to gate. Hogg Estate \$ 201 EH21 GB-Resident in room 6 & several staff reporting insect bites-carry out a treatment as required. Hogg Estate \$ 201 EH23 Pest Control - rat possibly getting in to kitchen u nder the sink Hogg Estate \$ 201 EH24 GC ants in ladies tollets and in office Hogg Estate \$ 201 EH25 AVI Pest Control wasps at front at the roof Hogg Estate \$ 201 EH26 AVI Pest Control wasps at front at the roof Hogg Estate \$ 201 EH27 Pest Control Ants in livingroom Hogg Estate \$ 201 EH28 GC ants in ladies at bucket Hogg Estate \$ 201 EH32 GC ants in ladies at bucket Hogg Estate \$ 201 EH32 GC ants in ladies at bucket Hogg Estate \$ 201 EH32 GC birds nesting in building see text Hogg Estate \$ 201 EH33 PEST CONT masonary bees in vent at end of building beside wayer tap/hose. Hogg Estate \$ 201 EH34 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH32 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH33 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH34 PEST CONTROL - seagulls nesting on roof Hogg Estate \$ 201 EH34 PEST CONTROL - seagulls nesting on roof Hogg Estate \$ 201 EH34 PEST CONTROL - hats in the property - bathroom Hogg Estate \$ 201 EH34 PEST CONTROL - seagulls nesting on roof Hogg Estate \$ 201 EH34 PEST CONTROL - seagulls nesting on roof Hogg Estate \$ 201 | EH33 | PEST CONTROL - unusual smell in hallway, poss dead rodent under floorboards?, not sewage | Hogg Estate S | 2018 |
| PEST CONTROL - rat in kitchen, poss still in kitchen cupboard, baby in prop Hogg Estate \$ 201 EH21 pest control - 2 wasps nests at top of stairs at gate (2ft away from door and have to pass to get Hogg Estate \$ 201 EH32 Pest control ants at back door and porch and in livingroom, kitchen Hogg Estate \$ 201 EH32 PEST CONTROL - ants in kitchen Hogg Estate \$ 201 EH21 GB-Carry out a treatment for rats at vacant nursery building-113 padlock for access to gate. Hogg Estate \$ 201 EH21 GB-Resident in room 6 & several staff reporting insect bites-carry out a treatment as required. Hogg Estate \$ 201 EH21 GC ants in ladies toilets and in office Hogg Estate \$ 201 EH22 AVI Pest Control wasps at front at the roof Hogg Estate \$ 201 EH21 PEST CONTROL infestion of ants livingroom Hogg Estate \$ 201 EH21 PEST CONTROL infestion of ants livingroom Hogg Estate \$ 201 EH21 Pest Control Ants in livingroom, halll, kitchen Hogg Estate \$ 201 EH22 PEST CONTROL infestion of ants livingroom Hogg Estate \$ 201 EH23 GC ants in ladies at bucket Hogg Estate \$ 201 EH32 GC ants in ladies at bucket Hogg Estate \$ 201 EH32 PEST CONTROL and set to the kitchen, living room Hogg Estate \$ 201 EH33 PEST CONTROL and set to the kitchen, living room Hogg Estate \$ 201 EH34 PEST CONTROL and se to the kitchen, living room Hogg Estate \$ 201 EH35 PEST CONTROL as per our telephone conversation property contains fleas Hogg Estate \$ 201 EH36 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH37 PEST CONTROL - seagulls nesting on roof Hogg Estate \$ 201 EH38 PEST CONTROL - Ants in the property - bathroom Hogg Estate \$ 201 EH38 PEST CONTROL - Ants in the property - bathroom Hogg Estate \$ 201 EH39 PEST CONTROL - Ants in the property - bathroom Hogg Estate \$ 201 EH39 PEST CONTROL - Ants in the property - bathroom Hogg Estate \$ 201 EH39 PEST CONTROL - Ants in the property - bathroom Hogg Estate \$ 201 EH39 PEST CONTROL - Jose sting in the rowans - wak ing the children. At rear of the house at car park | EH33 | Pest control wasps in livingroom | Hogg Estate S | 2018 |
| EH21 pest control - 2 wasps nests at top of stairs at gate (2ft away from door and have to pass to get Hogg Estate \$ 201 EH32 Pest control ants at back door and porch and in livingroom, kitchen Hogg Estate \$ 201 EH32 PEST CONTROL - ants in kitchen Hogg Estate \$ 201 EH21 GB-Carry out a treatment for rats at vacant nursery building-113 padlock for access to gate. Hogg Estate \$ 201 EH21 GB-Resident in room 6 & several staff reporting insect bites-carry out a treatment as required. Hogg Estate \$ 201 EH23 Pest Control - rat possibly getting in to kitchen u nder the sink Hogg Estate \$ 201 EH24 AVI Pest Control wasps at front at the roof Hogg Estate \$ 201 EH25 PEST CONTROL infestion of ants livingroom Hogg Estate \$ 201 EH26 Pest Control Ants in livingroom,.halll. kitchen Hogg Estate \$ 201 EH27 Pest Control ants in the kitchen, living room Hogg Estate \$ 201 EH32 GC ants in ladies at bucket Hogg Estate \$ 201 EH32 PEST CONTROL masonary bees in vent at end of building beside wayer tap/hose. Hogg Estate \$ 201 EH32 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH32 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH32 PEST CONTROL - seagulls nesting on roof Hogg Estate \$ 201 EH32 PEST CONTROL - Seagulls nesting on roof Hogg Estate \$ 201 EH33 PEST CONTROL - Seagulls nesting on roof Hogg Estate \$ 201 EH34 PEST CONTROL - Seagulls nesting on roof Hogg Estate \$ 201 EH35 PEST CONTROL - Ants in the property - bathroom Hogg Estate \$ 201 EH34 PEST CONTROL - Seagulls nesting on roof Hogg Estate \$ 201 EH35 PEST CONTROL - Ants in the property - bathroom Hogg Estate \$ 201 EH35 PEST CONTROL - Ants in the property - bathroom Hogg Estate \$ 201 EH35 PEST CONTROL - Ants in the property - bathroom Hogg Estate \$ 201 EH35 PEST CONTROL - Ants in the property - bathroom Hogg Estate \$ 201 EH36 PEST CONTROL - Ants in the property - bathroom Hogg Estate \$ 201 | EH34 | Pest Contol - bees and wasp nests at the property | Hogg Estate S | 2018 |
| EH32 Pest control ants at back door and porch and in livingroom ,kitchen Hogg Estate \$ 201 EH32 PEST CONTROL - ants in kitchen Hogg Estate \$ 201 EH21 GB-Carry out a treatment for rats at vacant nursery building-113 padlock for access to gate. Hogg Estate \$ 201 EH21 GB-Resident in room 6 & several staff reporting insect bites-carry out a treatment as required. Hogg Estate \$ 201 EH33 Pest Control - rat possibly getting in to kitchen u nder the sink Hogg Estate \$ 201 EH21 GC ants in ladies toilets and in office Hogg Estate \$ 201 EH22 AVI Pest Control wasps at front at the roof Hogg Estate \$ 201 EH21 PEST CONTROL infestion of ants livingroom Hogg Estate \$ 201 EH21 Pest Control Ants in livingroom, shall ,kitchen Hogg Estate \$ 201 EH21 Pest Control ants in the kitchen, living room Hogg Estate \$ 201 EH32 GC ants in ladies at bucket Hogg Estate \$ 201 EH33 GC birds nesting in building see text Hogg Estate \$ 201 EH32 PEST CONT masonary bees in vent at end of building beside wayer tap/hose. Hogg Estate \$ 201 EH32 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH32 | EH32 | PEST CONTROL - rat in kitchen, poss still in kitchen cupboard, baby in prop | Hogg Estate S | 2018 |
| EH32 PEST CONTROL - ants in kitchen EH21 GB-Carry out a treatment for rats at vacant nursery building-113 padlock for access to gate. EH21 GB-Resident in room 6 & several staff reporting insect bites-carry out a treatment as required. EH23 Pest Control - rat possibly getting in to kitchen u nder the sink Hogg Estate \$ 201 EH24 GC ants in ladies toilets and in office Hogg Estate \$ 201 EH25 AVI Pest Control wasps at front at the roof Hogg Estate \$ 201 EH26 Pest Control infestion of ants livingroom Hogg Estate \$ 201 EH27 Pest Control Ants in livingroom, halll, kitchen Hogg Estate \$ 201 EH28 Pest Control Ants in livingroom, hall kitchen Hogg Estate \$ 201 EH29 Control Ants in ladies at bucket Hogg Estate \$ 201 EH32 GC ants in ladies at bucket Hogg Estate \$ 201 EH33 PEST CONTROL infestion of ants living room Hogg Estate \$ 201 EH34 Pest Control Ants in livingroom, hall kitchen, living room Hogg Estate \$ 201 EH35 Pest Control Ants in livingroom the kitchen, living room Hogg Estate \$ 201 EH36 Pest Control Ants in ladies at bucket Hogg Estate \$ 201 EH37 PEST CONT masonary bees in vent at end of building beside wayer tap/hose. Hogg Estate \$ 201 EH37 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH38 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH38 PEST CONTROL - Seagulls nesting on roof Hogg Estate \$ 201 EH39 PEST CONTROL - Ants in the property - bathroom Hogg Estate \$ 201 EH39 PEST CONTROL - Pigeons nesting in the rowans - wak ing the children. At rear of the house at car park Hogg Estate \$ 201 EH39 Pest Control - pigeons nesting in the rowans - wak ing the children. At rear of the house at car park Hogg Estate \$ 201 | EH21 | pest control - 2 wasps nests at top of stairs at gate (2ft away from door and have to pass to get | Hogg Estate S | 2018 |
| EH21 GB-Carry out a treatment for rats at vacant nursery building-113 padlock for access to gate. EH21 GB-Resident in room 6 & several staff reporting insect bites-carry out a treatment as required. EH33 Pest Contol - rat possibly getting in to kitchen u nder the sink Hogg Estate \$ 201 EH21 GC ants in ladies toilets and in office Hogg Estate \$ 201 EH42 AVI Pest Control wasps at front at the roof Hogg Estate \$ 201 EH21 PEST CONTROL infestion of ants livingroom Hogg Estate \$ 201 EH21 Pest Control Ants in livingroom, halll , kitchen Hogg Estate \$ 201 EH41 Pest Control- ants in the kitchen, living room Hogg Estate \$ 201 EH32 GC ants in ladies at bucket Hogg Estate \$ 201 EH32 GC birds nesting in building see text Hogg Estate \$ 201 EH32 PEST CONT masonary bees in vent at end of building beside wayer tap/hose. Hogg Estate \$ 201 EH32 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH32 PEST CONTROL - seagulls nesting on roof Hogg Estate \$ 201 EH32 PEST CONTROL - seagulls nesting on roof Hogg Estate \$ 201 Hogg Estate \$ 201 EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 Hogg Estate \$ 201 Hogg Estate \$ 201 Hogg Estate \$ 201 EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 | EH32 | Pest control ants at back door and porch and in livingroom ,kitchen | Hogg Estate S | 2018 |
| EH21 GB-Resident in room 6 & several staff reporting insect bites-carry out a treatment as required. EH33 Pest Contol - rat possibly getting in to kitchen u nder the sink Hogg Estate \$ 201 EH21 GC ants in ladies toilets and in office Hogg Estate \$ 201 EH42 AVI Pest Control wasps at front at the roof Hogg Estate \$ 201 EH21 PEST CONTROL infestion of ants livingroom Hogg Estate \$ 201 EH21 Pest Control Ants in livingroom, halll ,kitchen Hogg Estate \$ 201 EH21 Pest Control ants in the kitchen, living room Hogg Estate \$ 201 EH32 GC ants in ladies at bucket Hogg Estate \$ 201 EH32 GC birds nesting in building see text Hogg Estate \$ 201 EH32 PEST CONT masonary bees in vent at end of building beside wayer tap/hose. Hogg Estate \$ 201 EH32 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH32 PEST CONTROL - seagulls nesting on roof Hogg Estate \$ 201 EH32 PEST CONTROL - Ants in the property - bathroom Hogg Estate \$ 201 EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH32 Pest Control - pigeons nesting in the rowans - wak ing the children. At rear of the house at car park Hogg Estate \$ 201 | EH32 | PEST CONTROL - ants in kitchen | Hogg Estate S | 2018 |
| Pest Control - rat possibly getting in to kitchen u nder the sink Hogg Estate \$ 201 GC ants in ladies toilets and in office Hogg Estate \$ 201 EH21 AVI Pest Control wasps at front at the roof Hogg Estate \$ 201 EH21 PEST CONTROL infestion of ants livingroom Hogg Estate \$ 201 EH21 Pest Control Ants in livingroom, halli "kitchen Hogg Estate \$ 201 EH21 Pest Control Ants in livingroom, halli "kitchen Hogg Estate \$ 201 EH32 GC ants in ladies at bucket Hogg Estate \$ 201 EH32 GC birds nesting in building see text Hogg Estate \$ 201 EH32 PEST CONT masonary bees in vent at end of building beside wayer tap/hose. Hogg Estate \$ 201 EH32 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH32 PEST CONTROL - seagulls nesting on roof Hogg Estate \$ 201 EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH32 Pest Control - pigeons nesting in the rowans - wak ing the children. At rear of the house at car park Hogg Estate \$ 201 | EH21 | GB-Carry out a treatment for rats at vacant nursery building-113 padlock for access to gate. | Hogg Estate S | 2018 |
| EH21 GC ants in ladies toilets and in office EH22 AVI Pest Control wasps at front at the roof EH21 PEST CONTROL infestion of ants livingroom Hogg Estate \$ 201 EH21 Pest Control Ants in livingroom, halll ,kitchen Hogg Estate \$ 201 EH21 Pest Control ants in livingroom, halll ,kitchen Hogg Estate \$ 201 EH32 GC ants in ladies at bucket Hogg Estate \$ 201 EH32 GC birds nesting in building see text Hogg Estate \$ 201 EH32 PEST CONT masonary bees in vent at end of building beside wayer tap/hose. Hogg Estate \$ 201 EH32 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH32 PEST CONTROL - seagulls nesting on roof Hogg Estate \$ 201 EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH32 Pest Control - Pigeons nesting in the rowans - wak ing the children. At rear of the house at car park Hogg Estate \$ 201 | EH21 | GB-Resident in room 6 & several staff reporting insect bites-carry out a treatment as required. | Hogg Estate S | 2018 |
| EH42 AVI Pest Control wasps at front at the roof EH21 PEST CONTROL infestion of ants livingroom Hogg Estate \$ 201 EH21 Pest Control Ants in livingroom, hall l, kitchen Hogg Estate \$ 201 EH41 Pest Control- ants in the kitchen, living room Hogg Estate \$ 201 EH32 GC ants in ladies at bucket Hogg Estate \$ 201 EH32 GC birds nesting in building see text Hogg Estate \$ 201 EH32 PEST CONT masonary bees in vent at end of building beside wayer tap/hose. Hogg Estate \$ 201 EH21 Fumigate property as per our telephone conversation property contains fleas Hogg Estate \$ 201 EH32 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH32 PEST CONTROL - seagulls nesting on roof Hogg Estate \$ 201 EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH32 Pest Control - pigeons nesting in the rowans - wak ing the children. At rear of the house at car park Hogg Estate \$ 201 EH32 Pest Control - pigeons nesting in the rowans - wak ing the children. At rear of the house at car park Hogg Estate \$ 201 | EH33 | Pest Contol - rat possibly getting in to kitchen u nder the sink | Hogg Estate S | 2018 |
| EH21 PEST CONTROL infestion of ants livingroom Hogg Estate \$ 201 EH21 Pest Control Ants in livingroom, halll ,kitchen Hogg Estate \$ 201 EH41 Pest Control- ants in the kitchen, living room Hogg Estate \$ 201 EH32 GC ants in ladies at bucket Hogg Estate \$ 201 EH32 GC birds nesting in building see text Hogg Estate \$ 201 EH32 PEST CONT masonary bees in vent at end of building beside wayer tap/hose. Hogg Estate \$ 201 EH32 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH32 PEST CONTROL - seagulls nesting on roof Hogg Estate \$ 201 EH32 PEST CONTROL - seagulls nesting on roof Hogg Estate \$ 201 EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH32 Pest Control - Pigeons nesting in the rowans - wak ing the children. At rear of the house at car park Hogg Estate \$ 201 Hogg Estate \$ 201 Hogg Estate \$ 201 Hogg Estate \$ 201 EH32 Pest Control - Pigeons nesting in the rowans - wak ing the children. At rear of the house at car park | EH21 | GC ants in ladies toilets and in office | Hogg Estate S | 2018 |
| EH21 Pest Control Ants in livingroom, halll ,kitchen Hogg Estate \$ 201 EH41 Pest Control- ants in the kitchen, living room Hogg Estate \$ 201 EH32 GC ants in ladies at bucket Hogg Estate \$ 201 EH32 GC birds nesting in building see text Hogg Estate \$ 201 EH32 PEST CONT masonary bees in vent at end of building beside wayer tap/hose. Hogg Estate \$ 201 EH21 Fumigate property as per our telephone conversation property contains fleas Hogg Estate \$ 201 EH32 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH32 PEST CONTROL - seagulls nesting on roof Hogg Estate \$ 201 EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 | EH42 | AVI Pest Control wasps at front at the roof | Hogg Estate S | 2018 |
| EH41 Pest Control- ants in the kitchen, living room Hogg Estate \$ 201 EH32 GC ants in ladies at bucket Hogg Estate \$ 201 EH32 GC birds nesting in building see text Hogg Estate \$ 201 EH32 PEST CONT masonary bees in vent at end of building beside wayer tap/hose. Hogg Estate \$ 201 EH21 Fumigate property as per our telephone conversation property contains fleas Hogg Estate \$ 201 EH32 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH32 PEST CONTROL - seagulls nesting on roof Hogg Estate \$ 201 EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH32 Pest Control - pigeons nesting in the rowans - wak ing the children. At rear of the house at car park Hogg Estate \$ 201 | EH21 | PEST CONTROL infestion of ants livingroom | Hogg Estate S | 2018 |
| EH32 GC ants in ladies at bucket Hogg Estate \$ 201 EH32 GC birds nesting in building see text Hogg Estate \$ 201 EH32 PEST CONT masonary bees in vent at end of building beside wayer tap/hose. Hogg Estate \$ 201 EH21 Fumigate property as per our telephone conversation property contains fleas Hogg Estate \$ 201 EH32 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH32 PEST CONTROL - seagulls nesting on roof Hogg Estate \$ 201 EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH32 Pest Control - pigeons nesting in the rowans - wak ing the children. At rear of the house at car park Hogg Estate \$ 201 | EH21 | Pest Control Ants in livingroom,.halll ,kitchen | Hogg Estate S | 2018 |
| EH32 GC birds nesting in building see text EH32 PEST CONT masonary bees in vent at end of building beside wayer tap/hose. EH21 Fumigate property as per our telephone conversation property contains fleas EH32 PEST CONTROL - bees coming up from under slab at front gate (1st slab) EH32 PEST CONTROL - seagulls nesting on roof EH32 Pest Control - Ants in the property - bathroom EH32 Pest Control - Ants in the property - bathroom EH32 Pest Control - pigeons nesting in the rowans - wak ing the children. At rear of the house at car park Hogg Estate \$ 201 Hogg Estate \$ 201 Hogg Estate \$ 201 | EH41 | Pest Control- ants in the kitchen, living room | Hogg Estate S | 2018 |
| EH32 PEST CONT masonary bees in vent at end of building beside wayer tap/hose. EH21 Fumigate property as per our telephone conversation property contains fleas EH32 PEST CONTROL - bees coming up from under slab at front gate (1st slab) EH32 PEST CONTROL - seagulls nesting on roof Hogg Estate \$ 201 EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH32 Pest Control - pigeons nesting in the rowans - wak ing the children. At rear of the house at car park Hogg Estate \$ 201 | EH32 | GC ants in ladies at bucket | Hogg Estate S | 2018 |
| EH21 Fumigate property as per our telephone conversation property contains fleas EH32 PEST CONTROL - bees coming up from under slab at front gate (1st slab) EH32 PEST CONTROL - seagulls nesting on roof EH32 Pest Control - Ants in the property - bathroom EH32 Pest Control - Pest Control - Pigeons nesting in the rowans - wak ing the children. At rear of the house at car park Hogg Estate \$ 201 EH32 Pest Control - pigeons nesting in the rowans - wak ing the children. At rear of the house at car park Hogg Estate \$ 201 | EH32 | GC birds nesting in building see text | Hogg Estate S | 2018 |
| EH32 PEST CONTROL - bees coming up from under slab at front gate (1st slab) Hogg Estate \$ 201 EH32 PEST CONTROL - seagulls nesting on roof Hogg Estate \$ 201 EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH32 Pest Control - pigeons nesting in the rowans - wak ing the children. At rear of the house at car park Hogg Estate \$ 201 | EH32 | PEST CONT masonary bees in vent at end of building beside wayer tap/hose. | Hogg Estate S | 2018 |
| EH32 PEST CONTROL - seagulls nesting on roof EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH32 Pest Control - pigeons nesting in the rowans - wak ing the children. At rear of the house at car park Hogg Estate \$ 201 EH32 Pest Control - pigeons nesting in the rowans - wak ing the children. At rear of the house at car park | EH21 | Fumigate property as per our telephone conversation property contains fleas | Hogg Estate S | 2018 |
| EH32 Pest Control - Ants in the property - bathroom Hogg Estate \$ 201 EH32 Pest Control - pigeons nesting in the rowans - wak ing the children. At rear of the house at car park Hogg Estate \$ 201 | EH32 | PEST CONTROL - bees coming up from under slab at front gate (1st slab) | Hogg Estate S | 2018 |
| EH32 Pest Control - pigeons nesting in the rowans - wak ing the children. At rear of the house at car park Hogg Estate \$ 201 | EH32 | PEST CONTROL - seagulls nesting on roof | Hogg Estate S | 2018 |
| | EH32 | Pest Control - Ants in the property - bathroom | Hogg Estate S | 2018 |
| FU22 PECT CONTROL wate in head woulder | EH32 | Pest Control - pigeons nesting in the rowans - wak ing the children. At rear of the house at car park | Hogg Estate S | 2018 |
| Hogg Estate \$ 201 | EH33 | PEST CONTROL - rate in back garden | Hogg Estate S | 2018 |

| EH33 | Pest Control rats in garden | Hogg Estate S | 2018 |
|------|--|---------------|------|
| EH42 | PEST CONTROL - rat in rear garden under garage tenant has 3 dogs, concerned ifpoison put down | Hogg Estate S | 2018 |
| EH33 | PEST CONTROL - bees/wasps in attic, accessing through 2 pipes under rear guttering | Hogg Estate S | 2018 |
| EH21 | PEST CONTROL - mice or birds in cavity wall | Hogg Estate S | 2018 |
| EH41 | Pest control bees/wasps at front of the door at surroundson left hand side | Hogg Estate S | 2018 |
| EH32 | pest control mice droppings at back door and possibly nesting at the shed area | Hogg Estate S | 2018 |
| EH34 | Meet BL put pellets in external vent under I/room window | Hogg Estate S | 2018 |
| EH33 | PEST CONTOL - bees nest at the bottom of the house- tenant insisted i had to put a new line on | Hogg Estate S | 2018 |
| EH35 | PEST CONTROL - ants in livingroom and hall | Hogg Estate S | 2018 |
| EH42 | PEST CONTROL bees nest under bathroom window | Hogg Estate S | 2018 |
| EH21 | rats in kitchen boiler cupboard | Hogg Estate S | 2018 |
| EH33 | PEST CONTROL - rats in hall cupboard and leads to back garden | Hogg Estate S | 2018 |
| EH21 | PEST rats in back garden at back door | Hogg Estate S | 2018 |
| EH32 | Pest Control - hears scratching up in back bedroom as if something stuck in wall cavity | Hogg Estate S | 2018 |
| EH42 | PEST CONTROL - waps nest at back door | Hogg Estate S | 2018 |
| EH39 | Pest Control wasps nesting 2nd vent from front door, next to drain pipe, flower pot in front | Hogg Estate S | 2018 |